Airworthiness Directive Schedule

Gliders Technoflug 26 April 2002

The date above indicates the amendment date of this schedule.

New or amended ADs are shown with an asterisk *

Contents

DCA/TFLUG/1	Wing Attachment Bolt Installation - Modification	. 2
DCA/TFLUG/2	Fuel Tank Filler Gasket - Installation	. 2
DCA/TFLUG/3	Cylinder Head Temperature Gauge - Installation	.2
* DCA/TLUG/A	Strut to Spar Connection - Inspection	

Gliders Technoflug

DCA/TFLUG/1 Wing Attachment Bolt Installation - Modification

Applicability: All Model 'Piccolo' with S/N 2 through 23.

Requirement: To prevent incorrect wing bolt installation, modify per Technoflug SB 845/3.

(Luftfahrt Bundesamt AD 89-66 refers)

Compliance: By 31 December 1989

Effective Date: 24 November 1989

DCA/TFLUG/2 Fuel Tank Filler Gasket - Installation

Applicability: All Model Piccolo.

Requirement: To prevent fuel entering the aircraft install fuel tank filler gasket per Technoflug SB

845/5.

(Luftfahrt Bundesamt AD 91-4 refers)

Compliance: By 22 April 1991.

Effective Date: 22 March 1991

DCA/TFLUG/3 Cylinder Head Temperature Gauge - Installation

Applicability: All Model Piccolo.

Requirement: Install cylinder head temperature gauge per Technoflug SB 845/4-2, Issue 2.

(Luftfahrt Bundesamt AD 90-331/2 refers)

Compliance: By 30 June 1992 Effective Date: 27 March 1992

* DCA/TLUG/4 Strut to Spar Connection – Inspection

Applicability: All Model Piccolo and Piccolo B

Requirement: To detect possible cracks in the spar near to the strut connection, inspect using a

boroscope per Technoflug SB 845/8 Piccolo-Piccolo B.

(LBA AD 2002-124 refers)

Compliance: At 1000 hours TTIS or within 10 hours TIS whichever occurs later.

Effective Date: 26 April 2002

Issued 26 April 2002 Page 2 of 2 CAA of NZ