

List of NZ CAA ADs issued in the last

AD Schedule*	AD	AD Title	Eff Date
Aeroplanes	Aeroplanes		
Beechcraft 200 Series	FAA AD 2025-20-11	Rudder Control Pushrod – Inspection	30-Oct-25
Bolkow 208 Series	EASA AD 2025-0284	Rudder Control System / Drive - Inspection	30-Dec-25
Bolkow 209 Series	EASA AD 2025-0284	Rudder Control System / Drive - Inspection	30-Dec-25
Britten-Norman Islander BN2 Series	DCA/BN-2/58	Cancelled – UK CAA 003-07-2000 refers	25-Jul-24
Britten-Norman Islander BN2 Series	UK CAA AD 003-07-2000	Engine Throttle Friction Adjuster - Inspection	25-Jul-24
Cessna 182 Series	FAA AD 2025-23-08	Intercooler Inlet and Outlet Hoses – Inspection	2-Dec-25
Cessna 525 and 525A Series	FAA AD 2001-02-13	Power Battery Switches - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2002-20-09	Adaptive Flight Display Units - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2004-14-20	Pitch Trim Circuit Breaker and AP Servo Circuit Breaker - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2005-17-11	Fire Extinguisher Bottles - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2008-03-10	Lower Wing Skin Structure - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2008-12-01	Firewall Sealant - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2010-12-01	Engine - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2013-08-05	Air Conditioning - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2020-24-06	Flight Controls - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2024-15-09	Gust Lock / Damper System - Inspection	22-Oct-24
Cessna 525 and 525A Series	FAA AD 97-01-02	MLG Trunnion Pins - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 97-05-03R1	Global Positioning Systems - Inspection	26-Sept-24
Cirrus SR20 and SR22	FAA AD 2024-24-11	Upper Power Lever - Inspection	23-Dec-24
De Havilland DHC-3 (Otter)	FAA AD 2022-23-08	Cancelled – Purpose fulfilled	28-Aug-25
De Havilland DHC-3 (Otter)	TC AD CF-2024-46	Horizontal Stabiliser Actuator – Inspection	6-Jan-25
Diamond DA 20 Series	TC AD CF-2026-03	ELT G-Switch Jumper Wire – Inspection	4-Feb-26
Diamond DA 40 Series	TC AD CF-2019-39R1	Fuel Tank Connection Hose - Inspection	4-Jun-25
Diamond DA 40 Series	TC AD CF-2025-30	Passenger Door – Inspection	31-Jul-25
Diamond DA 42	EASA AD 2024-0235	Rear Passenger Door Latching Mechanism – Inspection and Modification	19-Dec-24
Diamond DA 42	EASA AD 2026-0067R1	Exhaust Pipes – Inspection and Modification	4-Jun-26
Diamond DA 42	EASA AD 2026-0125R1	NLG Hydraulic Actuator Rod End – Inspection	1-Jul-26
Gippsland GA8 Series	CASA AD/GA8/12	Engine Operating Limitations - Amendment	31-Jan-25
Maule Series	FAA AD 81-25-01	Woodward Governors – Inspection	30-Jan-25
Maule Series	FAA AD 97-26-14	Power Levers – Inspection	30-Jan-25
Pilatus PC-12 Series	EASA AD 2025-0182	Emergency Exit / Passenger Service Unit Trim Panel - Inspection	8-Sept-25
Pilatus PC-12 Series	EASA AD 2025-0201	Engine Indications During Engine Start - Inspection	2-Oct-25
Pilatus PC-12 Series	EASA AD 2025-0271	Central Computer / Primus APEX Operational Software - Modification	18-Dec-25
Pilatus PC-12 Series	EASA AD 2026-0065-E	Brake Pipe Assembly - Replacement	23-Apr-26
Pilatus PC-6 Series	DCA/PC6/32D	EASA AD 2007-0241R4 Cancelled – EASA AD 2025-0281 refers	25-Dec-25

Pilatus PC-6 Series	EASA AD 2020-0278	Cancelled – EASA AD 2025-0281 refers	25-Dec-25
Pilatus PC-6 Series	EASA AD 2025-0281	Airworthiness Limitations Section – Amendment	25-Dec-25
Piper J3 Series	FAA AD 2025-02-11	Rudder Post – Inspection	20-Mar-25
Piper PA-14 Series	FAA AD 2025-02-11	Rudder Post – Inspection	20-Mar-25
Piper PA-18 Series	FAA AD 2025-02-11	Rudder Post – Inspection	20-Mar-25
Piper PA-20 Series	FAA AD 2025-02-11	Rudder Post – Inspection	20-Mar-25
Piper PA-22 Series	FAA AD 2025-02-11	Rudder Post – Inspection	20-Mar-25
Piper PA-25 Series	Argentina ANAC AD 2024-05-01	Cancelled – DCA/PA-25/127 refers	19-Sept-24
Piper PA-25 Series	Argentina ANAC AD 2024-05-01R1	Forward and Aft Wing Spars - Inspection	30-Jan-25
Piper PA-25 Series	DCA/PA-25/127	Cancelled - Argentina ANAC AD 2024-05-01R1 refers	30-Jan-25
Piper PA-28 Series	DCA/PA-28/174	Cancelled – FAA AD 81-11-02R1 refers	25-Sept-25
Piper PA-28 Series	FAA AD 81-11-02R1	Engine Oil Drain Valve – Inspection and Placards	25-Sept-25
Socata TB9, TB10 and TB20 Series	DCA/TB9/35	Cancelled – EASA AD 2025-0160 refers	8-Aug-25
Socata TB9, TB10 and TB20 Series	EASA AD 2025-0160	Lower Rudder Hinge Fitting – Inspection	8-Aug-25
Tecnam Aircraft	EASA AD 2021-0119	Trim Tab Trailing Edge – Inspection	26-Mar-26
Tecnam Aircraft	EASA AD 2024-0138	Seat Rails – Inspection	18-Jul-24
Tecnam Aircraft	EASA AD 2024-0152R1	Advanced Start System – Deactivation	27-Feb-25
Tecnam Aircraft	EASA AD 2024-0239	Rudder Pedals Torque Tube Hinges – Modification	27-Mar-25
Tecnam Aircraft	EASA AD 2026-0023	Exhaust Muffler – Inspection	16-Feb-26
Tecnam Aircraft	EASA AD 2026-0071	Engine Shock Mounts – Replacement	14-Apr-26
Tecnam Aircraft	EASA AD 2026-0124	Aileron Hinge / Cotter Pins – Inspection	15-Jul-26
Tecnam Aircraft	ENAC AD 2005-345	Rudder Pedals – Inspection	26-Mar-26
Transavia PL-12 Series	AD/PL 12/1 Amdt 2	Nose landing Gear Upper and Lower Pivot Support Assemblies - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/10	Engine Mount Tube - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/11 Amdt 1	Nose Wheel Pivot Pin – Inspection and Replacement	29-Jan-26
Transavia PL-12 Series	AD/PL 12/12 Amdt 3	Cockpit Overturn Structure - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/13	Nose Wheel Pivot Assembly - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/14 Amdt 1	Nose Landing Gear Pivot Pin and Bushes - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/15 Amdt 1	Landing Gear Lower Pivot Lug - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/16 Amdt 1	Engine Mount Tube - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/17	Pilot Compartment / Restraint - Modification	29-Jan-26
Transavia PL-12 Series	AD/PL 12/18 Amdt 1	Landing Gear Oleo Assemblies - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/19	Stub Wing Internal Structure - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/2	Aerodynamic Surfaces - Modification	29-Jan-26
Transavia PL-12 Series	AD/PL 12/20 Amdt 3	Main Wing and Stub Wing Fatigue Life Limitation	29-Jan-26
Transavia PL-12 Series	AD/PL 12/3 Amdt 1	Longitudinal Trim Augmenter - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/4	Stub Wing Structure - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/5	Rudder Pedal Assemblies - Inspection	29-Jan-26

Transavia PL-12 Series	AD/PL 12/6 Amdt 3	Nose Wheel Pivot Leg - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/7	Fuel Tank - Modification	29-Jan-26
Transavia PL-12 Series	AD/PL 12/8 Amdt 3	Stub Wing Spar - Inspection	29-Jan-26
Transavia PL-12 Series	AD/PL 12/9	Cancelled – CASA AD/PL 12/15 refers	29-Jan-26
Vulcanair P68 Series	EASA AD 2026-0051	Quantity Indicating Placard and AFM– Modification and Amendment	26-Mar-26
Yakovlev/Aerostar Series	UK CAA MPD 2026-004	Landing Gear and Flap Actuator - Inspection	7-Sept-26
Helicopters	Helicopters		
Airbus Helicopters AS 155 Series	EASA AD 2024-0173	Cancelled – EASA AD 2026-0011 refers	29-Jan-26
Airbus Helicopters AS 155 Series	EASA AD 2026-0011	Jettisonable Windows, Sliding Doors and Fixed Panels - Modification	29-Jan-26
Airbus Helicopters AS 350 Series	DCA/AS350/100	Cancelled – EASA AD 2026-0089 refers	4-Jun-26
Airbus Helicopters AS 350 Series	DCA/AS350/23F	Cancelled – EASA AD 2024-0133 refers	25-Jul-24
Airbus Helicopters AS 350 Series	EASA AD 2012-0257-E	Cancelled by EASA AD 2012-0257-CN – Purpose fulfilled	25-Jul-24
Airbus Helicopters AS 350 Series	EASA AD 2021-0194R1	Cancelled – EASA AD 2024-0133 refers	25-Jul-24
Airbus Helicopters AS 350 Series	EASA AD 2021-0282R1 (correction)	Tail Rotor Head Pitch Change Unit Bearing Spacer - Inspection	30-Jan-25
Airbus Helicopters AS 350 Series	EASA AD 2023-0089	Cancelled – EASA AD 2024-0139 refers	26-Jul-24
Airbus Helicopters AS 350 Series	EASA AD 2023-0187R1	Microswitches - Inspection	27-Mar-25
Airbus Helicopters AS 350 Series	EASA AD 2024-0133R1	Cancelled – EASA AD 2026-0102 refers	9-Jun-26
Airbus Helicopters AS 350 Series	EASA AD 2024-0139	Vertical Fin - Inspection	26-Jul-24
Airbus Helicopters AS 350 Series	EASA AD 2025-0025	Emergency Release Control of Cargo Swing Installation – Inspection	6-Feb-25
Airbus Helicopters AS 350 Series	EASA AD 2025-0036	Cargo Hook Assembly – Inspection	27-Feb-25
Airbus Helicopters AS 350 Series	EASA AD 2025-0137	Cancelled – EASA AD 2026-0101 refers	9-Jun-26
Airbus Helicopters AS 350 Series	EASA AD 2025-0137 (Correction)	Airworthiness Limitations Section - Amendment	27-Nov-25
Airbus Helicopters AS 350 Series	EASA AD 2025-0159	Sliding Door Placards - Installation	7-Aug-25
Airbus Helicopters AS 350 Series	EASA AD 2025-0263	Single Generation Hydraulic System Wiring Diode – Cut-off Test	18-Dec-25
Airbus Helicopters AS 350 Series	EASA AD 2026-0021	MGB to Fuselage Mounts and Attachment - Inspection	26-Feb-26
Airbus Helicopters AS 350 Series	EASA AD 2026-0052R1	Fuse Cover Attachment of Circuit Breaker Panel - Modification	23-Jul-26
Airbus Helicopters AS 350 Series	EASA AD 2026-0089	Starter Generator Limitation Label - Installation	4-Jun-26
Airbus Helicopters AS 350 Series	EASA AD 2026-0101	Airworthiness Limitations Section - Amendment	9-Jun-26
Airbus Helicopters AS 350 Series	EASA AD 2026-0102	Airworthiness Limitations Section - Amendment	9-Jun-26
Airbus Helicopters AS 350 Series	EASA AD 2026-0111	Tail Rotor Drive Shaft Sleeves - Inspection	25-Jun-26
Airbus Helicopters AS 350 Series	EASA AD 2026-0132	Main Rotor Servos Upper Ball Bearing Ends - Inspection	23-Jul-26
Airbus Helicopters AS 350 Series	EASA AD 2026-0146	Mechanical Dropping Control - Inspection	3-Sept-26
Airbus Helicopters AS 355 Series	DCA/AS355/8D	Cancelled – EASA AD 2024-0134 refers	25-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2012-0257-E	Cancelled by EASA AD 2012-0257-CN – Purpose fulfilled	25-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2021-0193	Cancelled – EASA AD 2024-0134 refer	25-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2021-0282R1 (correction)	Tail Rotor Head Pitch Change Unit Bearing Spacer - Inspection	30-Jan-25
Airbus Helicopters AS 355 Series	EASA AD 2023-0089	Cancelled – EASA AD 2024-0139 refers	26-Jul-24

Airbus Helicopters AS 355 Series	EASA AD 2023-0154R1	Vertical Upper Fin Assembly - Inspection	26-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2024-0127	Tail Rotor Drive Fan Wheel and Second Stage Impeller	25-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2024-0134	Cancelled – EASA AD 2026-0103 refers	9-Jun-26
Airbus Helicopters AS 355 Series	EASA AD 2024-0139	Vertical Fin - Inspection	26-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2025-0025	Emergency Release Control of Cargo Swing Installation – Inspection	6-Feb-25
Airbus Helicopters AS 355 Series	EASA AD 2025-0052	Fan Support Legs – Inspection	27-Mar-25
Airbus Helicopters AS 355 Series	EASA AD 2025-0159	Sliding Door Placards - Installation	7-Aug-25
Airbus Helicopters AS 355 Series	EASA AD 2025-0287	Fuel Draining System - Inspection	29-Jan-26
Airbus Helicopters AS 355 Series	EASA AD 2026-0103	Airworthiness Limitations Section - Amendment	9-Jun-26
Airbus Helicopters AS 355 Series	EASA AD 2026-0132	Main Rotor Servos Upper Ball Bearing Ends - Inspection	23-Jul-26
Airbus Helicopters AS 355 Series	EASA AD 2026-0146	Mechanical Dropping Control - Inspection	3-Sept-26
Airbus Helicopters BO105 Series	EASA AD 2025-0217	Rotor Flight Control Fork Lever - Inspection	30-Oct-25
Airbus Helicopters Deutschland EC 135	EASA AD 2026-0050	Automatic Flight Control System – Functional Check Flight	26-Mar-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2022-0168R3	Integrated Modular Avionics and AFM - Inspection and Amendment	4-Jun-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2024-0131	Main Rotor Control Rods / Pitch Links Assemblies– Inspection	25-Jul-24
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2024-0222 (correction)	Equipment Rack Extension Support Rails – Modification	30-Jan-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2024-0237-E	Tail Rotor Actuator – Inspection	11-Dec-24
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2024-0249	Cancelled – EASA AD 2026-0081 refers	4-May-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0027	Swashplate Inner and Outer Ring Bolts – Inspection	27-Feb-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0028	Main Rotor Head – Inspection	27-Feb-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0029	Swashplate – Inspection	27-Feb-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0051R1	Hoist – Replacement	29-May-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0055	Rescue Hoist Cable Drum – Inspection	27-Mar-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0153	Cargo Common Hook Beam – Modification	1-Aug-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0188	Large Hook Damper Assembly – Modification	25-Sept-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0217	Rotor Flight Control Fork Lever - Inspection	30-Oct-25

Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0298-E	Cancelled – EASA AD 2026-0127 refers	23-Jul-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2026-0050	Automatic Flight Control System – Functional Check Flight	26-Mar-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2026-0078-E	Cancelled – EASA AD 2026-0091 refers	4-Jun-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2026-0081	Warning Unit Emergency Off Switches – Operational Check / Replacement	4-May-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2026-0087	Main Rotor Drive Vertical Mount – Inspection / Life Limitation	4-Jun-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2026-0091	Cancelled – EASA AD 2026-0151 refers	3-Sept-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2026-0096	Integrated Modular Avionics and AFM - Inspection and Amendment	4-Jun-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2026-0109	Low Pressure Oxygen Hoses - Replacement	25-Jun-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2026-0127	Main Rotor Swashplate - Inspection	23-Jul-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2026-0151	Main Rotor Drive Hub Shaft - Inspection	3-Sept-26
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2026-0152	Vapour Cyle Airconditioning System - Inspection	6-Aug-26
Airbus Helicopters EC 120 B	EASA AD 2020-0247	Cancelled by EASA AD 2020-0247-CN – Purpose fulfilled	25-Jul-24
Airbus Helicopters EC 120 B	EASA AD 2024-0209	Tail Rotor Hub Body – Inspection	11-Nov-24
Airbus Helicopters EC 120 B	EASA AD 2024-0243	Pilot Cyclic Stick Bonding Braid – Inspection	27-Dec-24
Airbus Helicopters EC 120 B	EASA AD 2025-0159	Sliding Door Placards - Installation	7-Aug-25
Airbus Helicopters EC 130 Series	DCA/EC130/16	Cancelled – EASA AD 2026-0089 refers	4-Jun-26
Airbus Helicopters EC 130 Series	EASA AD 2021-0194R1	Cancelled – EASA AD 2024-0133 refers	25-Jul-24
Airbus Helicopters EC 130 Series	EASA AD 2022-0150R1	Tail Rotor Blades - Inspection	25-Jul-24
Airbus Helicopters EC 130 Series	EASA AD 2023-0187R1	Microswitches - Inspection	27-Mar-25
Airbus Helicopters EC 130 Series	EASA AD 2023-0190R1	Cancelled - EASA AD 2024-0144 refers	2-Aug-24
Airbus Helicopters EC 130 Series	EASA AD 2023-0214R1	Tail Rotor Drive Shaft / Rear Transmission Bearing Support - Modification	24-Sept-26
Airbus Helicopters EC 130 Series	EASA AD 2024-0133	Airworthiness Limitations Section - Amendment	25-Jul-24
Airbus Helicopters EC 130 Series	EASA AD 2024-0144R1	Tail Rotor Drive Shaft - Inspection	24-Sept-26
Airbus Helicopters EC 130 Series	EASA AD 2024-0232	Door Star Support - Modification	19-Dec-24
Airbus Helicopters EC 130 Series	EASA AD 2025-0025	Emergency Release Control of Cargo Swing Installation – Inspection	6-Feb-25
Airbus Helicopters EC 130 Series	EASA AD 2025-0062	Main Rotor Blades – Inspection	3-Apr-25
Airbus Helicopters EC 130 Series	EASA AD 2025-0137	Cancelled – EASA AD 2026-0101 refers	9-Jun-26
Airbus Helicopters EC 130 Series	EASA AD 2025-0137 (Correction)	Airworthiness Limitations Section - Amendment	27-Nov-25
Airbus Helicopters EC 130 Series	EASA AD 2025-0159	Sliding Door Placards - Installation	7-Aug-25

Airbus Helicopters EC 130 Series	EASA AD 2025-0249-E	Cancelled – EASA AD 2025-0262-E refers	27-Nov-25
Airbus Helicopters EC 130 Series	EASA AD 2025-0262-E	Tail Rotor Drive Centre Shaft Assembly – Inspection / Replacement / Life Limit	27-Nov-25
Airbus Helicopters EC 130 Series	EASA AD 2026-0052R1	Fuse Cover Attachment of Circuit Breaker Panel - Modification	23-Jul-26
Airbus Helicopters EC 130 Series	EASA AD 2026-0089	Starter Generator Limitation Label - Installation	4-Jun-26
Airbus Helicopters EC 130 Series	EASA AD 2026-0101	Airworthiness Limitations Section - Amendment	9-Jun-26
Airbus Helicopters EC 130 Series	EASA AD 2026-0111	Tail Rotor Drive Shaft Sleeves - Inspection	25-Jun-26
Airbus Helicopters EC 130 Series	EASA AD 2026-0132	Main Rotor Servos Upper Ball Bearing Ends - Inspection	23-Jul-26
Airbus Helicopters EC 130 Series	EASA AD 2026-0146	Mechanical Dropping Control - Inspection	3-Sept-26
Airbus Helicopters EC 135 Series	EASA AD 2013-0289-E	Cancelled – EASA AD 2025-0174 refers	28-Aug-25
Airbus Helicopters EC 135 Series	EASA AD 2022-0168R3	Integrated Modular Avionics and AFM - Inspection and Amendment	4-Jun-26
Airbus Helicopters EC 135 Series	EASA AD 2024-0028R1	Cancelled – EASA AD 2026-0032 refers	5-Mar-26
Airbus Helicopters EC 135 Series	EASA AD 2024-0249	Cancelled – EASA AD 2026-0081 refers	4-May-26
Airbus Helicopters EC 135 Series	EASA AD 2025-0051R1	Hoist – Replacement	29-May-25
Airbus Helicopters EC 135 Series	EASA AD 2025-0055	Rescue Hoist Cable Drum – Inspection	27-Mar-25
Airbus Helicopters EC 135 Series	EASA AD 2025-0108	Cancelled – EASA AD 2025-0260 refers	1-Dec-25
Airbus Helicopters EC 135 Series	EASA AD 2025-0113	Cancelled – EASA AD 2026-0031 refers	5-Mar-26
Airbus Helicopters EC 135 Series	EASA AD 2025-0174R1	Rear Structure / Ring Frame – Inspection	29-Sept-25
Airbus Helicopters EC 135 Series	EASA AD 2025-0260	Yaw Control System Ball Bearing – Inspection	1-Dec-25
Airbus Helicopters EC 135 Series	EASA AD 2026-0024	Yaw Control System Ball Bearing – Inspection	26-Feb-26
Airbus Helicopters EC 135 Series	EASA AD 2026-0031	Tail Rotor Blades – Inspection	5-Mar-26
Airbus Helicopters EC 135 Series	EASA AD 2026-0032	Tail Rotor Blades – Inspection	5-Mar-26
Airbus Helicopters EC 135 Series	EASA AD 2026-0080	Emergency, Malfunction and Normal Procedures – AFM Amendment	1-May-26
Airbus Helicopters EC 135 Series	EASA AD 2026-0081	Warning Unit Emergency Off Switches – Operational Check / Replacement	4-May-26
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2010-0181	Cancelled – EASA AD 2025-0191 refers	25-Sept-25
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2021-0171R1	Tail Rotor Pitch Control Rod Bearing - Inspection	25-Jul-24
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2023-0090	Cancelled - EASA AD 2026-0118 refers	6-Jul-26
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2024-0110	Cancelled – EASA AD 2025-0239 refers	10-Nov-25
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2024-0173	Jettisonable Windows, Sliding Doors and Fixed Panels - Modification	26-Sept-24
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2024-0244	Hoist - Inspection	20-Dec-24
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2025-0051R1	Hoist – Replacement	29-May-25
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2025-0191	Airworthiness Limitation Section - Amendment	25-Sept-25

Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2025-0239	Upper Ball Bearing End of the Main Rotor Servo Controls - Inspection	10-Nov-25
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2026-0029	Tail Gearbox Input Flange – Functional Checks	26-Feb-26
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2026-0056	Engine Firewalls – Modification	30-Mar-26
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2026-0118	Tail Rotor Actuator - Inspection	6-Jul-26
Bell 205 Series	FAA AD 2024-16-01	Tail boom Attachment Cap Angle - Inspection	4-Sept-24
Bell 205 Series	FAA AD 2024-17-02	Tail Boom – Inspection	8-Nov-24
Bell 205 Series	FAA AD 2024-19-17	Main Rotor Blades Tension-Torsion Straps – Inspection	31-Oct-24
Bell 212 Series	FAA AD 2024-16-01	Tail boom Attachment Cap Angle - Inspection	4-Sept-24
Bell 212 Series	FAA AD 2024-16-19	Tail Boom – Inspection	8-Nov-24
Bell 212 Series	FAA AD 2024-19-17	Main Rotor Blades Tension-Torsion Straps – Inspection	31-Oct-24
Bell 222 Series	TC AD CF-2026-39	Tail Rotor Pitch Horn – Inspection	3-Sept-26
Bell 407 Series	TC AD CF-2022-68	Cancelled - CF-2025-59 refers	3-Dec-25
Bell 407 Series	TC AD CF-2024-18	Cyclic Stick Tube - Inspection	25-Jul-24
Bell 407 Series	TC AD CF-2025-21R1	Main Rotor Expandable Blade Bolts - Inspection	1-Dec-25
Bell 407 Series	TC AD CF-2025-22	Electrical Harness Chafing - Inspection	29-May-25
Bell 407 Series	TC AD CF-2025-59	Tail Boom - Inspection	3-Dec-25
Bell 412 Series	DCA/BELL412/3	Cancelled – AD 2000-18-09 superseded by AD 2024-16-01	4-Sept-24
Bell 412 Series	FAA AD 2024-16-01	Tail boom Attachment Cap Angle - Inspection	4-Sept-24
Bell 412 Series	FAA AD 2024-16-19	Tail Boom – Inspection	8-Nov-24
Bell 427	TC AD CF-2024-42	Transmission Oil Check Valve – Inspection	27-Dec-24
Bell 427	TC AD CF-2025-21R1	Main Rotor Expandable Blade Bolts - Inspection	1-Dec-25
Bell 429	TC AD CF-2021-15	Cancelled - CF-2025-60 refers	8-Dec-25
Bell 429	TC AD CF-2024-11	Cancelled - Transport Canada AD CF-2025-29 refers	10-Jun-25
Bell 429	TC AD CF-2025-16	Stability and Control Augmentation System Actuators - Inspection	31-Mar-25
Bell 429	TC AD CF-2025-29	Tail Rotor Blade Abrasion Strip Cracks - Inspection	10-Jun-25
Bell 429	TC AD CF-2025-60R1	TRGB Support Assembly to Tail Boom Attachment - Inspection	26-Feb-26
Bell 429	TC AD CF-2025-64	Sliding Door Lower Roller Disengagement - Inspection	18-Dec-25
Bell 505	TC AD CF-2024-03	Cancelled – CF-2025-32 refers	16-Jul-25
Bell 505	TC AD CF-2024-44	Wire Harness Chafing - Inspection	30-Jan-25
Bell 505	TC AD CF-2025-17	Cancelled - CF-2025-35 refers	18-Jul-25
Bell 505	TC AD CF-2025-23	Oil Cooler Fan Assembly Housing Bracket - Inspection	7-May-25
Bell 505	TC AD CF-2025-32	Vertical Stabiliser Top End Cap Assembly - Inspection	16-Jul-25
Bell 505	TC AD CF-2025-34	Tail Rotor Pitch Link Assembly - Inspection	31-Jul-25
Bell 505	TC AD CF-2025-35	Aft Moveable Ballast Box Assembly Door Hinge - Inspection	18-Jul-25
Bell 505	TC AD CF-2025-62	Elongated Holes and Gaps in Tail Cone Assembly - Inspection	12-Dec-25
Bell 505	TC AD CF-2026-01	Incorrect Tailcone Assembly P/N - Inspection	29-Jan-26
Bell 505	TC AD CF-2026-12	Aft Moveable Ballast Box Assembly - Inspection	4-Mar-26

Bell 505	TC AD CF-2026-20R1	Airworthiness Limitations – Life Limits	4-Aug-26
Bell UH-1 Series	FAA AD 2024-19-17	Main Rotor Blades Tension-Torsion Straps – Inspection	31-Oct-24
Guimbal Cabri G2	EASA AD 2025-0282	Emergency Locator Transmitter - Inspection	19-Dec-25
Guimbal Cabri G2	EASA AD 2026-0095R1	Cancelled – EASA AD 2026-0147	30-Jul-26
Guimbal Cabri G2	EASA AD 2026-0147	Main Rotor Mast - Inspection	30-Jul-26
Helicopters - General	FAA AD 2024-20-04	Cancelled - Refer to Aircraft Seats and Harnesses	25-Sept-25
Helicopters - General	FAA AD 2024-20-07	Emergency Float System - Inspection	5-Dec-24
Hiller UH-12C and UH-12E	FAA AD 2025-15-02	Main Rotor Transmission Drive Shaft – Inspection	24-Sept-25
Kawasaki BK117 Series	JCAB AD TCD-10427-2025	Main Rotor Head – Inspection	24-Apr-25
Kawasaki BK117 Series	JCAB AD TCD-10553-2025	Main Rotor System Fork Lever – Inspection	4-Nov-25
Leonardo A109 and AW109 Series	EASA AD 2024-0004R1	Centre Fuselage Frame Assembly – Inspection	3-Sept-26
Leonardo A109 and AW109 Series	EASA AD 2024-0193	Engine Fire Extinguisher Bottle Connections – Inspection	31-Oct-24
Leonardo A109 and AW109 Series	EASA AD 2024-0228 (Correction)	Hoist – Inspection	19-Jun-25
Leonardo A109 and AW109 Series	EASA AD 2025-0051R1	Hoist – Replacement	29-May-25
Leonardo A109 and AW109 Series	EASA AD 2025-0131	Main Rotor Swashplate Nuts – Inspection	30-Jun-25
Leonardo A109 and AW109 Series	EASA AD 2025-0142R1	Cyclic Pitch and Roll Actuators – Inspection	25-Sept-25
Leonardo A109 and AW109 Series	EASA AD 2025-0148	Swashplate Duplex Bearing – Inspection	31-Jul-25
Leonardo A109 and AW109 Series	EASA AD 2026-0115	Horizontal Stabilizer Torque Tube Assembly – Inspection	29-Jun-26
Leonardo A109 and AW109 Series	EASA AD 2026-0168	Tail Gearbox and Chip Detector – Inspection	7-Sept-26
Leonardo A119 and AW119 Series	EASA AD 2023-0035	Cancelled – EASA AD 2026-0045 refers	26-Mar-26
Leonardo A119 and AW119 Series	EASA AD 2025-0131	Main Rotor Swashplate Nuts – Inspection	30-Jun-25
Leonardo A119 and AW119 Series	EASA AD 2025-0142R1	Cyclic Pitch and Roll Actuators – Inspection	25-Sept-25
Leonardo A119 and AW119 Series	EASA AD 2025-0148	Swashplate Duplex Bearing – Inspection	31-Jul-25
Leonardo A119 and AW119 Series	EASA AD 2025-0199	Pneumatic Line – Inspection	30-Sept-25
Leonardo A119 and AW119 Series	EASA AD 2026-0045	Collective Stick Torque Tube Assembly – Inspection	26-Mar-26
Leonardo AW169 Helicopters	EASA AD 2025-0051R1	Hoist – Replacement	29-May-25
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2024-23-06	Cancelled - FAA AD 2026-19-01 refers	20-Oct-26
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2025-17-11	Tail Rotor Pedal Support Bracket - Inspection	10-Oct-25
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2026-19-01	Cyclic Torque Tube Assembly - Inspection	20-Oct-26
MD 600N Helicopters	FAA AD 2024-23-06	Cancelled - FAA AD 2026-19-01 refers	20-Oct-26
MD 600N Helicopters	FAA AD 2025-17-11	Tail Rotor Pedal Support Bracket - Inspection	10-Oct-25
MD 600N Helicopters	FAA AD 2026-19-01	Cyclic Torque Tube Assembly - Inspection	20-Oct-26
Robinson R22 Series	FAA AD 2024-20-03	Engine Governor - Replacement	29-Nov-24
Robinson R44 Series	FAA AD 2024-19-11	Cancelled – FAA AD 2025-11-07 refers	11-Jul-25
Robinson R44 Series	FAA AD 2024-20-03	Engine Governor - Replacement	29-Nov-24
Robinson R44 Series	FAA AD 2024-23-01	Belt Tension Clutch Actuator Brackets - Inspection	7-Jan-25
Robinson R44 Series	FAA AD 2025-11-07	Engine / Transmission Coupling - Inspection	11-Jul-25

	EASA AD 2021-0069	Cancelled - EASA AD 2024-0209 refers	11-Nov-24
Amateur Built Microlights	Amateur Built Microlights		
Microlights - Eurofox Aircraft	UK MPD 2026-002R1-E	Rudder Pedal Torque Tube – Inspection	26-Feb-26
Ex-military and Vintage Aircraft Factory Built – Not type certified	Ex-military and Vintage Aircraft Factory Built – Not type certified		
Ex-military and Vintage Aircraft	UK MPD 2016-001R1	Cancelled – UK CAA MPD 2026-001 refers	29-Jan-26
Ex-military and Vintage Aircraft	UK MPD 2026-001	Turbine Engine Fuel System Aging Effects – Inspection	29-Jan-26
Gliders	Gliders		
DG Aviation Gliders	EASA AD 2024-0126	Automatic Elevator Connection – Inspection	25-Jul-24
DG Aviation Gliders	EASA AD 2025-0056	Airspeed Indicator and Placards – Modification	18-Mar-25
DG Aviation Gliders	EASA AD 2026-0009	Control Column Pivoting Bearing – Inspection	29-Jan-26
DG Aviation Gliders	EASA AD 2026-0010	Control Column Pivoting Bearing – Inspection	29-Jan-26
Grob Gliders	EASA AD 2025-0140	Rudder Drive Plate – Inspection	31-Jul-25
Grob Gliders	EASA AD 2026-0112	Fuel Shut-off Valve – Inspection	29-Jun-26
Schempp-Hirth	DCA/SH/11	Cancelled – EASA AD 2024-0242R1 refers	30-Jan-25
Schempp-Hirth	EASA AD 2024-0242R1	Horizontal Tailplane Drive Lower Bearing – Modification	30-Jan-25
Schempp-Hirth	EASA AD 2024-0251	Cancelled – EASA AD 2025-0157 refers	4-Aug-25
Schempp-Hirth	EASA AD 2025-0157	Wing Fuel Tank Hose – Inspection	4-Aug-25
Schempp-Hirth Gliders	EASA AD 2024-0242	Horizontal Tailplane Drive Lower Bearing – Modification	26-Dec-24
Balloons	Balloons		
Balloons - PRV Adaptor CB8426	UK CAA AD G-2025-0001R1-E	Cancelled – UK CAA AD G-2025-0004-E refers	28-Aug-25
Balloons - PRV Adaptor CB8426	UK CAA AD G-2025-0004-E	Pressure Relief Valves (PRV) Adaptor CB8426 – Inspection	28-Aug-25
Engines	Engines		
Austro E4 Series Engines	EASA AD 2024-0172-E	Piston – Inspection / Replacement	30-Aug-24
Continental TAE 125-01 and TAE 125-02 Series	EASA AD 2024-0236	Cancelled – EASA AD 2026-0077 refers	28-Apr-26
Continental TAE 125-01 and TAE 125-02 Series	EASA AD 2026-0077	Engine Coolant Contamination – Inspection	28-Apr-26
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2024-0040-E	Cancelled – EASA AD 2024-0194 refers	31-Oct-24
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2024-0194	Centrifugal Compressor Case - Inspection	31-Oct-24
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2025-0022	Fuel Control System – Additive Application	4-Feb-25
Lycoming AEIO-320, IO-320 and LIO-32(	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming AEIO-320, IO-320 and LIO-32(	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming AEIO-360, HIO-360, IO-360 ar	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming AEIO-360, HIO-360, IO-360 ar	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26

Lycoming AEIO-390 series and IO-390 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming AEIO-390 series and IO-390 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming AEIO-540 and IO-540 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming AEIO-540 and IO-540 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming AEIO-540 and IO-540 series	FAA AD 2026-17-10	Piston Pin – Inspection	14-Sept-26
Lycoming AEIO-580-B1A and IO-580-B1A	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming AEIO-580-B1A and IO-580-B1A	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming HO-360, LO-360 and O-360 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming HO-360, LO-360 and O-360 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming IO-720 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming IO-720 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming IVO-360-A1A engine and VO-360-A1A engine	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming IVO-360-A1A engine and VO-360-A1A engine	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming LTIO-540 and TIO-540 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming LTIO-540 and TIO-540 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming LTO-360 and TO-360 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming LTO-360 and TO-360 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming O-235 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming O-235 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming O-235 series	FAA AD 2026-17-10	Piston Pin – Inspection	14-Sept-26
Lycoming O-290 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming O-290 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming O-320 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming O-320 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming O-540 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming O-540 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming O-540 series	FAA AD 2026-17-10	Piston Pin – Inspection	14-Sept-26
Lycoming TIO-360 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming TIO-360 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming TVO-435 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming TVO-435 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming VO-435 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming VO-435 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Lycoming VO-540 series	FAA AD 2024-21-02	Cancelled – FAA AD 2026-04-11 refers	8-Apr-26
Lycoming VO-540 series	FAA AD 2026-04-11	Connecting Rod Assemblies and Bushing - Inspection	8-Apr-26
Pratt & Whitney PT6 Series	TC AD CF-2024-33	First Stage Power Turbine (PT1) Blades - Inspection	30-Sept-24
Pratt & Whitney PT6 Series	TC AD CF-2025-66	Compressor Turbine (CT) Disk Assembly - Inspection	19-Dec-25
Pratt & Whitney PW210 Series	TC AD CF-2026-23	Cancelled – CF-2026-35 refers	16-Jul-26
Pratt & Whitney PW210 Series	TC AD CF-2026-35	Turbine Exhaust Frame (TEF) – Inspection	16-Jul-26
Pratt & Whitney PW210A and PW210S engines	TC AD CF-2020-13	Impeller and HP Compressor Rotor Cycle Count – Manual Calculation	29-May-25
Rotax Engines	EASA AD 2025-0019-E	Internal Generator - Inspection	20-Jan-25

Rotax Engines	EASA AD 2025-0267-E	Propeller Gearbox - Inspection	2-Dec-25
Rotax Engines	EASA AD 2026-0121-E	Propeller Gearbox - Inspection	26-Jun-26
Rotax Engines	EASA AD 2026-0178-E	Turbocharger Valve Housing - Replacement	16-Sept-26
Rotax Engines	UK CAA MPD 2025-001-E	Internal Generator - Inspection	10-Feb-25
Rotax Engines	UK CAA MPD 2025-006-E	Propeller Gearbox - Inspection	6-Dec-25
Rotax Engines	UK CAA MPD 2026-003-E	Propeller Gearbox - Inspection	7-Jul-26
Rotax Engines	UK CAA MPD 2026-005-E	Turbocharger Valve Housing - Replacement	18-Sept-26
Safran Helicopter Engines Arriel 1 Series	EASA AD 2024-0207R1	(Correction) Gas Generator 1 st Stage HP Turbine Blades – Cancelled by EASA	27-Mar-25
Safran Helicopter Engines Arriel 2 Series	EASA AD 2017-0121	Cancelled – EASA AD 2026-0153 refers	3-Sept-26
Safran Helicopter Engines Arriel 2 Series	EASA AD 2025-0079	Cancelled – EASA AD 2026-0153 refers	3-Sept-26
Safran Helicopter Engines Arriel 2 Series	EASA AD 2026-0153	Airworthiness Limitations - Amendment	3-Sept-26
Safran Helicopter Engines Arrius 1A Series	DCA/TUR/55	Cancelled – AD 2008-0133 superseded by AD 2024-0148	28-Aug-24
Safran Helicopter Engines Arrius 1A Series	DCA/TUR/59	Cancelled – AD F-2005-063R1 superseded by AD 2024-0148	28-Aug-24
Safran Helicopter Engines Arrius 1A Series	EASA AD 2024-0148	Airworthiness Limitations – Amendment	28-Aug-24
Safran Helicopter Engines Arrius 1A Series	EASA AD 2026-0128 (Correction)	Hydromechanical Measuring Unit – Replacement	3-Sept-26
Safran Helicopter Engines Arrius 2B and 2K Series	EASA AD 2022-0203	Cancelled – EASA AD 2024-0149 refers	28-Aug-24
Safran Helicopter Engines Arrius 2B1, 2B2 and 2K1	EASA AD 2024-0149	Cancelled – EASA AD 2026-0027 refers	26-Feb-26
Safran Helicopter Engines Arrius 2B1, 2B2 and 2K1	EASA AD 2026-0027	Airworthiness Limitations – Amendment	26-Feb-26
Safran Helicopter Engines Arrius 2B1, 2B2 and 2K1 Series	EASA AD 2024-0195R1	Cancelled – EASA AD 2026-0131 refers	23-Jul-26
Safran Helicopter Engines Arrius 2B1, 2B2 and 2K1 Series	EASA AD 2026-0131	EECU Software - Update & Preference Injector - Non-extinguishing Test	23-Jul-26
Safran Helicopter Engines Arrius 2F and 2R Series	DCA/TUR/29	DGAC AD F-2005-088 cancelled by EASA AD 2024-0115-CN – Purpose fulfilled	25-Jul-24
Safran Helicopter Engines Arrius 2F and 2R Series	EASA AD 2024-0202R1	Fuel Control Unit - Replacement	25-Sept-25
Safran Helicopter Engines Arrius 2F and 2R Series	EASA AD 2024-0218R1	Gas Generator HP Turbine Blades - Cancelled by EASA	27-Mar-25
Williams International FJ44 Series	FAA AD 2022-13-15	Turbine Section - Inspection	31-Oct-24
Williams International FJ44 Series	FAA AD 97-01-05	Disk Posts and Turbine Blades - Inspection	31-Oct-24
Williams International FJ44 Series	FAA AD 99-07-04	High Pressure Turbine (HPT) Disk - Inspection	31-Oct-24

Propellers		Propellers	
Woodward Constant Speed Propeller Governors	DCA/WOOD/114	Cancelled – Maule M5 235C FAA AD 81-25-01 refers	31-Jul-25
Components & Equip**		Components & Equip**	
Aircraft Seats and Harnesses	EASA AD 2025-0294R1	B/E Aerospace Fischer Medical Seats – Modification	26-Feb-26
Aircraft Seats and Harnesses	FAA AD 2021-07-13	Cancelled – FAA AD 2024-26-02 refers	7-Mar-25
Aircraft Seats and Harnesses	FAA AD 2024-20-04	Rotary Buckle Assembly – Inspection	25-Sept-25
Aircraft Seats and Harnesses	FAA AD 2024-26-02	Pacific Scientific Company Rotary Buckle Assemblies – Inspection	7-Mar-25
Aircraft Seats and Harnesses	FAA AD 2025-16-09	Rotary Buckle Assembly - Inspection	22-Sept-25
Aircraft Seats and Harnesses	UK CAA AD G-2025-0005	Acro Series 9 Passenger Seats – Inspection	2-Oct-25
Aircraft Seats and Harnesses	UK CAA AD G-2026-0001	Acro Series 6 Passenger Seats – Inspection	23-Apr-26
Aircraft Seats and Harnesses	UK CAA AD G-2026-0003	Irvingq Crewman Restraint – Inspection	3-Sept-26
Avionics Equipment	DCA/RAD/9B	Radio Altimeter Antennae - Inspection	29-May-25
Avionics Equipment	EASA AD 2026-0044	Kannad 406 AF-Compact ELT - Inspection	26-Mar-26
Avionics Equipment	FAA AD 2025-07-01 (Correction)	Thommen AC32 Digital Air Data Computers (ADCs) - Inspection	29-May-25
Brakes & Wheels	Brazilian AD 2025-08-01R1	Wheel and Brake Assemblies - Inspection	28-Aug-25
Brakes & Wheels	DCA/BRAKE/4	Cancelled – Purpose Fulfilled	23-Apr-26
Emergency Equipment	EASA AD 2025-0222	Portable Breathing Equipment – Operational Instructions	30-Oct-25
Emergency Equipment	EASA AD 2025-0297R1	Portable Breathing Equipment – Removal from Service	26-Feb-26
Emergency Equipment	UK CAA AD G-2026-0004	Techtest PLB / ELT – Inspection	24-Sept-26
Instruments & Automatic Pilots	FAA AD 2024-14-03	Garmin GFC 500 Autopilot System – Inspection	20-Aug-24

Notes:

* The AD Schedule often covers a complete series of types.

** This is not the AD Schedule title but more specific to the components affected.

*** AD Numbering - If the AD number is less than 10, a zero has been added before the number.

This is for sorting only and the AD should still be referred to as in the AD Schedule.