Airworthiness Directive Schedule

Gliders Schneider ES52 Kookaburra 29 October 2009

Notes	1.	This AD schedule is applicable to Schneider ES52/II Kookaburra aircraft manufactured by Edmund Schneider Ltd under CASA Certificate of Type Approval Number 25-1.
	2.	The date above indicates the amendment date of this schedule.
	3.	New or amended ADs are shown with an asterisk *
		Contents

* DCA/ES52/1	Elevator Center Hinge – Inspection	.2
* DCA/ES52/2	Control Column Link Rod – Inspection and Replacement	.2
* DCA/ES52/3	Flight Limitations – Placard and Inspections	.2

* DCA/ES52/1	Elevator Center Hinge – Inspection
Applicability:	All model ES52 Kookaburra aircraft
Requirement:	To prevent failure of the elevator due to cracks in the elevator center hinge, accomplish the requirements specified in Glider Federation of Australia (GFA) AD 0014.
Note:	A copy of the GFA AD is available on the Glider Federation of Australia (GFA) web site at http://2009.gfa.org.au/index.php?option=com_content&task=view&id=254&Itemid=13 3
	(Gliding Federation of Australia AD GFA AD 0014 refers)
Compliance:	At the initial threshold specified in GFA AD 0014 unless previously accomplished, and thereafter at intervals not to exceed those specified in the GFA AD.
Effective Date:	29 October 2009
* DCA/ES52/2	Control Column Link Rod – Inspection and Replacement
Applicability:	All model ES52 Kookaburra aircraft
Requirement:	To prevent failure of the control column link rod due to fatigue cracks in the screwed ends, accomplish the requirements specified in Glider Federation of Australia (GFA) AD 0211.
Note:	A copy of the GFA AD is available on the Glider Federation of Australia (GFA) web site at <u>http://2009.gfa.org.au/index.php?option=com_content&task=view&id=254&Itemid=13</u> <u>3</u>
	(Gliding Federation of Australia AD GFA AD 0211 refers)
Compliance:	At the initial threshold specified in GFA AD 0211 unless previously accomplished.
Effective Date:	29 October 2009
* DCA/ES52/3	Flight Limitations – Placard and Inspections
Applicability:	All model ES52 Kookaburra aircraft
Requirement:	To prevent structural failure of the aircraft, accomplish the requirements specified in Glider Federation of Australia (GFA) AD 0378.
Note:	A copy of the GFA AD is available on the Glider Federation of Australia (GFA) web site at http://2009.gfa.org.au/index.php?option=com_content&task=view&id=254&Itemid=13 3
	(Gliding Federation of Australia AD GFA AD 0378 refers)
Compliance:	At the initial threshold specified in GFA AD 0378 unless previously accomplished, and thereafter at intervals not to exceed those specified in the GFA AD.
Effective Date:	29 October 2009