

List of NZ CAA ADs issued in the last 27 months as at Amendment Nr 25-11

AD Schedule*	AD	AD Title	Eff Date
Aeroplanes	Aeroplanes		
Beechcraft 200 Series	DCA/B200/5	Cancelled - FAA AD 89-19-04R1 refers	30-Nov-23
Beechcraft 200 Series	FAA AD 2025-20-11	Rudder Control Pushrod – Inspection	30-Oct-25
Beechcraft 200 Series	FAA AD 89-19-04R1	Wing Fuel Bay Skin Panels - Inspection	30-Nov-23
Britten-Norman Islander BN2 Series	DCA/BN-2/58	Cancelled – UK CAA 003-07-2000 refers	25-Jul-24
Britten-Norman Islander BN2 Series	UK CAA AD 003-07-2000	Engine Throttle Friction Adjuster - Inspection	25-Jul-24
Cessna 182 Series	FAA AD 2025-23-08	Intercooler Inlet and Outlet Hoses – Inspection	2-Dec-25
Cessna 525 and 525A Series	FAA AD 2001-02-13	Power Battery Switches - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2002-20-09	Adaptive Flight Display Units - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2004-14-20	Pitch Trim Circuit Breaker and AP Servo Circuit Breaker - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2005-17-11	Fire Extinguisher Bottles - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2008-03-10	Lower Wing Skin Structure - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2008-12-01	Firewall Sealant - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2010-12-01	Engine - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2013-08-05	Air Conditioning - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2020-24-06	Flight Controls - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 2024-15-09	Gust Lock / Damper System - Inspection	22-Oct-24
Cessna 525 and 525A Series	FAA AD 97-01-02	MLG Trunnion Pins - Inspection	26-Sept-24
Cessna 525 and 525A Series	FAA AD 97-05-03R1	Global Positioning Systems - Inspection	26-Sept-24
Cirrus SR20 and SR22	FAA AD 2024-24-11	Upper Power Lever - Inspection	23-Dec-24
De Havilland DHC-3 (Otter)	FAA AD 2022-23-08	Cancelled – Purpose fulfilled	28-Aug-25
De Havilland DHC-3 (Otter)	TC AD CF-2024-46	Horizontal Stabiliser Actuator – Inspection	6-Jan-25
Diamond DA 40 Series	TC AD CF-2019-39R1	Fuel Tank Connection Hose - Inspection	4-Jun-25
Diamond DA 40 Series	TC AD CF-2023-50R1	NLG Leg Pivot Axle - Inspection	21-Dec-23
Diamond DA 40 Series	TC AD CF-2025-30	Passenger Door – Inspection	31-Jul-25
Diamond DA 42	EASA AD 2023-0013R1	Rudder Steering Bracket – Inspection and Modification	30-May-24
Diamond DA 42	EASA AD 2024-0235	Rear Passenger Door Latching Mechanism – Inspection and Modification	19-Dec-24
Diamond DA 62	TC AD CF-2018-13	Passenger Safety Lap Belts - Inspection	21-Dec-23
Diamond DA 62	TC AD CF-2021-24	Baggage Nets - Inspection	21-Dec-23
Diamond DA 62	TC AD CF-2024-02	Horizontal Stabiliser – Inspection	26-Jan-24
Gippsland GA8 Series	CASA AD/GA8/11	Solenoid (Relay) Box Electrical Bonding - Inspection	23-Dec-23
Gippsland GA8 Series	CASA AD/GA8/12	Engine Operating Limitations - Amendment	31-Jan-25
Gippsland GA8 Series	CASA AD/GA8/3 Amdt 4	Forward Cargo Door Slide - Inspection	30-May-24
Gippsland GA8 Series	DCA/GA8/3A	Cancelled – CASA AD/GA8/3 Amdt 3 refers	15-Sept-23
Maule Series	FAA AD 81-25-01	Woodward Governors – Inspection	30-Jan-25
Maule Series	FAA AD 97-26-14	Power Levers – Inspection	30-Jan-25

Miles M38 Messenger	UK CAA AD 2706 PRE 80	Pipes Forward of the Fireproof Bulkhead	18-Jun-24
Miles M38 Messenger	UK CAA AD 2707 PRE 80	Laminated Safety Glass or Perspex in Cabin Doors	18-Jun-24
Miles M38 Messenger	UK CAA AD 2708 PRE 80	Venting and Draining of Fuel Tanks	18-Jun-24
Miles M38 Messenger	UK CAA AD 2709 PRE 80	Chain to Operate the Flap Jack and an Additional Support	18-Jun-24
Miles M38 Messenger	UK CAA AD 2710 PRE 80	Lift Flap Bell Crank Levers	18-Jun-24
Miles M38 Messenger	UK CAA AD 2711 PRE 80	Flap Operating Chain Pulley Under the Front Seat	18-Jun-24
Miles M38 Messenger	UK CAA AD 2712 PRE 80	Rear Windows	18-Jun-24
Miles M38 Messenger	UK CAA AD 2713 PRE 80	Aileron Torque Shaft	18-Jun-24
Miles M38 Messenger	UK CAA AD 2714 PRE 80	Crossing of Battery Connection	18-Jun-24
Miles M38 Messenger	UK CAA AD 2715 PRE 80	Crossing of Battery Connection	18-Jun-24
Miles M38 Messenger	UK CAA AD 2716 PRE 80	Cabin Door Jettison Gear	18-Jun-24
Miles M38 Messenger	UK CAA AD 2717 PRE 80	Tailplane Front False Spar Attachments	18-Jun-24
Miles M38 Messenger	UK CAA AD 2718 PRE 80	Starter Isolation Switch	18-Jun-24
Miles M38 Messenger	UK CAA AD 2719 PRE 80	Rudder Bar Parallel Motion Links	18-Jun-24
Miles M38 Messenger	UK CAA AD 2720 PRE 80	Fuel Tank Filler Caps, and alterations to Vent and Drain Pipes	18-Jun-24
Miles M38 Messenger	UK CAA AD 2721 PRE 80	Fuel Drain Pipe in the Engine Bay	18-Jun-24
Miles M38 Messenger	UK CAA AD 2722 PRE 80	Cable Connections at the Trim Tabs	18-Jun-24
Miles M38 Messenger	UK CAA AD 2723 PRE 80	Rib 4 at Undercarriage Attachment	18-Jun-24
Miles M38 Messenger	UK CAA AD 2724 PRE 80	Nose Cowl Leg	18-Jun-24
Miles M38 Messenger	UK CAA AD 2725 PRE 80	Elevator Hinge Block	18-Jun-24
Miles M38 Messenger	UK CAA AD 2726 PRE 80	Fork Ends to Flap Jacks	18-Jun-24
Miles M38 Messenger	UK CAA AD 2727 PRE 80	Flap Jack Mounting P/N 3838262	18-Jun-24
Miles M38 Messenger	UK CAA AD 2728 PRE 80	Vent and Drain Connections on Fuel Tanks	18-Jun-24
Miles M38 Messenger	UK CAA AD 2729 PRE 80	Rudder Bar Pedals	18-Jun-24
Miles M38 Messenger	UK CAA AD 2730 PRE 80	Aileron Outer Hinge Bearing Housing	18-Jun-24
Pilatus PC-12 Series	EASA AD 2008-0163	Cancelled – EASA AD 2023-0184 refers	2-Nov-23
Pilatus PC-12 Series	EASA AD 2022-0103	Cancelled – EASA AD 2023-0184 refers	2-Nov-23
Pilatus PC-12 Series	EASA AD 2023-0184	Airworthiness Limitations - Amendment	2-Nov-23
Pilatus PC-12 Series	EASA AD 2025-0182	Emergency Exit / Passenger Service Unit Trim Panel - Inspection	8-Sept-25
Pilatus PC-12 Series	EASA AD 2025-0201	Engine Indications During Engine Start - Inspection	2-Oct-25
Piper J3 Series	FAA AD 2025-02-11	Rudder Post – Inspection	20-Mar-25
Piper PA-14 Series	FAA AD 2025-02-11	Rudder Post – Inspection	20-Mar-25
Piper PA-18 Series	FAA AD 2025-02-11	Rudder Post – Inspection	20-Mar-25
Piper PA-20 Series	FAA AD 2025-02-11	Rudder Post – Inspection	20-Mar-25
Piper PA-22 Series	FAA AD 2025-02-11	Rudder Post – Inspection	20-Mar-25
Piper PA-25 Series	Argentina ANAC AD 2024-05-01	Cancelled – DCA/PA-25/127 refers	19-Sept-24
Piper PA-25 Series	Argentina ANAC AD 2024-05-01R1	Forward and Aft Wing Spars - Inspection	30-Jan-25
Piper PA-25 Series	DCA/PA-25/127	Cancelled - Argentina ANAC AD 2024-05-01R1 refers	30-Jan-25

Piper PA-28 Series	DCA/PA-28/174	Cancelled – FAA AD 81-11-02R1 refers	25-Sept-25
Piper PA-28 Series	FAA AD 2024-10-04	Wing Spar Attachment Fittings – Inspection	6-Jun-24
Piper PA-28 Series	FAA AD 81-11-02R1	Engine Oil Drain Valve – Inspection and Placards	25-Sept-25
Piper PA-34 Series	FAA AD 2024-10-04	Wing Spar Attachment Fittings – Inspection	6-Jun-24
Piper PA-44 Series	FAA AD 2024-10-04	Wing Spar Attachment Fittings – Inspection	6-Jun-24
Piper PA-46 Series	FAA AD 2023-25-02	Control Column Mount Bearing - Inspection	19-Dec-23
Robin DR400 Series	EASA AD 2023-0048-E	Cancelled by EASA	18-Jun-24
Socata TB9, TB10 and TB20 Series	DCA/TB9/35	Cancelled – EASA AD 2025-0160 refers	8-Aug-25
Socata TB9, TB10 and TB20 Series	EASA AD 2025-0160	Lower Rudder Hinge Fitting – Inspection	8-Aug-25
Tecnam Aircraft	EASA AD 2024-0138	Seat Rails – Inspection	18-Jul-24
Tecnam Aircraft	EASA AD 2024-0152R1	Advanced Start System – Deactivation	27-Feb-25
Tecnam Aircraft	EASA AD 2024-0239	Rudder Pedals Torque Tube Hinges – Modification	27-Mar-25
Vulcanair P68 Series	EASA AD 2020-0262R1	Stabilator Trim Control Cable – Inspection	26-Oct-23
Helicopters	Helicopters		
Agusta Bell AB212	EASA AD 2024-0104	Left Upper Cap Angle - Inspection	31-May-24
Airbus Helicopters AS 350 Series	DCA/AS350/23F	Cancelled – EASA AD 2024-0133 refers	25-Jul-24
Airbus Helicopters AS 350 Series	EASA AD 2012-0257-E	Cancelled by EASA AD 2012-0257-CN – Purpose fulfilled	25-Jul-24
Airbus Helicopters AS 350 Series	EASA AD 2021-0168	Cancelled – EASA AD 2024-0018 refers	25-Jan-24
Airbus Helicopters AS 350 Series	EASA AD 2021-0194R1	Cancelled – EASA AD 2024-0133 refers	25-Jul-24
Airbus Helicopters AS 350 Series	EASA AD 2021-0282R1 (correction)	Tail Rotor Head Pitch Change Unit Bearing Spacer - Inspection	30-Jan-25
Airbus Helicopters AS 350 Series	EASA AD 2023-0089	Cancelled – EASA AD 2024-0139 refers	26-Jul-24
Airbus Helicopters AS 350 Series	EASA AD 2023-0133	Cancelled - EASA AD 2023-0187 refers	30-Nov-23
Airbus Helicopters AS 350 Series	EASA AD 2023-0187R1	Microswitches - Inspection	27-Mar-25
Airbus Helicopters AS 350 Series	EASA AD 2024-0018	Indicating / Recording Systems Control Unit – Inspection	25-Jan-24
Airbus Helicopters AS 350 Series	EASA AD 2024-0133R1	Airworthiness Limitations Section - Amendment	31-Jul-25
Airbus Helicopters AS 350 Series	EASA AD 2024-0139	Vertical Fin - Inspection	26-Jul-24
Airbus Helicopters AS 350 Series	EASA AD 2025-0025	Emergency Release Control of Cargo Swing Installation – Inspection	6-Feb-25
Airbus Helicopters AS 350 Series	EASA AD 2025-0036	Cargo Hook Assembly – Inspection	27-Feb-25
Airbus Helicopters AS 350 Series	EASA AD 2025-0137 (Correction)	Airworthiness Limitations Section - Amendment	27-Nov-25
Airbus Helicopters AS 350 Series	EASA AD 2025-0159	Sliding Door Placards - Installation	7-Aug-25
Airbus Helicopters AS 355 Series	DCA/AS355/8D	Cancelled – EASA AD 2024-0134 refers	25-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2012-0257-E	Cancelled by EASA AD 2012-0257-CN – Purpose fulfilled	25-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2021-0193	Cancelled – EASA AD 2024-0134 refer	25-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2021-0282R1 (correction)	Tail Rotor Head Pitch Change Unit Bearing Spacer - Inspection	30-Jan-25
Airbus Helicopters AS 355 Series	EASA AD 2023-0089	Cancelled – EASA AD 2024-0139 refers	26-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2023-0154R1	Vertical Upper Fin Assembly - Inspection	26-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2024-0127	Tail Rotor Drive Fan Wheel and Second Stage Impeller	25-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2024-0134	Airworthiness Limitations Section - Amendment	25-Jul-24

Airbus Helicopters AS 355 Series	EASA AD 2024-0139	Vertical Fin - Inspection	26-Jul-24
Airbus Helicopters AS 355 Series	EASA AD 2025-0025	Emergency Release Control of Cargo Swing Installation – Inspection	6-Feb-25
Airbus Helicopters AS 355 Series	EASA AD 2025-0052	Fan Support Legs – Inspection	27-Mar-25
Airbus Helicopters AS 355 Series	EASA AD 2025-0159	Sliding Door Placards - Installation	7-Aug-25
Airbus Helicopters BO105 Series	EASA AD 2025-0217	Rotor Flight Control Fork Lever - Inspection	30-Oct-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2022-0168R2	Integrated Modular Avionics, Ethernet Network - Inspection	11-Nov-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2023-0175	Altitude Correction – AFM Amendment	26-Oct-23
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2023-0213	Cargo Hook Damper - Inspection	22-Dec-23
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2024-0107	Medical Equipment Support – Inspection	17-Jun-24
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2024-0131	Main Rotor Control Rods / Pitch Links Assemblies– Inspection	25-Jul-24
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2024-0222 (correction)	Equipment Rack Extension Support Rails – Modification	30-Jan-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2024-0237-E	Tail Rotor Actuator – Inspection	11-Dec-24
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2024-0249	Warning Unit Emergency Off Switches – Operational Check	30-Jan-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0027	Swashplate Inner and Outer Ring Bolts – Inspection	27-Feb-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0028	Main Rotor Head – Inspection	27-Feb-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0029	Swashplate – Inspection	27-Feb-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0051R1	Hoist – Replacement	29-May-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0055	Rescue Hoist Cable Drum – Inspection	27-Mar-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0153	Cargo Common Hook Beam – Modification	1-Aug-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0188	Large Hook Damper Assembly – Modification	25-Sept-25
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2025-0217	Rotor Flight Control Fork Lever - Inspection	30-Oct-25
Airbus Helicopters EC 120 B	EASA AD 2020-0247	Cancelled by EASA AD 2020-0247-CN – Purpose fulfilled	25-Jul-24
Airbus Helicopters EC 120 B	EASA AD 2021-0168	Cancelled – EASA AD 2024-0018 refers	25-Jan-24
Airbus Helicopters EC 120 B	EASA AD 2023-0166	Emergency Floatation System Supply Hose - Inspection	8-Sept-23
Airbus Helicopters EC 120 B	EASA AD 2024-0018	Indicating / Recording Systems Control Unit – Inspection	25-Jan-24

Airbus Helicopters EC 120 B	EASA AD 2024-0209	Tail Rotor Hub Body – Inspection	11-Nov-24
Airbus Helicopters EC 120 B	EASA AD 2024-0243	Pilot Cyclic Stick Bonding Braid – Inspection	27-Dec-24
Airbus Helicopters EC 120 B	EASA AD 2025-0159	Sliding Door Placards - Installation	7-Aug-25
Airbus Helicopters EC 130 Series	EASA AD 2021-0168	Cancelled – EASA AD 2024-0018 refers	25-Jan-24
Airbus Helicopters EC 130 Series	EASA AD 2021-0194R1	Cancelled – EASA AD 2024-0133 refers	25-Jul-24
Airbus Helicopters EC 130 Series	EASA AD 2022-0150R1	Tail Rotor Blades - Inspection	25-Jul-24
Airbus Helicopters EC 130 Series	EASA AD 2022-0251-E	Cancelled - EASA AD 2023-0190-E refers	6-Nov-23
Airbus Helicopters EC 130 Series	EASA AD 2023-0028	Cancelled - EASA AD 2023-0214 refers	21-Dec-23
Airbus Helicopters EC 130 Series	EASA AD 2023-0133	Cancelled - EASA AD 2023-0187 refers	30-Nov-23
Airbus Helicopters EC 130 Series	EASA AD 2023-0166	Emergency Floatation System Supply Hose - Inspection	8-Sept-23
Airbus Helicopters EC 130 Series	EASA AD 2023-0187R1	Microswitches - Inspection	27-Mar-25
Airbus Helicopters EC 130 Series	EASA AD 2023-0190R1	Cancelled - EASA AD 2024-0144 refers	2-Aug-24
Airbus Helicopters EC 130 Series	EASA AD 2023-0214	Rear Transmission Bearing Support - Inspection	21-Dec-23
Airbus Helicopters EC 130 Series	EASA AD 2024-0018	Indicating / Recording Systems Control Unit – Inspection	25-Jan-24
Airbus Helicopters EC 130 Series	EASA AD 2024-0113	Tail Rotor Hub Tension-Torsion Bars – Inspection	27-Jun-24
Airbus Helicopters EC 130 Series	EASA AD 2024-0133	Airworthiness Limitations Section - Amendment	25-Jul-24
Airbus Helicopters EC 130 Series	EASA AD 2024-0144	Tail Rotor Drive Shaft - Inspection	2-Aug-24
Airbus Helicopters EC 130 Series	EASA AD 2024-0232	Door Star Support - Modification	19-Dec-24
Airbus Helicopters EC 130 Series	EASA AD 2025-0025	Emergency Release Control of Cargo Swing Installation – Inspection	6-Feb-25
Airbus Helicopters EC 130 Series	EASA AD 2025-0062	Main Rotor Blades – Inspection	3-Apr-25
Airbus Helicopters EC 130 Series	EASA AD 2025-0137 (Correction)	Airworthiness Limitations Section - Amendment	27-Nov-25
Airbus Helicopters EC 130 Series	EASA AD 2025-0159	Sliding Door Placards - Installation	7-Aug-25
Airbus Helicopters EC 130 Series	EASA AD 2025-0249-E	Cancelled – EASA AD 2025-0262-E refers	27-Nov-25
Airbus Helicopters EC 130 Series	EASA AD 2025-0262-E	Tail Rotor Drive Centre Shaft Assembly – Inspection / Replacement / Life	27-Nov-25
Airbus Helicopters EC 135 Series	EASA AD 2013-0289-E	Cancelled – EASA AD 2025-0174 refers	28-Aug-25
Airbus Helicopters EC 135 Series	EASA AD 2022-0168R2	Integrated Modular Avionics, Ethernet Network - Inspection	11-Nov-25
Airbus Helicopters EC 135 Series	EASA AD 2023-0197	Tail Rotor Drive - Inspection	30-Nov-23
Airbus Helicopters EC 135 Series	EASA AD 2024-0028R1	Tail Rotor Blades - Inspection	26-Apr-24
Airbus Helicopters EC 135 Series	EASA AD 2024-0249	Warning Unit Emergency Off Switches – Operational Check	30-Jan-25
Airbus Helicopters EC 135 Series	EASA AD 2025-0051R1	Hoist – Replacement	29-May-25
Airbus Helicopters EC 135 Series	EASA AD 2025-0055	Rescue Hoist Cable Drum – Inspection	27-Mar-25
Airbus Helicopters EC 135 Series	EASA AD 2025-0108	Cancelled – EASA AD 2025-0260 refers	1-Dec-25
Airbus Helicopters EC 135 Series	EASA AD 2025-0113	Tail Rotor Blades – Inspection	29-May-25
Airbus Helicopters EC 135 Series	EASA AD 2025-0174R1	Rear Structure / Ring Frame – Inspection	29-Sept-25
Airbus Helicopters EC 135 Series	EASA AD 2025-0260	Yaw Control System Ball Bearing – Inspection	1-Dec-25
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2010-0181	Cancelled – EASA AD 2025-0191 refers	25-Sept-25
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2021-0171R1	Tail Rotor Pitch Control Rod Bearing - Inspection	25-Jul-24

Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2024-0110	Cancelled – EASA AD 2025-0239 refers	10-Nov-25
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2024-0173	Jettisonable Windows, Sliding Doors and Fixed Panels - Modification	26-Sept-24
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2024-0244	Hoist - Inspection	20-Dec-24
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2025-0051R1	Hoist – Replacement	29-May-25
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2025-0191	Airworthiness Limitation Section - Amendment	25-Sept-25
Airbus Helicopters EC 155 and SA 365 Series	EASA AD 2025-0239	Upper Ball Bearing End of the Main Rotor Servo Controls - Inspection	10-Nov-25
Bell 205 Series	FAA AD 2024-16-01	Tail boom Attachment Cap Angle - Inspection	4-Sept-24
Bell 205 Series	FAA AD 2024-17-02	Tail Boom – Inspection	8-Nov-24
Bell 205 Series	FAA AD 2024-19-17	Main Rotor Blades Tension-Torsion Straps – Inspection	31-Oct-24
Bell 212 Series	FAA AD 2024-16-01	Tail boom Attachment Cap Angle - Inspection	4-Sept-24
Bell 212 Series	FAA AD 2024-16-19	Tail Boom – Inspection	8-Nov-24
Bell 212 Series	FAA AD 2024-19-17	Main Rotor Blades Tension-Torsion Straps – Inspection	31-Oct-24
Bell 407 Series	TC AD CF-2022-68	Cancelled - CF-2025-59 refers	3-Dec-25
Bell 407 Series	TC AD CF-2023-63	Tail Rotor Blades - Inspection	19-Aug-23
Bell 407 Series	TC AD CF-2024-18	Cyclic Stick Tube - Inspection	25-Jul-24
Bell 407 Series	TC AD CF-2025-21R1	Main Rotor Expandable Blade Bolts - Inspection	1-Dec-25
Bell 407 Series	TC AD CF-2025-22	Electrical Harness Chafing - Inspection	29-May-25
Bell 407 Series	TC AD CF-2025-59	Tail Boom - Inspection	3-Dec-25
Bell 412 Series	DCA/BELL412/3	Cancelled – AD 2000-18-09 superseded by AD 2024-16-01	4-Sept-24
Bell 412 Series	FAA AD 2024-16-01	Tail boom Attachment Cap Angle - Inspection	4-Sept-24
Bell 412 Series	FAA AD 2024-16-19	Tail Boom – Inspection	8-Nov-24
Bell 427	TC AD CF-2024-42	Transmission Oil Check Valve – Inspection	27-Dec-24
Bell 427	TC AD CF-2025-21R1	Main Rotor Expandable Blade Bolts - Inspection	1-Dec-25
Bell 429	TC AD CF-2024-11	Cancelled - Transport Canada AD CF-2025-29 refers	10-Jun-25
Bell 429	TC AD CF-2025-16	Stability and Control Augmentation System Actuators - Inspection	31-Mar-25
Bell 429	TC AD CF-2025-29	Tail Rotor Blade Abrasion Strip Cracks - Inspection	10-Jun-25
Bell 429	TC AD CF-2021-15	Cancelled - CF-2025-60 refers	8-Dec-25
Bell 429	TC AD CF-2025-60	TRGB Support Assembly to Tail Boom Attachment - Inspection	8-Dec-25
Bell 505	TC AD CF-2023-16R1	Fuel and Control - AFM Limitations	2-Aug-23
Bell 505	TC AD CF-2024-03	Cancelled – CF-2025-32 refers	16-Jul-25
Bell 505	TC AD CF-2024-44	Wire Harness Chafing - Inspection	30-Jan-25
Bell 505	TC AD CF-2025-17	Cancelled - CF-2025-35 refers	18-Jul-25
Bell 505	TC AD CF-2025-23	Oil Cooler Fan Assembly Housing Bracket - Inspection	7-May-25

Bell 505	TC AD CF-2025-32	Vertical Stabiliser Top End Cap Assembly - Inspection	16-Jul-25
Bell 505	TC AD CF-2025-34	Tail Rotor Pitch Link Assembly - Inspection	31-Jul-25
Bell 505	TC AD CF-2025-35	Aft Moveable Ballast Box Assembly Door Hinge - Inspection	18-Jul-25
Bell UH-1 Series	FAA AD 2024-19-17	Main Rotor Blades Tension-Torsion Straps – Inspection	31-Oct-24
Guimbal Cabri G2	EASA AD 2023-0204-E	Cancelled – EASA AD 2024-0007-E refers	10-Jan-24
Guimbal Cabri G2	EASA AD 2024-0007-E	Pilot and Copilot Cyclic Stick Base - Inspection	10-Jan-24
Guimbal Cabri G2	EASA AD 2024-0071	Swashplate - Inspection	21-Mar-24
Helicopters - General	FAA AD 2024-20-04	Cancelled - Refer to Aircraft Seats and Harnesses	25-Sept-25
Helicopters - General	FAA AD 2024-20-07	Emergency Float System - Inspection	5-Dec-24
Hiller UH-12C and UH-12E	FAA AD 2025-15-02	Main Rotor Transmission Drive Shaft – Inspection	24-Sept-25
Kawasaki BK117 Series	JCAB AD TCD-10427-2025	Main Rotor Head – Inspection	24-Apr-25
Kawasaki BK117 Series	JCAB AD TCD-10553-2025	Main Rotor System Fork Lever – Inspection	4-Nov-25
Leonardo A109 and AW109 Series	EASA AD 2022-0153	Cancelled – EASA AD 2024-0004 refers	19-Jan-24
Leonardo A109 and AW109 Series	EASA AD 2023-0159	Main Rotor Blade Tip Caps – Inspection	24-Aug-23
Leonardo A109 and AW109 Series	EASA AD 2024-0004	Centre Fuselage Frame Assembly – Inspection	19-Jan-24
Leonardo A109 and AW109 Series	EASA AD 2024-0193	Engine Fire Extinguisher Bottle Connections – Inspection	31-Oct-24
Leonardo A109 and AW109 Series	EASA AD 2024-0228 (Correction)	Hoist – Inspection	19-Jun-25
Leonardo A109 and AW109 Series	EASA AD 2025-0051R1	Hoist – Replacement	29-May-25
Leonardo A109 and AW109 Series	EASA AD 2025-0131	Main Rotor Swashplate Nuts – Inspection	30-Jun-25
Leonardo A109 and AW109 Series	EASA AD 2025-0142R1	Cyclic Pitch and Roll Actuators – Inspection	25-Sept-25
Leonardo A109 and AW109 Series	EASA AD 2025-0148	Swashplate Duplex Bearing – Inspection	31-Jul-25
Leonardo A119 and AW119 Series	EASA AD 2023-0210	Battery - Modification	11-Dec-23
Leonardo A119 and AW119 Series	EASA AD 2025-0131	Main Rotor Swashplate Nuts – Inspection	30-Jun-25
Leonardo A119 and AW119 Series	EASA AD 2025-0142R1	Cyclic Pitch and Roll Actuators – Inspection	25-Sept-25
Leonardo A119 and AW119 Series	EASA AD 2025-0148	Swashplate Duplex Bearing – Inspection	31-Jul-25
Leonardo A119 and AW119 Series	EASA AD 2025-0199	Pneumatic Line – Inspection	30-Sept-25
Leonardo AW169 Helicopters	EASA AD 2022-0178	Cancelled – EASA AD 2023-0160 refers	31-Aug-23
Leonardo AW169 Helicopters	EASA AD 2023-0160	Maintenance Checks – Airworthiness Limitations	31-Aug-23
Leonardo AW169 Helicopters	EASA AD 2023-0188-E	Float Assemblies - Replacement	1-Nov-23
Leonardo AW169 Helicopters	EASA AD 2025-0051R1	Hoist – Replacement	29-May-25
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2024-23-06	Cyclic Torque Tube Assembly - Inspection	24-Dec-24
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2025-17-11	Tail Rotor Pedal Support Bracket - Inspection	10-Oct-25
MD 600N Helicopters	FAA AD 2024-23-06	Cyclic Torque Tube Assembly - Inspection	24-Dec-24
MD 600N Helicopters	FAA AD 2025-17-11	Tail Rotor Pedal Support Bracket - Inspection	10-Oct-25
Robinson R22 Series	FAA AD 2024-04-02	Tail Rotor Blades - Inspection	2-Apr-24
Robinson R22 Series	FAA AD 2024-20-03	Engine Governor - Replacement	29-Nov-24
Robinson R44 Series	FAA AD 2024-04-02	Tail Rotor Blades - Inspection	2-Apr-24

Robinson R44 Series	FAA AD 2024-19-11	Cancelled – FAA AD 2025-11-07 refers	11-Jul-25
Robinson R44 Series	FAA AD 2024-20-03	Engine Governor - Replacement	29-Nov-24
Robinson R44 Series	FAA AD 2024-23-01	Belt Tension Clutch Actuator Brackets - Inspection	7-Jan-25
Robinson R44 Series	FAA AD 2025-11-07	Engine / Transmission Coupling - Inspection	11-Jul-25
Robinson R66	FAA AD 2024-04-02	Tail Rotor Blades - Inspection	2-Apr-24
	EASA AD 2021-0069	Cancelled - EASA AD 2024-0209 refers	11-Nov-24
Amateur Built	Amateur Built		
Amateur Built - Rotorway Helicopters	UK CAA MPD 2014-003	(Correction) Aluminium Engine Cam Gear P/N A24-1502 – Life Limitation	30-May-24
Microlights	Microlights		
Ex-military and Vintage Aircraft Factory Built – Not type certified	Ex-military and Vintage Aircraft Factory Built – Not type certified		
Ex-military Aircraft	UK CAA MPD 2018-003R2	Assisted Escape Systems - Inspection	21-Dec-23
Gliders	Gliders		
DG Aviation Gliders	EASA AD 2024-0126	Automatic Elevator Connection – Inspection	25-Jul-24
DG Aviation Gliders	EASA AD 2025-0056	Airspeed Indicator and Placards – Modification	18-Mar-25
Grob Gliders	EASA AD 2025-0140	Rudder Drive Plate – Inspection	31-Jul-25
Schempp-Hirth	DCA/SH/11	Cancelled – EASA AD 2024-0242R1 refers	30-Jan-25
Schempp-Hirth	EASA AD 2024-0242R1	Horizontal Tailplane Drive Lower Bearing – Modification	30-Jan-25
Schempp-Hirth	EASA AD 2024-0251	Cancelled – EASA AD 2025-0157 refers	4-Aug-25
Schempp-Hirth	EASA AD 2025-0157	Wing Fuel Tank Hose – Inspection	4-Aug-25
Schempp-Hirth Gliders	EASA AD 2024-0059	Canopy Locking Mechanism – Modification	28-Mar-24
Schempp-Hirth Gliders	EASA AD 2024-0242	Horizontal Tailplane Drive Lower Bearing – Modification	26-Dec-24
Balloons	Balloons		
Balloons - Fuel Cylinder P/N CB2990	UK CAA AD G-2022-0010-E	Cancelled – UK CAA AD G-2023-0005-E refers	2-Aug-23
Balloons - Fuel Cylinder P/N CB2990	UK CAA AD G-2023-0005-E	Cameron Fuel Cylinders – Inspection	2-Aug-23
Balloons - Lindstrand Envelopes	UK CAA AD G-2024-0001-E	Envelopes with Polyester Filled Aramid (Kevlar) Load Tapes – Removal from Service	2-May-24
Balloons - Occupant restraint harnesses P/N CI-C-1302	EASA AD 2024-0094	Occupant Restraint Harness – Inspection	30-May-24
Balloons - PRV Adaptor CB8426	UK CAA AD G-2025-0001R1-E	Cancelled – UK CAA AD G-2025-0004-E refers	28-Aug-25
Balloons - PRV Adaptor CB8426	UK CAA AD G-2025-0004-E	Pressure Relief Valves (PRV) Adaptor CB8426 – Inspection	28-Aug-25
Engines	Engines		
Austro E4 Series Engines	EASA AD 2022-0240R1	Cancelled – EASA AD 2023-0163 Refers	1-Sept-23
Austro E4 Series Engines	EASA AD 2023-0163	Pistons – Oil Analysis/Replacement	1-Sept-23
Austro E4 Series Engines	EASA AD 2024-0037R1	Engine Main Bearing / Studs – Replacement	6-Feb-24
Austro E4 Series Engines	EASA AD 2024-0172-E	Piston – Inspection / Replacement	30-Aug-24
Continental 300 Series	FAA AD 2022-04-04	Cancelled – FAA AD 2023-17-04 refers	26-Oct-23
Continental 300 Series	FAA AD 2023-17-04	Oil Filter Adapter – Inspection	26-Oct-23

Continental 360 Series	FAA AD 2022-04-04	Cancelled – FAA AD 2023-17-04 refers	26-Oct-23
Continental 360 Series	FAA AD 2023-17-04	Oil Filter Adapter – Inspection	26-Oct-23
Continental 470 Series	FAA AD 2022-04-04	Cancelled – FAA AD 2023-17-04 refers	26-Oct-23
Continental 470 Series	FAA AD 2023-17-04	Oil Filter Adapter – Inspection	26-Oct-23
Continental 520 Series	FAA AD 2022-04-04	Cancelled – FAA AD 2023-17-04 refers	26-Oct-23
Continental 520 Series	FAA AD 2023-17-04	Oil Filter Adapter – Inspection	26-Oct-23
Continental 550 Series	FAA AD 2022-04-04	Cancelled – FAA AD 2023-17-04 refers	26-Oct-23
Continental 550 Series	FAA AD 2023-17-04	Oil Filter Adapter – Inspection	26-Oct-23
Continental TAE 125-01 and TAE 125-02 Series	EASA AD 2024-0236	Engine Coolant Contamination – Inspection	17-Dec-24
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2024-0040-E	Cancelled – EASA AD 2024-0194 refers	31-Oct-24
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2024-0194	Centrifugal Compressor Case - Inspection	31-Oct-24
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2025-0022	Fuel Control System – Additive Application	4-Feb-25
Lycoming AEIO-320, IO-320 and LIO-320 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming AEIO-360, HIO-360, IO-360 and LIO-360 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming AEIO-390 and IO-390 Series	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming AEIO-540 and IO-540 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming AEIO-580 and IO-580 Series	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming HO-360, LO-360 and O-360 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming IVO-360-A1A Engine and VO-360 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming LTIO-540 and TIO-540 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming LTO-360 and TO-360 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming O-235 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming O-320 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming O-540 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming TIO-360 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming TVO-435 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming VO-435 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Lycoming VO-540 Series Engines	FAA AD 2024-21-02	Connecting Rod Assemblies - Inspection	5-Dec-24
Pratt & Whitney PT6 Series	TC AD CF-2024-05	Second Stage Power Turbine (PT2) Blades - Inspection	17-Feb-24

Pratt & Whitney PT6 Series	TC AD CF-2024-33	First Stage Power Turbine (PT1) Blades - Inspection	30-Sept-24
Pratt & Whitney PW210A and PW210S engines	TC AD CF-2020-13	Impeller and HP Compressor Rotor Cycle Count – Manual Calculation	29-May-25
Rotax Engines	EASA AD 2023-0156-E	Propeller Gearbox – Magnetic Plug Inspection	4-Aug-23
Rotax Engines	EASA AD 2025-0019-E	Internal Generator - Inspection	20-Jan-25
Rotax Engines	UK CAA MPD 2023-002-E	Propeller Gearbox – Magnetic Plug Inspection	15-Aug-23
Rotax Engines	UK CAA MPD 2025-001-E	Internal Generator - Inspection	10-Feb-25
Safran Helicopter Engines Arriel 1 Series	EASA AD 2024-0207R1	(Correction) Gas Generator 1 st Stage HP Turbine Blades – Cancelled by E	27-Mar-25
Safran Helicopter Engines Arriel 2 Series	EASA AD 2022-0083	Cancelled – EASA AD 2025-0079 refers	24-Apr-25
Safran Helicopter Engines Arriel 2 Series	EASA AD 2025-0079	Airworthiness Limitations	24-Apr-25
Safran Helicopter Engines Arrius 1A Series	DCA/TUR/55	Cancelled – AD 2008-0133 superseded by AD 2024-0148	28-Aug-24
Safran Helicopter Engines Arrius 1A Series	DCA/TUR/59	Cancelled – AD F-2005-063R1 superseded by AD 2024-0148	28-Aug-24
Safran Helicopter Engines Arrius 1A Series	EASA AD 2024-0148	Airworthiness Limitations – Amendment	28-Aug-24
Safran Helicopter Engines Arrius 2B and 2K Series	EASA AD 2022-0203	Cancelled – EASA AD 2024-0149 refers	28-Aug-24
Safran Helicopter Engines Arrius 2B and 2K Series	EASA AD 2024-0149	Airworthiness Limitations – Amendment	28-Aug-24
Safran Helicopter Engines Arrius 2B1, 2B2 and 2K1 Series	EASA AD 2024-0195R1	EECU Software - Update & Preference Injector - Non-extinguishing Test	1-Nov-24
Safran Helicopter Engines Arrius 2F and 2R Series	DCA/TUR/29	DGAC AD F-2005-088 cancelled by EASA AD 2024-0115-CN – Purpose fulfilled	25-Jul-24
Safran Helicopter Engines Arrius 2F and 2R Series	EASA AD 2024-0202R1	Fuel Control Unit - Replacement	25-Sept-25
Safran Helicopter Engines Arrius 2F and 2R Series	EASA AD 2024-0218R1	Gas Generator HP Turbine Blades - Cancelled by EASA	27-Mar-25
Williams International FJ44 Series	FAA AD 2022-13-15	Turbine Section - Inspection	31-Oct-24
Williams International FJ44 Series	FAA AD 97-01-05	Disk Posts and Turbine Blades - Inspection	31-Oct-24
Williams International FJ44 Series	FAA AD 99-07-04	High Pressure Turbine (HPT) Disk - Inspection	31-Oct-24
Propellers	Propellers		
Woodward Constant Speed Propeller Governors	DCA/WOOD/114	Cancelled – Maule M5 235C FAA AD 81-25-01 refers	31-Jul-25
Components & Equip**	Components & Equip**		
Aircraft Seats and Harnesses	FAA AD 2021-07-13	Cancelled – FAA AD 2024-26-02 refers	7-Mar-25
Aircraft Seats and Harnesses	FAA AD 2024-20-04	Rotary Buckle Assembly – Inspection	25-Sept-25
Aircraft Seats and Harnesses	FAA AD 2024-26-02	Pacific Scientific Company Rotary Buckle Assemblies – Inspection	7-Mar-25
Aircraft Seats and Harnesses	FAA AD 2025-16-09	Rotary Buckle Assembly - Inspection	22-Sept-25
Aircraft Seats and Harnesses	UK CAA AD G-2025-0005	Acro Series 9 Passenger Seats – Inspection	2-Oct-25
Avionics Equipment	DCA/RAD/9B	Radio Altimeter Antennae - Inspection	29-May-25

Avionics Equipment	FAA AD 2025-07-01 (Correction)	Thommen AC32 Digital Air Data Computers (ADCs) - Inspection	29-May-25
Brakes & Wheels	Brazilian AD 2025-08-01R1	Wheel and Brake Assemblies - Inspection	28-Aug-25
Emergency Equipment	EASA AD 2025-0222	Portable Breathing Equipment – Operational Instructions	30-Oct-25
Instruments & Automatic Pilots	FAA AD 2024-14-03	Garmin GFC 500 Autopilot System – Inspection	20-Aug-24

Notes:

* The AD Schedule often covers a complete series of types.

** This is not the AD Schedule title but more specific to the components affected.

*** AD Numbering - If the AD number is less than 10, a zero has been added before the number.

This is for sorting only and the AD should still be referred to as in the AD Schedule.