

List of NZ CAA ADs issued in the last 27 months as at Amendment Nr 21-04

AD Schedule*	AD	AD Title
Aeroplanes	Aeroplanes	
Aeroplanes General - Small	DCA/GEN/6A	Flight Control Cable End Assemblies - Proof Load
Aerostar 600 & 601 Series	FAA AD 2002-24-07	Roto-Master and Rajay Scavenge Pumps – Inspection
Aerostar 600 & 601 Series	FAA AD 80-18-03	Fuel Pressure System – Fuel Gauge Markings and AFM Amendment
Aerostar 600 & 601 Series	FAA AD 87-21-01	Fuel Filler Openings – Inspection
Aerostar 600 & 601 Series	FAA AD 88-21-05	Exhaust Systems STC SA980NM – Inspection
Aerostar 600 & 601 Series	FAA AD 88-25-02	Engine Fluid Hoses – Inspection
Air Tractor AT-402 Series	FAA AD 2021-05-14	Flap Torque Tube Actuator Attachment Brackets – Inspection
Air Tractor AT-602 Series	FAA AD 2021-05-14	Flap Torque Tube Actuator Attachment Brackets – Inspection
Aviat A-1 (Husky) Series	FAA AD 2019-10-06	Fuel Vent Check Valve – Inspection and AFM Amendment
Aviat A-1 (Husky) Series	FAA AD 2020-16-06	Forward Horizontal Stabiliser Support Assembly – Inspection
Aviat Aircraft Inc. (Pitts)	DCA/PITTS/1A	Airworthiness Directive Compliance at Initial C of A Issue
Aviat Aircraft Inc. (Pitts)	FAA AD 2006-12-07	ECi Cylinder Assemblies
Aviat Aircraft Inc. (Pitts)	FAA AD 2019-10-06	Fuel Distribution
Aviat Aircraft Inc. (Pitts)	FAA AD 90-20-05	Forward Seat Back
Aviat Aircraft Inc. (Pitts)	FAA AD 91-23-02	Carburettor Air Intake Box
Aviat Aircraft Inc. (Pitts)	FAA AD 96-09-06	Air Filter Assemblies
Beechcraft 35 & 36 Series (Bonanza)	FAA AD 2019-21-08	Cancelled – FAA AD 2019-23-10 refers
Beechcraft 35 & 36 Series (Bonanza)	FAA AD 2019-23-10	Aileron Flight Control Cables - Inspection
Beechcraft 76 Series (Duchess)	DCA/B76/10B	Cancelled – FAA AD 2021-08-06 refers
Beechcraft 76 Series (Duchess)	FAA AD 2021-08-06	MLG “A” Frame Assemblies - Inspection
Cessna 172 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection
Cessna 180 Series	FAA AD 2020-21-22	Tailcone and Horizontal Stabiliser – Inspection
Cessna 180 Series	FAA AD 62-17-04	Float Installation STC SA1-622 - Inspection
Cessna 180 Series	FAA AD 73-23-07	Defective Spar Attachment Fittings - Inspection
Cessna 180 Series	FAA AD 81-15-03	Engine Inlet Air Filter STC SA71GL - Inspection
Cessna 180 Series	FAA AD 83-17-06	Aileron Balance Weights STC SA1435WE - Inspection
Cessna 180 Series	FAA AD 86-24-07	Engine Controls Installation - Inspection
Cessna 180 Series	FAA AD 96-12-22	Full Flow Engine Oil Adaptor - Inspection
Cessna 180 Series	FAA AD 98-21-21R1	Electric Inflatable Door Seals STC SA4284WE - Inspection
Cessna 182 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection
Cessna 182 Series	FAA AD 2020-21-22	Tailcone and Horizontal Stabiliser – Inspection
Cessna 185 Series	FAA AD 2020-21-22	Tailcone and Horizontal Stabiliser – Inspection
Cessna 188 Series	DCA/CESS188/114B	Cancelled – Purpose Fulfilled

Cessna 206 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection
Cessna 207 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection
Cessna 208 Series	FAA AD 2021-04-10	Elevator Torque Tube – Inspection
Cessna 210 Series	FAA AD 2020-03-16	Carry-Thru Spar Lower Cap– Inspection
Cessna 210 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection
De Havilland DHC-2 (Beaver)	CASA AD/DHC-2/15 Amdt 1 (Correction)	Main Undercarriage Lower Forward Bolt Attachment – Inspection
De Havilland DHC-2 (Beaver)	DCA/C2/143	Cancelled – CASA AD/DHC-2/15 Amdt 1 refers
De Havilland DHC-2 (Beaver)	DCA/C2/160A	Cancelled – CF-2020-22 refers
De Havilland DHC-2 (Beaver)	TC AD CF-2017-33	Cancelled - CF-2019-25 refers
De Havilland DHC-2 (Beaver)	TC AD CF-2019-25	Airframe Corrosion - Inspection
De Havilland DHC-2 (Beaver)	Transport Canada CF-2020-22	Fuselage Struts - Inspection
De Havilland DHC-3 (Otter)	Transport Canada CF-2020-20	Wing Strut – Inspection
Diamond DA 40 Series	EASA AD 2012-0180	Airspeed Indicator Markings / Placard – Installation
Diamond DA 40 Series	EASA AD 2013-0018	Turbo Intercooler Installation – Inspection
Diamond DA 40 Series	EASA AD 2016-0190	Auto-pilot Bridle Cable Clamps – Inspection
Diamond DA 40 Series	EASA AD 2016-0203	V-band Clamps – Inspection
Diamond DA 40 Series	TC AD CF-2019-39	Fuel Tank Connection Hose – Inspection
Diamond DA 42 Series	EASA AD 2012-0269	Air Intake / Induction Filter Icing – AFM Revision
Diamond DA 42 Series	EASA AD 2013-0224	Alternator Fail Indication – Modification
Diamond DA 42 Series	EASA AD 2016-0190	Auto-pilot Bridle Cable Clamps – Inspection
Diamond DA 42 Series	EASA AD 2017-0074	Cancelled – EASA AD 2020-0008 refers
Diamond DA 42 Series	EASA AD 2018-0214	Rudder Pedal Gust Lock Mounts – Removal
Diamond DA 42 Series	EASA AD 2019-0066	NLG Leg Assembly – Inspection
Diamond DA 42 Series	EASA AD 2019-0218	Fuel Tank Connection Hoses – Inspection
Diamond DA 42 Series	EASA AD 2019-0302	Rudder T-Yoke Axle Self-Locking Nut – Inspection
Diamond DA 42 Series	EASA AD 2020-0008	Flap Control System / Bellcrank Assembly – Inspection
Embraer EMB-500	Brazilian ANAC AD 2009-02-04	Flap System – Inspection
Embraer EMB-500	Brazilian ANAC AD 2009-09-01	Elevator Mass Balance Fasteners – Inspection
Embraer EMB-500	Brazilian ANAC AD 2009-10-01R3	ADS Sensors - Inspection
Embraer EMB-500	Brazilian ANAC AD 2010-07-01	Drain Holes in Control Surfaces – Inspection
Embraer EMB-500	Brazilian ANAC AD 2010-08-01	Cabin Pressurization - Inspection
Embraer EMB-500	Brazilian ANAC AD 2010-09-02	Harness W101 - Inspection
Embraer EMB-500	Brazilian ANAC AD 2011-05-03	Angle of Attack (AOA) Sensor – Inspection
Embraer EMB-500	Brazilian ANAC AD 2014-07-03	Stabilizer Joint – Inspection
Embraer EMB-500	Brazilian ANAC AD 2016-04-02	Optimized Performance Analyser Software – AFM Revision

Embraer EMB-500	Brazilian ANAC AD 2016-05-01	Passenger Seat Attachment – Inspection
Embraer EMB-500	Brazilian ANAC AD 2017-11-01	Aileron, Rudder and Elevator – Inspection
Embraer EMB-500	Brazilian ANAC AD 2020-05-03	Operation at Static Temperature Below -54 Deg Celsius – Inspection
Extra EA 300 Series	EASA AD 2006-0281	Upper Longeron at the Horizontal Stabiliser – Inspection
Extra EA 300 Series	EASA AD 2009-0160	Tail Spring Support – Inspection
Extra EA 300 Series	EASA AD D-1994-043R1	Upper Longeron Cutout Bridge – Inspection
Extra EA 300 Series	EASA AD D-2004-489	Bottom Fuselage Cover/Firewall Sealing – Inspection
Extra EA 300 Series	LBA AD 1992-199	Elevator Mass Balance Support – Inspection
Extra EA 300 Series	LBA AD 1993-081	Rudder Control Cable Compression Sleeve – Inspection
Extra EA 300 Series	LBA AD 1993-145/2	Wing Root Rib/Auxiliary Spar Attachment - Inspection
Extra EA 300 Series	LBA AD 1994-258	Canopy Latches - Inspection
Extra EA 300 Series	LBA AD 1995-125	Air Inlet Screen - Inspection
Extra EA 300 Series	LBA AD 1995-126	Engine Cowling and Firewall Fire Protection – Inspection
Extra EA 300 Series	LBA AD 1995-443	Rudder Pedal Safety Control Stop – Inspection
Extra EA 300 Series	LBA AD 1997-203/2	Front Seat Belt Safety Cover – Inspection
Extra EA 300 Series	LBA AD 2002-408	Fuel Selector Valve – Inspection
Gulfstream Aerospace GA-7	FAA AD 78-20-09	Fuel Selector Valves – Inspection
Gulfstream Aerospace GA-7	FAA AD 78-22-06	Elevator Control – Inspection
Gulfstream Aerospace GA-7	FAA AD 79-03-06	Rudder Assembly – Inspection
Gulfstream Aerospace GA-7	FAA AD 79-05-06	Main Fuel Line – Inspection
Gulfstream Aerospace GA-7	FAA AD 79-05-07	Fuel Tank Ribs – Inspection
Jabiru series aircraft	CASA AD/JABIRU/3	Aileron Control Tube - Inspection
Mitsubishi MU-2B-26A/-60 Series	DCA/MU2/17C	FAA AD 75-16-20 Cancelled - FAA AD 2020-26-14 refers
Mitsubishi MU-2B-26A/-60 Series	FAA AD 2016-08-19	MLG Oleo Strut Attach Fittings – Inspection
Mitsubishi MU-2B-26A/-60 Series	FAA AD 2020-26-14	Propeller Pitch Control Lever – Inspection
Mitsubishi MU-2B-30 Series	DCA/MU2B-30/1A	Airworthiness Directive Compliance
Mitsubishi MU-2B-30 Series	JCAB AD TCD-4753B-2020	Pilot in Charge Training Requirements
Pacific Aerospace 750XL	DCA/750XL/32B	NLG and MLG Attachment Bolts – Inspection
Pacific Aerospace 750XL	DCA/750XL/33A	Aileron Pivot Fork Assembly – Inspection
Pacific Aerospace 750XL	DCA/750XL/34	Port Wing Internal Tank Abrasion – Inspection
Pacific Aerospace 750XL	DCA/750XL/35	Engine Mount Chafing – Inspection
Pacific Aerospace 750XL	DCA/750XL/36	Fuel Pickup Assembly and Wing Spar Web – Inspection
Pacific Aerospace 750XL	DCA/750XL/37	Engine Fuel Lines and Electrical Wiring – Inspection
Pacific Aerospace 750XL	DCA/750XL/38A	Flap Assembly Screw Jack – Inspection
Pacific Aerospace 750XL	DCA/750XL/39	Fuel Condition Lever – Inspection
Pacific Aerospace Cresco 08-600	DCA/CRESCO/22	Wing Main Spar Assembly - Inspection
Pacific Aerospace CT/4 series aircraft	DCA/CT4/8	Flap Actuator Assembly – Inspection

Pacific Aerospace CT/4 Series Airtrainer	DCA/CT4/9	Wing Rear Spar – Inspection
Partenavia (Vulcanair) P68 Series	DCA/P68/18B	Wing Spar - Inspection
Pilatus PC-12 Series	EASA AD 2016-0083	Cancelled – EASA AD 2021-0005 (Correction) refers
Pilatus PC-12 Series	EASA AD 2019-0032	MLG Spring Pack Assemblies – Inspection
Pilatus PC-12 Series	EASA AD 2019-0231	Flap Drive System – Inspection
Pilatus PC-12 Series	EASA AD 2020-0229	Fuel Transfer Injector – Inspection
Pilatus PC-12 Series	EASA AD 2021-0005 (Correction)	Airworthiness Limitations - Amendment
Pilatus PC-12 Series	EASA AD 2021-0010	Inward Vent Valve – Inspection
Pilatus PC-12 Series	EASA AD 2021-0110	Nose Landing Gear Fork Assembly - Inspection
Pilatus PC-12 Series	EASA AD 2019-0129	Horizontal Stabiliser Rear Attachment Bolts – Inspection
Pilatus PC-6 Series	DCA/PC6/38	Cancelled – EASA AD 2021-0098 refers
Pilatus PC-6 Series	EASA AD 2014-0181	Cancelled – EASA AD 2018-0285 refers
Pilatus PC-6 Series	EASA AD 2018-0285	Cancelled – EASA AD 2020-0120 refers
Pilatus PC-6 Series	EASA AD 2020-0120	Cancelled – EASA AD 2020-0278 refers
Pilatus PC-6 Series	EASA AD 2020-0278	Airworthiness Limitations
Pilatus PC-6 Series	EASA AD 2021-0098	Aileron, Elevator and Rudder Hinge Bolts – Inspection
Piper PA-23 Series	DCA/PA-23/147A	Cancelled – FAA AD 80-18-10 refers
Piper PA-23 Series	DCA/PA-23/157	Cancelled – FAA AD 80-18-10 refers
Piper PA-23 Series	FAA AD 80-18-10	Fuel Valves and Cables – Inspection
Piper PA-28 Series	FAA AD 2020-24-05	Wing Spars – Inspection
Piper PA-28 Series	FAA AD 2020-26-16	Wing Spars – Inspection
Piper PA-31 Series	DCA/PA31/29B	Cancelled – FAA AD 80-18-10 refers
Piper PA-31 Series	DCA/PA31/47A	Cancelled – FAA AD 80-18-10 refers
Piper PA-31 Series	DCA/PA31/54	Cancelled – FAA AD 82-27-13R2 refers
Piper PA-31 Series	FAA AD 80-18-10	Fuel Valves and Cables – Inspection
Piper PA-32 Series	FAA AD 2020-24-05	Wing Spars - Inspection
Piper PA-32 Series	FAA AD 2020-26-16	Wing Spars – Inspection
Piper PA-34 Series	FAA AD 2020-24-09	Rudder Flight Control Cables – Inspection
Piper PA-46 Series	FAA AD 2021-09-02	Stall Warning Heat Control System – Inspection
Reims F406	DCA/REIMS406/14	Cancelled – EASA AD 2019-0015 refers
Reims F406	EASA AD 2015-0159R1	Cancelled – EASA AD 2019-0016 refers
Reims F406	EASA AD 2019-0015	Circuit Breaker Switches – Inspection
Reims F406	EASA AD 2019-0016	Rudder Control Pedal Torque Tubes – Inspection
Robin DR400 Series	EASA AD 2019-0211	Thermostatic Oil Cooler Bypass Valve – Inspection
Robin DR400 Series	EASA AD 2019-0242	Disc Braking System – AFM Amendment
Robin DR400 Series	EASA AD 2019-0292	Stabilator – Inspection

Agusta Bell AB212	EASA AD IT-1977-090	Engine Mount Bearing Assembly - Inspection
Agusta Bell AB212	EASA AD IT-1977-122	Tail Rotor Drive Transmission - Inspection
Agusta Bell AB212	EASA AD IT-1977-130	Passenger Door Assemblies - Inspection
Agusta Bell AB212	EASA AD IT-1977-166	Tail Rotor Driveshaft - Inspection
Agusta Bell AB212	EASA AD IT-1977-172	Emergency Escape Release Door Handle Covers - Inspection
Agusta Bell AB212	EASA AD IT-1977-198	Tail Rotor Pitch Change Horn - Inspection
Agusta Bell AB212	EASA AD IT-1977-245	Hydraulic Actuators - Inspection
Agusta Bell AB212	EASA AD IT-1978-005	Main Rotor Blades – Inspection
Agusta Bell AB212	EASA AD IT-1978-006	Main Rotor Blades Skin Cracks – Inspection
Agusta Bell AB212	EASA AD IT-1978-094	Landing Gear Forward Cross Tube Assemblies – Inspection
Agusta Bell AB212	EASA AD IT-1978-131	Main Rotor Blades – Inspection
Agusta Bell AB212	EASA AD IT-1978-159	Emergency Float Kits – Inspection
Agusta Bell AB212	EASA AD IT-1978-160	Float Landing Gear – Inspection
Agusta Bell AB212	EASA AD IT-1978-161	Main Rotor Hub Inboard Fitting – Inspection
Agusta Bell AB212	EASA AD IT-1978-163	Emergency Exits – Inspection
Agusta Bell AB212	EASA AD IT-1978-166	Main Rotor Drive Centre Line Firewall – Inspection
Agusta Bell AB212	EASA AD IT-1978-180	Passenger Door Emergency Escape Panels – Inspection
Agusta Bell AB212	EASA AD IT-1978-192	External Cargo Hook Link Assembly – Inspection
Agusta Bell AB212	EASA AD IT-1978-211	Skid Landing Gear – Inspection
Agusta Bell AB212	EASA AD IT-1978-219	Flight Control Rods and Bellcranks – Inspection
Agusta Bell AB212	EASA AD IT-1978-245	Main Rotor Drive Spiral Bevel Gear – Inspection
Agusta Bell AB212	EASA AD IT-1979-062	Emergency Flotation Equipment – Inspection
Agusta Bell AB212	EASA AD IT-1979-187	Main Rotor Blades – Inspection
Agusta Bell AB212	EASA AD IT-1979-188	Main Rotor Blades Steel Grip Pad – Inspection
Agusta Bell AB212	EASA AD IT-1980-036	Main Rotor Hub Assembly – Inspection
Agusta Bell AB212	EASA AD IT-1980-252	Main Rotor Hub Strap Assemblies – Inspection
Agusta Bell AB212	EASA AD IT-1980-253	Main Rotor Hub Strap Assemblies – Inspection
Agusta Bell AB212	EASA AD IT-1981-055	Main Rotor Mast Bearing – Inspection
Agusta Bell AB212	EASA AD IT-1981-057	Main Rotor Swashplate Filter – Inspection
Agusta Bell AB212	EASA AD IT-1981-107	Main Rotor Swashplate Support – Inspection
Agusta Bell AB212	EASA AD IT-1981-224	Main Rotor Yokes – Inspection
Agusta Bell AB212	EASA AD IT-1986-030	Main Rotor Swashplate Bearing – Inspection
Agusta Bell AB212	EASA AD IT-1989-165	Main Rotor Transmission Internal Sump Oil Filter – Inspection
Agusta Bell AB212	EASA AD IT-1989-272	Landing Gear Cross Tubes – Inspection
Agusta Bell AB212	EASA AD IT-1991-074	Main Rotor Drag Brace Assemblies – Inspection
Agusta Bell AB212	EASA AD IT-1993-079	Tail Rotor Driveshaft Hanger Bearing – Inspection
Agusta Bell AB212	EASA AD IT-1993-116	Main Rotor Yokes – Inspection

Agusta Bell AB212	EASA AD IT-1993-157	Main Rotor Pillow Blocks – Inspection
Agusta Bell AB212	EASA AD IT-1994-261	Main Rotor Retension Strap – Inspection
Agusta Bell AB212	EASA AD IT-1994-273	Main Transmission Lower Planetary Spider – Inspection
Agusta Bell AB212	EASA AD IT-1997-195	Tail Rotor Blades – Inspection
Agusta Bell AB212	EASA AD IT-1997-226	Tail Rotor Flapping Loads – Inspection
Agusta Bell AB212	EASA AD IT-1998-282	Tail Rotor Yoke Assembly – Inspection
Agusta Bell AB212	EASA AD IT-2000-382	Main Rotor Mast – Inspection
Agusta Bell AB212	EASA AD IT-2001-206	Rotor Flight Control Actuator Pin – Inspection
Agusta Bell AB212	EASA AD IT-2001-275	Tail Rotor Counterweight Bellcrank Retention Nut – Inspection
Agusta Bell AB212	EASA AD IT-2001-485	Main Rotor Drive – Inspection
Agusta Bell AB212	EASA AD IT-2004-022	Main Hydraulic Servo Actuator – Inspection
Agusta Bell AB212	EASA AD IT-2005-139	Tail Rotor Blades – Inspection
Airbus Helicopters AS350 Series	DCA/AS350/130	HETS STC 11/21E/34 – Removal from Service
Airbus Helicopters AS350 Series	DCA/AS350/131	Dual Front Seat Modification MB 25.20.05 - Inspection
Airbus Helicopters AS350 Series	DCA/AS350/61A	Cancelled – DGAC AD 2001-557-086R3 refers
Airbus Helicopters AS350 Series	DCA/AS350/70	Cancelled – EASA AD 2019-0228 refers
Airbus Helicopters AS350 Series	DGAC AD 2001-557-086R3	Starflex Star – Inspection
Airbus Helicopters AS350 Series	EASA AD 2011-0164R3	Tail Rotor Control Stop Screws – Inspection
Airbus Helicopters AS350 Series	EASA AD 2014-0076R2	Rear Structure Junction Frame Reinforcement Angles – Inspection
Airbus Helicopters AS350 Series	EASA AD 2017-0020R1	Tail Rotor Pitch Rod – Inspection
Airbus Helicopters AS350 Series	EASA AD 2017-0089R1	Main Rotor Mast Upper Bearing - Inspection
Airbus Helicopters AS350 Series	EASA AD 2017-0114	Cancelled - EASA AD 2020-0186 refers
Airbus Helicopters AS350 Series	EASA AD 2018-0287	Cancelled – EASA AD 2019-0060 refers
Airbus Helicopters AS350 Series	EASA AD 2019-0060	Tail Rotor Gearbox Actuating Rod – Inspection
Airbus Helicopters AS350 Series	EASA AD 2019-0184	Main Rotor Servo Actuators – Inspection
Airbus Helicopters AS350 Series	EASA AD 2019-0225-E	MGB Drive Shaft / Engine Coupling – Inspection
Airbus Helicopters AS350 Series	EASA AD 2019-0228	Electric Hoist Installation – Inspection
Airbus Helicopters AS350 Series	EASA AD 2019-0280	Spherical Bearing – Inspection
Airbus Helicopters AS350 Series	EASA AD 2020-0064	Emergency Flotation System – Inspection
Airbus Helicopters AS350 Series	EASA AD 2020-0175	Sliding Doors – Inspection
Airbus Helicopters AS350 Series	EASA AD 2020-0186	Cancelled – EASA AD 2021-0099 refers
Airbus Helicopters AS350 Series	EASA AD 2020-0217-E	Cancelled – EASA AD 2021-0023 refers
Airbus Helicopters AS350 Series	EASA AD 2020-0224R1	Tail Rotor Blades – Inspection
Airbus Helicopters AS350 Series	EASA AD 2021-0023	Cyclic Stick Grip UP / Down Hoist Control Switch – Modification
Airbus Helicopters AS350 Series	EASA AD 2021-0048	Main Rotor Pitch Rod Upper Links – Inspection
Airbus Helicopters AS350 Series	EASA AD 2021-0099	Vertical Fin – Inspection
Airbus Helicopters AS350 Series	FAA AD 2018-18-12	Cancelled – FAA AD 2019-16-16 refers

Airbus Helicopters AS350 Series	FAA AD 2018-25-17	Air Comm Corp Air Conditioning System – Inspection
Airbus Helicopters AS350 Series	FAA AD 2019-16-16	Inlet Barrier Filter – Inspection
Airbus Helicopters AS350 Series	FAA AD 2020-02-23	Emergency Float System STC SR00470LA - Inspection
Airbus Helicopters AS350 Series	TC AD CF-2019-01	Helicopter External Transport System (HETS) STC SH98-35
Airbus Helicopters AS355 Series	DCA/AS355/45	Cancelled – EASA AD 2019-0228 refers
Airbus Helicopters AS355 Series	DCA/AS355/99	HETS STC 11/21E/34 – Removal from Service
Airbus Helicopters AS355 Series	EASA AD 2011-0164R3	Tail Rotor Control Stop Screws – Inspection
Airbus Helicopters AS355 Series	EASA AD 2014-0076R2	Rear Structure Junction Frame Reinforcement Angles – Inspection
Airbus Helicopters AS355 Series	EASA AD 2017-0020R1	Tail Rotor Pitch Rod – Inspection
Airbus Helicopters AS355 Series	EASA AD 2017-0089R1	Main Rotor Mast Upper Bearing - Inspection
Airbus Helicopters AS355 Series	EASA AD 2017-0114	Cancelled - EASA AD 2020-0186 refers
Airbus Helicopters AS355 Series	EASA AD 2018-0287	Cancelled – EASA AD 2019-0060 refers
Airbus Helicopters AS355 Series	EASA AD 2019-0060	Tail Rotor Gearbox Actuating Rod – Inspection
Airbus Helicopters AS355 Series	EASA AD 2019-0184	Main Rotor Servo Actuators – Inspection
Airbus Helicopters AS355 Series	EASA AD 2019-0228	Electric Hoist Installation – Inspection
Airbus Helicopters AS355 Series	EASA AD 2020-0064	Emergency Flotation System – Inspection
Airbus Helicopters AS355 Series	EASA AD 2020-0175	Sliding Doors – Inspection
Airbus Helicopters AS355 Series	EASA AD 2020-0186	Cancelled – EASA AD 2021-0099 refers
Airbus Helicopters AS355 Series	EASA AD 2020-0217-E	Cancelled – EASA AD 2021-0023 refers
Airbus Helicopters AS355 Series	EASA AD 2020-0224R1	Tail Rotor Blades – Inspection
Airbus Helicopters AS355 Series	EASA AD 2020-0266	N2 Speed Avoidance Limitation – Placard and AFM Amendment
Airbus Helicopters AS355 Series	EASA AD 2021-0023	Cyclic Stick Grip UP / Down Hoist Control Switch – Modification
Airbus Helicopters AS355 Series	EASA AD 2021-0027R1	Collective Controls – Modification
Airbus Helicopters AS355 Series	EASA AD 2021-0048	Main Rotor Pitch Rod Upper Links – Inspection
Airbus Helicopters AS355 Series	EASA AD 2021-0099	Vertical Fin – Inspection
Airbus Helicopters AS355 Series	FAA AD 2020-02-23	Emergency Float System STC SR00645LA - Inspection
Airbus Helicopters AS355 Series	TC AD CF-2019-01	Helicopter External Transport System (HETS) STC SH98-35
Airbus Helicopters BO105 Series	EASA AD 2019-0024	Tension Torsion Straps - Storage Life Limit
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2015-0198	Cancelled – EASA AD 2019-030 refers
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2017-0238	Cancelled – EASA AD 2019-0208 refers
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2018-0163	Cancelled – EASA AD 2021-0116 refers
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2018-0283	Cancelled – EASA AD 2020-0257 refers
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0030	Engine Mount Bushings - Inspection
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0030	Cancelled – EASA AD 2019-0275 refers
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0198	Flight Controls Wiring Harness - Modification
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0208	Aircraft Management Computer – Software Modification
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0258	Tail Rotor Drive Titanium Bolts – Inspection

Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0275
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0305
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0313
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2020-0013
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2020-0064
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2020-0084
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2020-0246
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2020-0257
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0074
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0116
Airbus Helicopters Deutschland MBB-BK117 Series	FAA AD 2019-10-51
Airbus Helicopters EC 120 B	EASA AD 2015-0020
Airbus Helicopters EC 120 B	EASA AD 2018-0186
Airbus Helicopters EC 120 B	EASA AD 2019-0139
Airbus Helicopters EC 120 B	EASA AD 2020-0064
Airbus Helicopters EC 120 B	EASA AD 2020-0095
Airbus Helicopters EC 120 B	EASA AD 2020-0247
Airbus Helicopters EC 120 B	EASA AD 2021-0015
Airbus Helicopters EC120 B	EASA AD 2019-0139
Airbus Helicopters EC120 B	EASA AD 2019-0272R1
Airbus Helicopters EC120 B	EASA AD 2021-0046
Airbus Helicopters EC120 B	EASA AD 2021-0069
Airbus Helicopters EC120 B	EASA AD 2021-0079
Airbus Helicopters EC130 Series	EASA AD 2015-0020
Airbus Helicopters EC130 Series	EASA AD 2017-0089R1
Airbus Helicopters EC130 Series	EASA AD 2019-0001
Airbus Helicopters EC130 Series	EASA AD 2019-0001
Airbus Helicopters EC130 Series	EASA AD 2019-0184
Airbus Helicopters EC130 Series	EASA AD 2019-0225-E
Airbus Helicopters EC130 Series	EASA AD 2020-0064
Airbus Helicopters EC130 Series	EASA AD 2020-0069
Airbus Helicopters EC130 Series	EASA AD 2020-0095
Airbus Helicopters EC130 Series	EASA AD 2020-0187
Airbus Helicopters EC130 Series	EASA AD 2021-0048
Airbus Helicopters EC130 Series	FAA AD 2018-25-17
Airbus Helicopters EC135 Series	EASA AD 2017-0199
Airbus Helicopters EC135 Series	EASA AD 2018-0168R1

Engine Mount Bushings – Inspection
Cabin Wiring Harness – Inspection
Tail Rotor Actuator – Inspection
Hand Held Fire Extinguishers – Inspection
Emergency Flotation System – Inspection
Collective Lever Switch Unit – Inspection
Lateral Control Rod Wiring – Inspection
Main Rotor Actuator – Inspection
Collective Bellcrank – Inspection
Co-pilot Collective Lever Wire Harness - Inspection
FAA STC SR00592DE – Inspection
Cancelled – EASA AD 2020-0095 refers
Cancelled - EASA AD 2019-0139 refers
Main Rotor Hub Scissors Attach Bolts - Inspection
Emergency Flotation System – Inspection
Sliding Door Star Support – Inspection
Skid Tubes – Inspection
Tailboom – Inspection
Cancelled - EASA AD 2021-0046 refers
Cancelled - EASA AD 2021-0069 refers
Main Rotor Hub Scissors Attach Bolts - Inspection
Tail Rotor Hub Body - Inspection
Tail Rotor Blades - Inspection
Cancelled – EASA AD 2020-0095 refers
Main Rotor Mast Upper Bearing - Inspection
Sliding Door Opening Mechanism – Inspection
Cancelled – EASA AD 2020-0069 refers
Main Rotor Servo Actuators – Inspection
MGB Drive Shaft / Engine Coupling – Inspection
Emergency Flotation System – Inspection
Sliding Door Opening Mechanism – Inspection
Sliding Door Star Support – Inspection
Tail Rotor Blades – Inspection
Main Rotor Pitch Rod Upper Links – Inspection
Air Comm Corp Air Conditioning System – Inspection
Cancelled – EASA AD 2021-0011 refers
Tail Rotor Blades – Life Limitation

Airbus Helicopters EC135 Series	EASA AD 2018-0284	Main Rotor Actuator – Inspection
Airbus Helicopters EC135 Series	EASA AD 2019-0087-E	Cancelled – EASA AD 2020-0105 refers
Airbus Helicopters EC135 Series	EASA AD 2019-0199	Tail Rotor Drive Ti-Bolt – Inspection
Airbus Helicopters EC135 Series	EASA AD 2020-0013	Hand Held Fire Extinguishers – Inspection
Airbus Helicopters EC135 Series	EASA AD 2020-0064	Emergency Flotation System – Inspection
Airbus Helicopters EC135 Series	EASA AD 2020-0099	Titanium Bolts – Inspection
Airbus Helicopters EC135 Series	EASA AD 2020-0102	Tail Rotor Control System – Inspection
Airbus Helicopters EC135 Series	EASA AD 2020-0105	Main Rotor Actuator Single-Axis Actuators – Inspection
Airbus Helicopters EC135 Series	EASA AD 2020-0282	Tail Rotor Blades – Inspection
Airbus Helicopters EC135 Series	EASA AD 2021-0011	Outboard Load System – Inspection and Modification
Airbus Helicopters EC135 Series	EASA AD 2021-0050	Tail Rotor Blades – Replacement
Airbus Helicopters EC135 Series	EASA AD 2021-0066	Outboard Load System Fittings – Inspection
Bell 205 Series	DCA/BELL205/7	Cancelled – DCA/BELL205/8 refers
Bell 205 Series	FAA AD 2020-12-10	Tail Rotor Blades – Inspection
Bell 205 Series	FAA AD 2020-16-10	Shoulder Harness Seat Belt – Inspection
Bell 205 Series	FAA AD 2020-19-08	Main Rotor Hub Tension-Torsion Straps – Inspection
Bell 206 & AB206 Series	EASA AD 2019-0178-E	Main Rotor Blades – Inspection
Bell 206 & AB206 series	TC AD CF-2016-13R1	Freewheel Lubrication System – Inspection
Bell 206 Series	FAA AD 2018-25-17	Air Comm Corp Air Conditioning System – Inspection
Bell 206 Series	TC AD CF-2019-01	Helicopter External Transport System (HETS) STC SH98-35
Bell 206 Series	TC AD CF-2019-34	Cancelled – CF-2020-15 refers
Bell 206 Series	TC AD CF-2020-15	Tail Rotor Drive Shaft Coupling Bolted Connections – Inspection
Bell 212 and 412 Series	FAA AD 2018-17-01	Cancelled – FAA AD 2019-09-02 refers
Bell 212 and 412 Series	FAA AD 2019-09-02	Oil and Fuel Check Valves – Inspection
Bell 212 Series	FAA AD 2011-12-08	Cancelled – FAA AD 2020-12-10 refers
Bell 212 Series	FAA AD 2020-12-10	Tail Rotor Blades – Inspection
Bell 212 Series	FAA AD 2020-16-10	Shoulder Harness Seat Belt – Inspection
Bell 212 Series	FAA AD 2020-19-08	Main Rotor Hub Tension-Torsion Straps – Inspection
Bell 407	DCA/BELL407/51	Cancelled – TC AD CF-2011-42R1 refers
Bell 407	FAA AD 2018-25-17	Air Comm Corp Air Conditioning System – Inspection
Bell 407	TC AD CF-2016-13R1	Freewheel Lubrication System – Inspection
Bell 407	TC AD CF-2019-01	Helicopter External Transport System (HETS) STC SH98-35
Bell 407	TC CF-2011-42R1	Longeron Structure - Inspection
Bell 412 Series	DCA/BELL412/15	Cancelled – FAA AD 2020-12-10 refers
Bell 412 Series	FAA AD 2015-04-04	Cancelled – FAA AD 2020-02-11 refers
Bell 412 Series	FAA AD 2020-02-11	Static Inverter – Inspection
Bell 412 Series	FAA AD 2020-12-10	Tail Rotor Blades – Inspection

Bell 412 Series	FAA AD 2020-16-10	Shoulder Harness Seat Belt – Inspection
Bell 412 Series	FAA AD 2020-22-07	MGB Support Case – AFM Amendment
Bell 429	TC AD CF-2018-35	Tail Rotor Gearbox – Inspection
Bell 429	TC AD CF-2019-03	Airworthiness Limitations
Bell 429	TC AD CF-2019-15	Tail Rotor System Limitations
Bell 429	TC AD CF-2019-16	Flight Control System - Yaw Trim
Bell 429	TC AD CF-2020-11	Control Bellcrank Bearing Staking - Inspection
Bell 429	TC AD CF-2020-18R1	Prohibit use of Map Mode on LH and RH Display Units - AFM Amendment
Bell 429	TC AD CF-2020-21R1	Emergency Flotation System Supply Hoses - Inspection
Bell 429	TC AD CF-2021-15	TRGB Support Assembly to Tailboom Attachment - Inspection
Bell 505	TC AD CF-2019-08	AFM Limitation for Fuels
Bell 505	TC AD CF-2019-28	Swashplate Assembly – Improperly Staked Bearings
Bell 505	TC AD CF-2019-35	Airframe Truss Clevis Lower Lug – Inspection
Bell 505	TC AD CF-2021-05R3	Pilot Collective Stick and Grip Assembly – Inspection
Guimbal Cabri G2	EASA AD 2016-0032	Cancelled – EASA AD 2019-0025 refers
Guimbal Cabri G2	EASA AD 2017-0039	Cancelled – EASA AD 2019-0187 refers
Guimbal Cabri G2	EASA AD 2019-0025	Airworthiness Limitations – Amendment
Guimbal Cabri G2	EASA AD 2019-0185	Main Rotor / Swashplate Guide Bellcrank Bushing - Replacement
Guimbal Cabri G2	EASA AD 2019-0186	Main Rotor / Non-rotating Scissor Link - Replacement
Guimbal Cabri G2	EASA AD 2019-0187 (Correction)	Engine Cooling Fan - Replacement
Guimbal Cabri G2	EASA AD 2020-0199 (Correction)	Main Rotor Scissors Fittings - Inspection
Helicopters - General	DCA/HELI/7A	Flight Control Cable End Assemblies - Proof Load
Helicopters - General	EASA AD 2020-0039	Hand Held Fire Extinguishers - Inspection
Kawasaki BK117 Series	JCAB AD TCD-9361-2019	Airworthiness Limitations – Revision
Kawasaki BK117 Series	JCAB AD TCD-9687-2020	Airworthiness Limitations – Revision
Leonardo A109 Series	DCA/A109/4	Cancelled – EASA AD 2020-0230 refers
Leonardo A109 Series	EASA AD 2014-0150	Cancelled – EASA AD 2019-0294 refers
Leonardo A109 Series	EASA AD 2015-0097	Cancelled – EASA AD 2020-0142 refers
Leonardo A109 Series	EASA AD 2016-0261R1	Fire Extinguisher Bottles – Inspection
Leonardo A109 Series	EASA AD 2019-0182	Enhanced MLG Strut Assembly – Inspection
Leonardo A109 Series	EASA AD 2019-0213	Hydraulic Pumps – Inspection
Leonardo A109 Series	EASA AD 2019-0294	Vertical Fin Vibration Absorber – Inspection
Leonardo A109 Series	EASA AD 2020-0065	Main Rotor Blades – Inspection
Leonardo A109 Series	EASA AD 2020-0142	Tail Rotor Drive Slider Assembly Pitch Control – Inspection
Leonardo A109 Series	EASA AD 2020-0230	Main Rotor Blade Tip Cap – Inspection

Leonardo A109 Series	EASA AD 2020-0256	Centre Fuselage Frame Assembly – Inspection
Leonardo A109 Series	EASA AD 2021-0031	Gearbox Assembly – Inspection
Leonardo A109 Series	EASA AD 2021-0065	Wiring Protection – Modification
Leonardo A109 Series	EASA AD 2021-0067	Rotor Brake Control Cable – Inspection
Leonardo A119 & AW119 Series	EASA AD 2018-0156	Cancelled – EASA AD 2020-0206 refers
Leonardo A119 & AW119 Series	EASA AD 2019-0057	Cancelled – EASA AD 2021-0096 refers
Leonardo A119 & AW119 Series	EASA AD 2019-0194-E	Cancelled – EASA AD 2020-0128 refers
Leonardo A119 & AW119 Series	EASA AD 2020-0128	Tail Rotor Duplex Bearing and Plug – Inspection
Leonardo A119 & AW119 Series	EASA AD 2020-0206	Gearbox Output Shaft – Inspection
Leonardo A119 & AW119 Series	EASA AD 2021-0040	Instrument Wiring – Inspection
Leonardo A119 & AW119 Series	EASA AD 2021-0096	Collective Stick Torque Tube Assembly – Inspection
Leonardo AW169 Helicopters	EASA AD 2018-0261-E (correction)	Cancelled – EASA AD 2019-0023 refers
Leonardo AW169 Helicopters	EASA AD 2019-0019	Tail Rotor Actuator Input Lever – Inspection
Leonardo AW169 Helicopters	EASA AD 2019-0022 (correction)	Tail Rotor Duplex Bearing – Inspection
Leonardo AW169 Helicopters	EASA AD 2019-0023	Cancelled – EASA AD 2019-0121 refers
Leonardo AW169 Helicopters	EASA AD 2019-0121R1	Cancelled – EASA AD 2019-0193 refers
Leonardo AW169 Helicopters	EASA AD 2019-0193	Cancelled – EASA AD 2020-0048 refers
Leonardo AW169 Helicopters	EASA AD 2019-0252	Yaw Pedal Assemblies – Modification
Leonardo AW169 Helicopters	EASA AD 2020-0013	Hand Held Fire Extinguishers – Inspection
Leonardo AW169 Helicopters	EASA AD 2020-0048	Cancelled – EASA AD 2020-0197 refers
Leonardo AW169 Helicopters	EASA AD 2020-0197	Tail Rotor Servo Actuator / Duplex Bearing – Inspection
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	DCA/HU369/34B	Main Rotor Transmission Cooling Installation - Inspection
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	DCA/HU369/97A	DG500 External Cargo Pod STC 11/21E/2 – Inspection
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2019-05-04	Main Rotor Blades - Inspection
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2020-11-07	Main Rotor Hub Lead-lag Bolt - Inspection
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2020-18-20	Main Rotor Blade Leading Edge Abrasion Strip - Inspection
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	TC AD CF-2019-01	Helicopter External Transport System (HETS) STC SH98-35
MD 600N Helicopters	FAA AD 2020-06-11	Main Rotor Blade Link Assembly – Inspection
MD 600N Helicopters	FAA AD 2020-11-07	Main Rotor Hub Lead-lag Bolt - Inspection
MD 600N Helicopters	FAA AD 2020-18-20	Main Rotor Blade Leading Edge Abrasion Strip - Inspection
Robinson R22 Series	DCA/R22/17A	Cancelled – FAA AD 88-26-01R2 refers
Robinson R22 Series	DCA/R22/18	Cancelled – FAA AD 88-26-01R2 refers
Robinson R22 Series	FAA AD 88-26-01R2	Main Rotor Spindle and Journals - Inspection
Robinson R44 Series	FAA AD 2019-12-18	Engine Air Induction Hose – Inspection
Robinson R44 Series	FAA AD 2019-12-18	Cancelled – FAA AD 2020-18-08 refers

Robinson R44 Series	FAA AD 2020-05-11	Agricultural Spray System STCs – Inspection
Robinson R44 Series	FAA AD 2020-08-10	Tail Rotor Blades – Inspection
Robinson R44 Series	FAA AD 2020-18-08	Engine Air Induction Hoses – Inspection
Robinson R66	FAA AD 2019-07-02	Oil Tank – Inspection
Robinson R66	FAA AD 2021-04-12	Tail Rotor Drive Shaft Assembly – Inspection
Sikorsky S-76 Series	DCA/S-76/1A	Airworthiness Directive Compliance at Initial Airworthiness Certificate Issue
Sikorsky S-76 Series	FAA AD 2001-22-14	Fire Extinguishing System
Sikorsky S-76 Series	FAA AD 2018-10-07	Cancelled – FAA AD 2019-19-12 refers
Sikorsky S-76 Series	FAA AD 2019-19-12	Engine Collective Position Transducer (CPT) – Inspection
Sikorsky S-76 Series	FAA AD 2020-15-17	Remote Data Acquisition Unit and Display Unit – Inspection
Sikorsky S-76 Series	FAA AD 85-07-03R1	Instrument Landing System
Sikorsky S-76 Series	FAA AD 88-05-01R1	Engine Support Cross Beam
Sikorsky S-76 Series	FAA AD 95-22-01	Fluorescent Lighting System
Sikorsky S-76 Series	FAA AD 96-15-03	Drive Shaft Assembly
Amateur Built	Amateur Built	
Dyn'Aero MCR Type Aircraft	DGAC AD F-2008-003	Front Landing Gear Leg (NLG) - Inspection
Dyn'Aero MCR Type Aircraft	DGAC AD F-2012-001	Horizontal Stabiliser - Inspection
Jodel D.11 Aircraft	DCA/ABUILT/2A	Aileron Pulley Mounting - Modification
Microlights	Microlights	
Airmaster AP306 & AP406 Propellers	DCA/MICRO/18	Airmaster Propellers - Removal from Service
Dyn'Aero MCR Type Aircraft	DCA/MICRO/4	Cancelled – DGAC AD F-2012-001 refers
Dyn'Aero MCR Type Aircraft	DGAC AD F-2012-001	Horizontal Stabiliser - Inspection
Jodel D.11 Aircraft	DCA/MICRO/20	Aileron Pulley Mounting - Modification
Revmaster Engines	DCA/MICRO/19	Crankshaft - Replacement and Propeller Attachment Flange - Inspection
Ex-military and Vintage Aircraft Factory Built – Not type certified	Ex-military and Vintage Aircraft Factory Built – Not type certified	
Ex-military and Vintage Factory Built Aircraft	UK MPD 2020-002	Cancelled – Refer Rolls-Royce Merlin Engines AD Schedule
Gliders	Gliders	
DG-100, DG-200, DG-300, DG-400, DG-500, DG-800, DG-808 and DG-1000 series gliders	EASA AD 2019-0237R1	Canopy Lock / Rear Locking Rods – Inspection
Grob Gliders	EASA AD 2020-0121	Cancelled – EASA AD 2020-0138 refers
Grob Gliders	EASA AD 2020-0138	Elevator Control Pushrod – Inspection
Schempp-Hirth Gliders	EASA AD 2017-0167-E	Cancelled – Refer to Glasflugel gliders AD schedule
Schempp-Hirth Gliders	EASA AD 2019-0079	Air Brake Control – Inspection
Schempp-Hirth Gliders	EASA AD 2020-0063	Flaperon Control – Inspection
Schempp-Hirth Gliders	EASA AD 2020-0233	Airbrake End Stops / Bushings – Inspection

Schempp-Hirth gliders	EASA AD 2020-0260	Elevator Connection – Inspection
Sportine Aviacija LAK-17 series	EASA AD 2005-0014	AFM and Maintenance Manual - Replacement
Sportine Aviacija LAK-17 series	EASA AD 2017-0167-E	Front Electric Sustainer/Battery Pack – Modification
SZD Gliders	EASA AD 2018-0081	Elevator Control System / Vertical Tail – Inspection
Balloons	Balloons	
Balloons	EASA AD 2019-0245	Schroeder Burners – Inspection
Balloons - Stratus Double Burners	EASA AD 2021-0042	Burner Assembly and Hanger – Inspection
Engines	Engines	
Austro E4 Series Engines	EASA AD 2011-0039	High Pressure Fuel Pump – Inspection and Replacement
Austro E4 Series Engines	EASA AD 2013-0213R1	Waste Gate Controller - Replacement
Austro E4 Series Engines	EASA AD 2017-0103R1	Timing Chain – Replacement / AFM – Amendment
Austro E4 Series Engines	EASA AD 2018-0125	Waste Gate Controller & Control Rod Circlip – Life Limit/Mod
Austro E4 Series Engines	EASA AD 2019-0041	Airworthiness Limitations - Amendment
Austro E4 Series Engines	EASA AD 2021-0055R1	Cancelled – EASA AD 2021-0094 refers
Austro E4 Series Engines	EASA AD 2021-0094	Oil Pump - Replacement
Continental 470 Series	DCA/CON/201	Exhaust Valves – Inspection
Continental 520 Series	FAA AD 2010-11-04	Hydraulic Lifters – Inspection
Continental 520 Series	FAA AD 2020-16-11	Cross-flow Cylinder Assemblies – Inspection
Continental 520 Series	FAA AD 77-05-04	Crankshaft – Inspection
Continental 550 Series	FAA AD 2020-16-11	Cross-flow Cylinder Assemblies – Inspection
Continental Motors	DCA/CON/176A	Cancelled - Refer to Continental Motors Publication M-O
Continental TAE 125-01 /-02 Series	DCA/THIE/3	Cancelled – DCA/THIE/26 refers
Continental TAE 125-01 /-02 Series	EASA AD 2020-0228 (Correction)	Turbocharger Hoses – Inspection
Continental TAE 125-01 /-02 Series	EASA AD 2021-0022	Main Bearing / Studs – Inspection
GE Aviation Czech (formerly Walter Engines) M601 Series	EASA AD 2016-0025-E (Correction)	Cancelled – EASA AD 2019-0061 refers
GE Aviation Czech (formerly Walter Engines) M601 Series	EASA AD 2017-0100	Cancelled – EASA AD 2019-0061 refers
GE Aviation Czech (formerly Walter Engines) M601 Series	EASA AD 2019-0061	Cancelled – EASA AD 2019-0143 refers
GE Aviation Czech (formerly Walter Engines) M601 Series	EASA AD 2019-0143	Power Turbine Disc – Inspection
GE Aviation Czech (formerly Walter Engines) M601 Series	EASA AD 2020-0201R2	Fuel Control Unit – Replacement
GE Aviation Czech (formerly Walter Engines) M601 Series	EASA AD 2021-0052	Propeller Shaft – Replacement

GE Aviation Czech (formerly Walter Engines) M601 Series	EASA AD 2021-0060	Airworthiness Limitations
Honeywell LTS101 & T53 Series	DCA/AL-T/28	Cancelled – DCA/AL-T/33 refers
Honeywell LTS101 & T53 Series	DCA/AL-T/6	Cancelled – DCA/AL-T/32 refers
Lycoming AEIO-320, IO-320 and LIO-320 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming AEIO-360, HIO-360, IO-360 and LIO-360 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming AEIO-360, HIO-360, IO-360 and LIO-360 Series	FAA AD 2020-25-12	Crankshaft Assemblies – Inspection
Lycoming AEIO-390 and IO-390 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming AEIO-540 and IO-540 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming AEIO-580 and IO-580 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming GO-480-G1A6 Engine	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming HO-360, LO-360 and O-360 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming HO-360, LO-360 and O-360 Series	FAA AD 2020-25-12	Crankshaft Assemblies – Inspection
Lycoming IGSO-540 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming IO-720 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming IVO-360-A1A Engine and VO-360 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming LTIO-540 and TIO-540 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming LTO-360 and TO-360 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming O-290 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming O-320 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming O-540 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming TIO-360 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming TVO-435 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming VO-435 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Lycoming VO-540 Series	DCA/LYC/224A	Lycoming Parallel Valve Cylinder and Head Assemblies – Replacement
Pratt & Whitney PT6 Series	TC AD CF-2003-16	Review of Critical Part Life Limits
Pratt & Whitney PT6 Series	TC AD CF-2015-01R2	Engine Torque Indication – Inspection
Pratt & Whitney PT6 Series	TC AD CF-2019-05	Fuel Control Unit Galvanic Corrosion – Inspection
Pratt & Whitney PT6 Series	TC AD CF-2019-30R1	Compressor Turbine Blades - Inspection
Pratt & Whitney PT6 Series	TC AD CF-87-17R1	Third Stage Stator Vane – Inspection
Pratt & Whitney PT6 Series	TC AD CF-88-01R1	Gas Generator Case – Inspection
Pratt & Whitney PW617F-E and PW617F1-E engines	TC AD CF-2010-02	Fuel Oil Heat Exchanger (FOHE) Fuel Filter Bypass Valve – Inspection
Rolls-Royce 250 Series	DCA/AL250/59	Fuel Nozzle Assembly Screen Filter – Inspection
Rolls-Royce 250 Series	DCA/AL250/60B	Engine Compressor Modules - Inspection
Rolls-Royce Merlin & Packard Merlin Engine Variants	UK MPD 2020-002R1	Camshaft Bracket Retaining Studs – Inspection

Rotax Engines	EASA AD 2018-0265R1 (Correction)	Exhaust Valves – Replacement
Rotax Engines	EASA AD 2019-0055-E (Correction)	Cancelled – EASA AD 2019-0253-E refers
Rotax Engines	EASA AD 2019-0253-E	Fuel Pump Assembly – Inspection
Rotax Engines	UK CAA MPD 2019-001-E	Exhaust Valves – Replacement
Rotax Engines	UK MPD 2019-004-E	Cancelled – UK MPD 2019-006-E refers
Rotax Engines	UK MPD 2019-006-E	Fuel Pump Assembly – Inspection
Safran Helicopter Engines Arriel 1 Series	EASA AD 2020-0151-E	Module 03 / Stage 2 High Pressure Turbine Disc – Replacement
Safran Helicopter Engines Arriel 2 Series	EASA AD 2019-0110	Torque Conformation Box - Inspection
Safran Helicopter Engines Arriel 2 Series	EASA AD 2019-0180	Fuel Filter Pre-blockage Pressure Switch - Inspection
Safran Helicopter Engines Arriel 2 Series	EASA AD 2020-0046	Digital Engine Control Unit – Inspection
Safran Helicopter Engines Arrius 1 Series	EASA AD 2019-0266-E	Module 02 / Gas Generator – Service Life
Safran Helicopter Engines Arrius 2 Series	DCA/TUR/24	Cancelled – EASA AD 2021-0088 refers
Safran Helicopter Engines Arrius 2 Series	EASA AD 2013-0082	Cancelled – EASA AD 2020-0033 refers
Safran Helicopter Engines Arrius 2 Series	EASA AD 2018-0044	Cancelled by EASA – Purpose fulfilled
Safran Helicopter Engines Arrius 2 Series	EASA AD 2020-0033	Hydro-Mechanical Metering Unit – Inspection
Safran Helicopter Engines Arrius 2 Series	EASA AD 2021-0088	Digital Engine Control Unit – Software Update
Solo 2350 Series Engines	FAA AD 2019-0029	Propeller Reduction Gear Excentric Axle Bearings – Inspection
Solo 2625 Series Engines	EASA AD 2020-0056	Engine Control Unit - Software Update
Superior Air Parts Engines	FAA AD 2009-02-03	Fuel Injection Servos – Inspection
Superior Air Parts Engines	FAA AD 2020-25-12	Crankshaft Assemblies – Inspection
Vedeneyev M-14, Ivchenko AI-14 & Housai HS-6 Series	DCA/VEDEN/1	Engine Life Limit – Maintenance Programme Review
Vedeneyev M-14, Ivchenko AI-14 & Housai HS-6 Series	UK CAA MPD 2019-002	Cancelled – DCA/VEDEN/1 refers

Propellers

Propellers

Hoffmann Propellers	EASA AD 2020-0226R1	Propeller Hub – Inspection
McCauley Propellers	FAA AD 2020-19-06	McCauley Governors – Inspection

Components & Equip**

Components & Equip**

Avionics Equipment	FAA AD 2019-12-09	Cancelled – FAA AD 2021-05-17 refers
Avionics Equipment	FAA AD 2020-16-08 (Correction)	Aspen Avionics Flight Displays – Inspection
Avionics Equipment	FAA AD 2020-18-51	Sandia Attitude Indicators – Inspection
Avionics Equipment	FAA AD 2021-05-17	Rockwell FDSA-6500 Flight Display System – Inspection
Avionics Equipment	EASA AD 2019-0004 (correction)	Thales GPS Receivers - Inspection
Avionics Equipment	FAA AD 2019-01-02	Aspen Avionics EFD500 and EFD1000 Displays – Inspection
Avionics Equipment	FAA AD 2019-12-09	Rockwell Collins FDSA-6500 System – Inspection

Avionics Equipment	FAA AD 2019-13-03	Trig Avionics, Avidyne & BendixKing/Honeywell Mode S Transponders – Inspection
Avionics Equipment	FAA AD 2020-10-05	Rockwell Collins Pro Line 4 & Pro Line 21 Flight Management Systems – Inspection
Avionics Equipment	FAA AD 2021-08-07	Rockwell Collins GPS-4000S – Inspection
Avionics Equipment	FAA AD 2021-08-15	Garmin GMN-00962 GTS Processor Units – Inspection
Carburetors & Injection Systems	DCA/MA/18A	Fuel Injection Servo RSA-10AD1 – Inspection
Carburetors & Injection Systems	DCA/MA/19B	Fuel Injection Servos RSA-5AB1, RSA-5AD1, RSA-10ED1, RSA-10ED2, RSA-10DB1 and RSA-10DB2 – Inspection
Role Equipment - Helicopters	DCA/EQUIP/1H	Cancelled – DCA/EQUIP/28A refers
Role Equipment - Helicopters	DCA/EQUIP/28A	Cable Suspended Cargo Hook Systems - Inspection
Role Equipment - Helicopters	EASA AD 2015-0226R5	Goodrich Hoists – Inspection
Role Equipment - Helicopters	TC AD CF-2014-26	Cancelled - TC AD CF-2019-01 refers
Seats and Harnesses	FAA AD 2021-07-13	Pacific Science Rotary Buckle Assemblies – Inspection

Notes:

* The AD Schedule often covers a complete series of types.

** This is not the AD Schedule title but more specific to the components affected.

*** AD Numbering - If the AD number is less than 10, a zero has been added before the number.

This is for sorting only and the AD should still be referred to as in the AD Schedule.

Eff Date

29-Oct-20
25-Feb-21
25-Feb-21
25-Feb-21
25-Feb-21
25-Feb-21
29-Apr-21
29-Apr-21
22-Jul-19
1-Sep-20
26-Sep-19
26-Sep-19
26-Sep-19
26-Sep-19
26-Sep-19
26-Sep-19
19-Dec-19
19-Dec-19
25-May-21
25-May-21
12-Nov-20
7-Dec-20
27-Feb-20
27-Feb-20
27-Feb-20
27-Feb-20
27-Feb-20
27-Feb-20
27-Feb-20
27-Feb-20
12-Nov-20
7-Dec-20
7-Dec-20
27-Aug-20

12-Nov-20
12-Nov-20
12-Apr-21
9-Mar-20
12-Nov-20
1-Oct-20

30-Jul-20
25-Jun-20
25-Jul-19
25-Jul-19

25-Jun-20
25-Jun-20
26-Nov-20
26-Nov-20
26-Nov-20
26-Nov-20
21-Nov-19
26-Nov-20
26-Nov-20
26-Nov-20
3-Feb-20
26-Nov-20
18-Apr-19
26-Sep-19
27-Dec-19
3-Feb-20
26-Nov-20
26-Nov-20
26-Nov-20

26-Nov-20
26-Nov-20
26-Nov-20
26-Nov-20
26-Nov-20
26-Nov-20

26-Nov-20
26-Nov-20
26-Nov-20
1-Oct-20
1-Oct-20
1-Oct-20
1-Oct-20
1-Oct-20
1-Oct-20
1-Oct-20
1-Oct-20
1-Oct-20
1-Oct-20
1-Oct-20
1-Oct-20
1-Oct-20
28-Feb-19
28-Feb-19
28-Feb-19
28-Feb-19
28-Feb-19
21-Mar-21
2-Feb-21
25-Jun-20
2-Feb-21
10-Jun-20
10-Jun-20
7-Feb-19
7-Feb-19
7-Feb-19
7-Feb-19
7-Feb-19
25-Apr-19
5-Sep-19
5-Sep-19
7-May-20
28-Feb-19

29-Apr-21
28-Mar-19
28-Jan-21
1-Mar-19
27-Sep-19
3-Nov-20
28-Jan-21

28-Jan-21
5-May-21
27-Jun-19
23-Apr-21
31-Jan-19
25-Jun-20
28-Dec-20
28-Dec-20
23-Apr-21
31-Jan-19
31-Jan-19
31-Jan-19
28-Dec-20
16-Feb-21
31-Jan-19
31-Jan-19
27-Feb-20
31-Jan-19
28-Dec-20
16-Feb-21
5-Jan-21
29-Apr-21
12-Feb-19
12-Feb-19
12-Feb-19
12-Feb-19
10-Sep-19
24-Oct-19
19-Dec-19

26-Mar-20
26-Mar-20
26-Mar-20
26-Mar-20
26-Mar-20
26-Mar-20
26-Mar-20
26-Mar-20
26-Mar-20
26-Mar-20
26-Mar-20
26-Mar-20
31-Jan-19
27-Feb-20
27-Jun-19
26-Sep-19
27-Jun-19
30-Apr-20
27-Aug-20
30-May-19
30-Jun-20
3-Sep-20
3-Apr-19
3-Apr-19
29-Aug-19
13-Sep-19
26-Sep-19
3-Dec-19
2-Apr-20
27-Aug-20
29-Apr-21
2-Feb-21
26-Nov-20
2-Feb-21
2-Mar-21
29-Apr-21
26-Sep-19

22-Jan-19
26-Sep-19
28-Feb-20
22-Jan-19
26-Sep-19
31-Jan-19
30-Apr-20
27-Aug-20
30-May-19
30-Jun-20
3-Sep-20
3-Apr-19
3-Apr-19
29-Aug-19
26-Sep-19
2-Apr-20
27-Aug-20
29-Apr-21
2-Feb-21
26-Nov-20
22-Dec-20
2-Feb-21
3-Feb-21
2-Mar-21
29-Apr-21
28-Feb-20
22-Jan-19
28-Feb-19
28-Feb-19
29-Aug-19
10-May-21
1-Dec-20
28-Feb-19
21-Nov-19
31-Aug-19
29-Aug-19
1-Nov-19

21-Nov-19
27-Dec-19
30-Jan-20
27-Feb-20
2-Apr-20
17-Apr-20
26-Nov-20
1-Dec-20
29-Mar-21
10-May-21
19-Sep-19
13-May-20
27-Jun-19
27-Jun-19
2-Apr-20
13-May-20
26-Nov-20
28-Jan-21
26-Feb-21
25-Mar-21
26-Feb-21
25-Mar-21
31-Mar-21
13-May-20
30-Jun-20
31-Jan-19
7-Apr-20
29-Aug-19
13-Sep-19
2-Apr-20
7-Apr-20
13-May-20
4-Sep-20
2-Mar-21
22-Jan-19
31-Jan-21
28-Jan-21

31-Jan-19
28-May-20
30-Aug-19
27-Feb-20
2-Apr-20
28-May-20
28-May-20
28-May-20
28-Jan-21
31-Jan-21
9-Mar-21
22-Mar-21
18-Apr-19
16-Jul-20
3-Sep-20
21-Oct-20
23-Jul-19
26-Sep-19
22-Jan-19
22-Jan-19
28-May-20
28-May-20
4-Jun-19
4-Jun-19
16-Jul-20
16-Jul-20
3-Sep-20
21-Oct-20
27-Jun-19
22-Jan-19
26-Sep-19
22-Jan-19
27-Jun-19
16-Jul-20
17-Mar-20
17-Mar-20
16-Jul-20

3-Sep-20
18-Nov-20
31-Jan-19
28-Feb-19
27-Apr-19
17-May-19
30-Apr-20
17-Dec-20

2-Sep-20
29-Apr-21
28-Mar-19
8-Aug-19
24-Oct-19
2-Apr-21
28-Feb-19
29-Aug-19
28-Feb-19
29-Aug-19
29-Aug-19
29-Aug-19

5-Oct-20

17-Dec-20
26-Mar-20
24-Oct-19
28-Jan-21
5-Nov-20
18-Dec-19
30-Jul-20
27-Feb-20
29-Aug-19
26-Sep-19
18-Dec-19
3-Apr-20
30-Jul-20
5-Nov-20

1-Dec-20
5-Feb-21
25-Mar-21
25-Mar-21
14-Oct-20
29-Apr-21


25-Jun-20
25-Jun-20
14-Oct-20
25-Feb-21
29-Apr-21
5-Feb-19



13-Feb-19
5-Feb-19

3-Jun-19
14-Aug-19
20-Mar-20
24-Oct-19
27-Feb-20
24-Sep-20
24-Sep-20
1-Oct-20
26-Mar-20
17-Apr-19
30-Jun-20
28-Oct-20
22-Jan-19
28-Apr-20
30-Jun-20
28-Oct-20
30-Apr-20
30-Apr-20
30-Apr-20
9-Jul-19
29-Aug-20

16-Apr-20
22-May-20
29-Aug-20
17-May-19
12-Apr-21
30-May-19
30-May-19
8-Nov-19
8-Nov-19
9-Sep-20
30-May-19
30-May-19
30-May-19
30-May-19


17-Dec-20
17-Dec-20
17-Dec-20


17-Dec-20
17-Dec-20
17-Dec-20
17-Dec-20
17-Dec-20


28-May-20

24-Sep-19

3-Jul-20
3-Jul-20
18-Apr-19
18-Apr-19
1-Apr-20
10-Nov-20

17-Dec-20

25-Jul-19

25-Jul-19

31-Jan-19

[Redacted]

24-Oct-19

12-Feb-21

[Redacted]

25-Jun-20

25-Jun-20

25-Jun-20

25-Jun-20

25-Jun-20

29-Apr-21

29-Apr-21

27-Aug-20

25-Jun-20

21-Sep-20

25-Jun-20

21-Sep-20

27-Jun-19

29-Oct-20

17-Dec-20

2-Feb-21

1-Apr-19

1-Apr-19

27-Jun-19

27-Jun-19

28-Jan-21

3-Mar-21

25-Mar-21

18-Apr-19

18-Apr-19

28-Feb-19

28-Feb-19

15-Jan-21

28-Feb-19

28-Feb-19

28-Feb-19

28-Feb-19

28-Feb-19

15-Jan-21

28-Feb-19

28-Feb-19

28-Feb-19

28-Feb-19

28-Feb-19

28-Feb-19

28-Feb-19

28-Feb-19

28-Feb-19

28-Feb-19

28-Feb-19

28-Feb-19

30-May-19

29-Oct-20

28-Feb-19

30-Jan-20

30-May-19

30-May-19

26-Nov-20

7-Mar-19

4-May-20

28-May-20

31-Jan-19

15-Oct-19

15-Oct-19

31-Jan-19

19-Oct-19

19-Oct-19

11-Jul-20

4-Jun-19

8-Aug-19

26-Mar-20

29-Oct-19

29-Apr-21

10-Mar-20

25-Jul-19

10-Mar-20

29-Apr-21

28-Feb-19

27-Mar-20

31-Jan-19

15-Jan-21

18-Apr-19

18-Apr-19

29-Apr-21

3-Nov-20

29-Apr-21

17-Aug-20

28-Sep-20

29-Apr-21

31-Jan-19

7-Feb-19

25-Jul-19

27-Aug-19

24-Jun-20

12-May-21

17-May-21

30-Jul-20

30-Jul-20

25-Jun-20

29-Oct-20

30-Jul-20

22-Jan-19

11-May-21