

List of NZ CAA ADs issued in the last 27 months as at Amendment Nr 21-12

AD Schedule*	AD	AD Title	Eff Date
Aeroplanes	Aeroplanes		
Aeroplanes General - Large	FAA AD 2021-23-12	Radio Altimeter Interference from 5G C-Band	23-Dec-21
Aeroplanes General - Small	DCA/GEN/6A	Flight Control Cable End Assemblies - Proof Load	29-Oct-20
Aeroplanes General - Small	FAA AD 2021-23-12	Radio Altimeter Interference from 5G C-Band	23-Dec-21
Aero Commander 100	FAA AD 68-23-03	Fuel Octane Placard - Inspection	24-Jun-21
Aero Commander 100	FAA AD 73-01-01	Exhaust Outlet Blockage - Inspection	24-Jun-21
Aerostar 600 & 601 Series	FAA AD 2002-24-07	Roto-Master and Rajay Scavenge Pumps – Inspection	25-Feb-21
Aerostar 600 & 601 Series	FAA AD 80-18-03	Fuel Pressure System – Fuel Gauge Markings and AFM Amendment	25-Feb-21
Aerostar 600 & 601 Series	FAA AD 87-21-01	Fuel Filler Openings – Inspection	25-Feb-21
Aerostar 600 & 601 Series	FAA AD 88-21-05	Exhaust Systems STC SA980NM – Inspection	25-Feb-21
Aerostar 600 & 601 Series	FAA AD 88-25-02	Engine Fluid Hoses – Inspection	25-Feb-21
Air Tractor AT-402 Series	FAA AD 2021-05-14	Flap Torque Tube Actuator Attachment Brackets – Inspection	29-Apr-21
Air Tractor AT-602 Series	FAA AD 2021-05-14	Flap Torque Tube Actuator Attachment Brackets – Inspection	29-Apr-21
Aviat A-1 (Husky) Series	FAA AD 2020-16-06	Forward Horizontal Stabiliser Support Assembly – Inspection	1-Sep-20
Aviat Aircraft Inc. (Pitts)	DCA/PITTS/1A	Airworthiness Directive Compliance at Initial Certificate of Airworthiness Issue	26-Sep-19
Aviat Aircraft Inc. (Pitts)	FAA AD 2006-12-07	ECi Cylinder Assemblies	26-Sep-19
Aviat Aircraft Inc. (Pitts)	FAA AD 2019-10-06	Fuel Distribution	26-Sep-19
Aviat Aircraft Inc. (Pitts)	FAA AD 90-20-05	Forward Seat Back	26-Sep-19
Aviat Aircraft Inc. (Pitts)	FAA AD 91-23-02	Carburettor Air Intake Box	26-Sep-19
Aviat Aircraft Inc. (Pitts)	FAA AD 96-09-06	Air Filter Assemblies	26-Sep-19
Beechcraft 35 & 36 Series (Bonanza)	FAA AD 2019-21-08	Cancelled – FAA AD 2019-23-10 refers	19-Dec-19
Beechcraft 35 & 36 Series (Bonanza)	FAA AD 2019-23-10	Aileron Flight Control Cables - Inspection	19-Dec-19
Beechcraft 76 Series (Duchess)	DCA/B76/10B	Cancelled – FAA AD 2021-08-06 refers	25-May-21
Beechcraft 76 Series (Duchess)	FAA AD 2021-08-06	MLG “A” Frame Assemblies - Inspection	25-May-21
Cessna 172 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection	12-Nov-20
Cessna 180 Series	FAA AD 2020-21-22	Tailcone and Horizontal Stabiliser – Inspection	7-Dec-20
Cessna 180 Series	FAA AD 62-17-04	Float Installation STC SA1-622 - Inspection	27-Feb-20
Cessna 180 Series	FAA AD 73-23-07	Defective Spar Attachment Fittings - Inspection	27-Feb-20
Cessna 180 Series	FAA AD 81-15-03	Engine Inlet Air Filter STC SA71GL - Inspection	27-Feb-20
Cessna 180 Series	FAA AD 83-17-06	Aileron Balance Weights STC SA1435WE - Inspection	27-Feb-20
Cessna 180 Series	FAA AD 86-24-07	Engine Controls Installation - Inspection	27-Feb-20
Cessna 180 Series	FAA AD 96-12-22	Full Flow Engine Oil Adaptor - Inspection	27-Feb-20
Cessna 180 Series	FAA AD 98-21-21R1	Electric Inflatable Door Seals STC SA4284WE - Inspection	27-Feb-20
Cessna 182 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection	12-Nov-20
Cessna 182 Series	FAA AD 2020-21-22	Tailcone and Horizontal Stabiliser – Inspection	7-Dec-20
Cessna 185 Series	FAA AD 2020-21-22	Tailcone and Horizontal Stabiliser – Inspection	7-Dec-20
Cessna 188 Series	DCA/CESS188/114B	Cancelled – Purpose Fulfilled	27-Aug-20

Cessna 206 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection	12-Nov-20
Cessna 207 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection	12-Nov-20
Cessna 208 Series	FAA AD 2021-04-10	Elevator Torque Tube – Inspection	12-Apr-21
Cessna 210 Series	FAA AD 2020-03-16	Carry-Thru Spar Lower Cap– Inspection	9-Mar-20
Cessna 210 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection	12-Nov-20
De Havilland DHC-2 (Beaver)	CASA AD/DHC-2/15 Amdt 1 (Correction)	Main Undercarriage Lower Forward Bolt Attachment – Inspection	1-Oct-20
De Havilland DHC-2 (Beaver)	DCA/C2/143	Cancelled – CASA AD/DHC-2/15 Amdt 1 refers	30-Jul-20
De Havilland DHC-2 (Beaver)	DCA/C2/160A	Cancelled – CF-2020-22 refers	25-Jun-20
De Havilland DHC-2 (Beaver)	TC AD CF-2020-22	Fuselage Struts - Inspection	25-Jun-20
De Havilland DHC-3 (Otter)	TC AD CF-2020-20	Wing Strut – Inspection	25-Jun-20
Diamond DA 40 Series	EASA AD 2012-0180	Airspeed Indicator Markings / Placard – Installation	26-Nov-20
Diamond DA 40 Series	EASA AD 2013-0018	Turbo Intercooler Installation – Inspection	26-Nov-20
Diamond DA 40 Series	EASA AD 2016-0190	Auto-pilot Bridle Cable Clamps – Inspection	26-Nov-20
Diamond DA 40 Series	EASA AD 2016-0203	V-band Clamps – Inspection	26-Nov-20
Diamond DA 40 Series	TC AD CF-2019-39	Fuel Tank Connection Hose – Inspection	21-Nov-19
Diamond DA 40 Series	TC AD CF-2021-24	Baggage Nets – Inspection	4-Aug-21
Diamond DA 42 Series	EASA AD 2012-0269	Air Intake / Induction Filter Icing – AFM Revision	26-Nov-20
Diamond DA 42 Series	EASA AD 2013-0224	Alternator Fail Indication – Modification	26-Nov-20
Diamond DA 42 Series	EASA AD 2016-0190	Auto-pilot Bridle Cable Clamps – Inspection	26-Nov-20
Diamond DA 42 Series	EASA AD 2017-0074	Cancelled – EASA AD 2020-0008 refers	3-Feb-20
Diamond DA 42 Series	EASA AD 2018-0214	Rudder Pedal Gust Lock Mounts – Removal	26-Nov-20
Diamond DA 42 Series	EASA AD 2019-0218	Fuel Tank Connection Hoses – Inspection	26-Sep-19
Diamond DA 42 Series	EASA AD 2019-0302	Rudder T-Yoke Axle Self-Locking Nut – Inspection	27-Dec-19
Diamond DA 42 Series	EASA AD 2020-0008	Flap Control System / Bellcrank Assembly – Inspection	3-Feb-20
Embraer EMB-500	Brazilian ANAC AD 2009-02-04	Flap System – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2009-09-01	Elevator Mass Balance Fasteners – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2009-10-01R3	ADS Sensors - Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2010-07-01	Drain Holes in Control Surfaces – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2010-08-01	Cabin Pressurization - Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2010-09-02	Harness W101 - Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2011-05-03	Angle of Attack (AOA) Sensor – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2014-07-03	Stabilizer Joint – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2016-04-02	Optimized Performance Analyser Software – AFM Revision	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2016-05-01	Passenger Seat Attachment – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2017-11-01	Aileron, Rudder and Elevator – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2020-05-03	Operation at Static Temperature Below -54 Deg Celsius – Inspection	26-Nov-20
Extra EA 300 Series	EASA AD 2006-0281	Upper Longeron at the Horizontal Stabiliser – Inspection	1-Oct-20
Extra EA 300 Series	EASA AD 2009-0160	Tail Spring Support – Inspection	1-Oct-20
Extra EA 300 Series	EASA AD D-1994-043R1	Upper Longeron Cutout Bridge – Inspection	1-Oct-20
Extra EA 300 Series	EASA AD D-2004-489	Bottom Fuselage Cover/Firewall Sealing – Inspection	1-Oct-20

Extra EA 300 Series	LBA AD 1992-199	Elevator Mass Balance Support – Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1993-081	Rudder Control Cable Compression Sleeve – Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1993-145/2	Wing Root Rib/Auxiliary Spar Attachment - Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1994-258	Canopy Latches - Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1995-125	Air Inlet Screen - Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1995-126	Engine Cowling and Firewall Fire Protection – Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1995-443	Rudder Pedal Safety Control Stop – Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1997-203/2	Front Seat Belt Safety Cover – Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 2002-408	Fuel Selector Valve – Inspection	1-Oct-20
G-164 Ag-Cat	FAA AD 62-08-07	Aileron Control Cable - Modification	29-Jul-21
G-164 Ag-Cat	FAA AD 63-01-01	Engine Mount Washers - Inspection	29-Jul-21
G-164 Ag-Cat	FAA AD 63-22-01	Spray Pump Fan Blades - Inspection	29-Jul-21
G-164 Ag-Cat	FAA AD 63-22-02	Throttle Control Pivot Bolt - Inspection	29-Jul-21
G-164 Ag-Cat	FAA AD 66-01-02	Propeller Cone and Spacer Sets - Inspection	29-Jul-21
G-164 Ag-Cat	FAA AD 67-29-04	Elevator Forward Pushrod - Inspection	29-Jul-21
G-164 Ag-Cat	FAA AD 72-02-02	Fuel Line Fitting - Inspection	29-Jul-21
G-164 Ag-Cat	FAA AD 77-13-04	Brake Warning - Placard	29-Jul-21
G-164 Ag-Cat	FAA AD 77-19-05	Flying Wire Terminals - Inspection	29-Jul-21
Grumman AA-1 and AA-5 Series	FAA AD 2021-14-12	Horizontal Stabiliser – Inspection	27-Jul-21
Jabiru Aeroplanes	CASA AD/JABIRU/3	Aileron Control Tube - Inspection	21-Mar-21
Jabiru Aeroplanes	CASA AD/JABIRU/4	Control Surface Hinges - Inspection	27-May-21
Mitsubishi MU-2B-26A/-60 Series	DCA/MU2/17C	FAA AD 75-16-20 Cancelled - FAA AD 2020-26-14 refers	2-Feb-21
Mitsubishi MU-2B-26A/-60 Series	FAA AD 2016-08-19	MLG Oleo Strut Attach Fittings – Inspection	25-Jun-20
Mitsubishi MU-2B-26A/-60 Series	FAA AD 2020-26-14	Propeller Pitch Control Lever – Inspection	2-Feb-21
Mitsubishi MU-2B-30 Series	DCA/MU2B-30/1A	Airworthiness Directive Compliance	10-Jun-20
Mitsubishi MU-2B-30 Series	JCAB AD TCD-4753B-2020	Pilot in Charge Training Requirements	10-Jun-20
Pacific Aerospace 750XL	DCA/750XL/38A	Flap Assembly Screw Jack – Inspection	5-Sep-19
Pacific Aerospace 750XL	DCA/750XL/39	Fuel Condition Lever – Inspection	5-Sep-19
Pacific Aerospace Cresco 08-600	DCA/CRESCO/22	Wing Main Spar Assembly - Inspection	7-May-20
Pacific Aerospace CT/4 Series Airtrainer	DCA/CT4/9	Wing Rear Spar – Inspection	29-Apr-21
Partenavia P68 Series	EASA AD 2021-0267	Rudder Hinges – Inspection	23-Dec-21
Pilatus PC-12 Series	EASA AD 2016-0083	Cancelled – EASA AD 2021-0005 (Correction) refers	28-Jan-21
Pilatus PC-12 Series	EASA AD 2019-0231	Flap Drive System – Inspection	27-Sep-19
Pilatus PC-12 Series	EASA AD 2020-0229	Fuel Transfer Injector – Inspection	3-Nov-20
Pilatus PC-12 Series	EASA AD 2021-0005	Cancelled - EASA AD 2021-0214 refers	1-Oct-21
Pilatus PC-12 Series	EASA AD 2021-0010	Inward Vent Valve – Inspection	28-Jan-21
Pilatus PC-12 Series	EASA AD 2021-0110 Cancelled	Cancelled by EASA on 3 November 2021	25-Nov-21
Pilatus PC-12 Series	EASA AD 2021-0214	Airworthiness Limitations - Amendment	1-Oct-21
Pilatus PC-12 Series	FAA AD 2021-24-01	Aerodynamic Fairing - Inspection	13-Jan-22
Pilatus PC-6 Series	DCA/PC6/38	Cancelled – EASA AD 2021-0098 refers	23-Apr-21
Pilatus PC-6 Series	EASA AD 2018-0285	Cancelled – EASA AD 2020-0120 refers	25-Jun-20

Pilatus PC-6 Series	EASA AD 2020-0120	Cancelled – EASA AD 2020-0278 refers	28-Dec-20
Pilatus PC-6 Series	EASA AD 2020-0278	Airworthiness Limitations	28-Dec-20
Pilatus PC-6 Series	EASA AD 2021-0098	Aileron, Elevator and Rudder Hinge Bolts – Inspection	23-Apr-21
Piper PA-28 Series	FAA AD 2020-24-05	Wing Spars – Inspection	28-Dec-20
Piper PA-28 Series	FAA AD 2020-26-16	Wing Spars – Inspection	16-Feb-21
Piper PA-31 Series	DCA/PA31/26C	Cancelled – FAA AD 82-27-13R2 refers	29-Jul-21
Piper PA-31 Series	DCA/PA31/54	Cancelled – FAA AD 82-27-13R2 refers	27-Feb-20
Piper PA-32 Series	FAA AD 2020-24-05	Wing Spars - Inspection	28-Dec-20
Piper PA-32 Series	FAA AD 2020-26-16	Wing Spars – Inspection	16-Feb-21
Piper PA-34 Series	FAA AD 2020-24-09	Rudder Flight Control Cables – Inspection	5-Jan-21
Piper PA-46 Series	FAA AD 2021-09-02	Stall Warning Heat Control System – Inspection	29-Apr-21
Robin DR400 Series	EASA AD 2019-0211	Thermostatic Oil Cooler Bypass Valve – Inspection	10-Sep-19
Robin DR400 Series	EASA AD 2019-0242	Disc Braking System – AFM Amendment	24-Oct-19
Robin DR400 Series	EASA AD 2019-0292	Stabilator – Inspection	19-Dec-19
Robin DR400 Series	EASA AD 2020-0001	Air Intake Duct – Inspection	30-Jan-20
Robin DR400 Series	EASA AD 2020-0147	Mixture Control Cable – Inspection	30-Jul-20
Rockwell Commander 112 & 114	FAA AD 73-14-04	Engine and Propeller Controls - Inspection	24-Jun-21
Rockwell Commander 112 & 114	FAA AD 73-14-06	Propeller Spinner Bulkhead - Inspection	24-Jun-21
Rockwell Commander 112 & 114	FAA AD 73-24-01	Aileron Hinges and Elevator Trim Tab Hinges - Inspection	24-Jun-21
Rockwell Commander 112 & 114	FAA AD 75-22-09	Ailerons - Inspection	24-Jun-21
Rockwell Commander 112 & 114	FAA AD 76-23-02	Cabin Vents and Air Ducts - Inspection	24-Jun-21
Rockwell Commander 112 & 114	FAA AD 77-01-08	Engine Oil Pressure Tube Assembly - Inspection	24-Jun-21
Socata TB 9, TB 10 and TB 20	EASA AD 2019-0274	Main Landing Gear Leg – Inspection	21-Nov-19
Supermarine Spitfire	UK CAA MPD 2020-004 (Correction)	Main Landing Gear Chassis Pintles – Inspection	29-Oct-20
Supermarine Spitfire	UK CAA MPD 2020-005	Main Landing Gear Support Eye Bolts – Inspection	1-Oct-20
Supermarine Spitfire	UK CAA MPD 2020-006	Main Landing Gear Pintle Mount Studs – Inspection	1-Oct-20
Vulcanair P68 Series	EASA AD 2020-0262	Stabilator Trim Control Cable – Inspection	17-Dec-20
Helicopters	Helicopters		
Agusta Bell AB212	EASA AD 2010-0272-E	Tail Rotor Blades – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD 2012-0001	Main Rotor Blades – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD 2013-0078	Main Rotor Hub Inboard Strap Fitting – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD 2013-0185	Tail Rotor Blades – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD 2013-0282-E	Rotor Drive Lubricating System – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD 2014-0113-E	Engine to Transmission Drive Shaft Line Nuts – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD 2014-0188R4	Emergency Flotation System – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD 2015-0121	External Cargo Hook System – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD 2015-0226R4	Hoist System – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD 2016-0166-E	Main Rotor Drive Spiral Bevel Gear – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD 2020-0013	Hand Held Fire Extinguishers – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD 2020-0062-E	Tail Rotor Hub/Blade Assembly - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD 2021-0126	Fuel/Oil Check Valves - Inspection	24-May-21
Agusta Bell AB212	EASA AD 2021-0165-E	Main Rotor Hub Strap Pins - Inspection	9-Jul-21

Agusta Bell AB212	EASA AD IT-1976-114	Main Rotor Drive - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1976-144	Stabiliser Bar Tube Assembly - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1976-145	Stabiliser Bar Tubes - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1976-191	Main Rotor Drive - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1976-233	Swashplate Support Assembly - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1976-234	Main Rotor Hydraulic Actuator - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1976-259	Main Rotor NAS Rotating Control Bolts - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1976-260	Tail Rotor Hanger Bearings - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1976-261	Fuel Booster Pumps - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1977-009	Ice and Rain Protection Screen Fitting - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1977-061	Tail Rotor Transmission to Engine Driveshaft - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1977-067	Rotor Brake Quill - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1977-070	Main Rotor Hub Fitting Assemblies - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1977-089	Rotor Brake Quill Bearings - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1977-090	Engine Mount Bearing Assembly - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1977-122	Tail Rotor Drive Transmission - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1977-130	Passenger Door Assemblies - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1977-166	Tail Rotor Driveshaft - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1977-172	Emergency Escape Release Door Handle Covers - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1977-198	Tail Rotor Pitch Change Horn - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1977-245	Hydraulic Actuators - Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-005	Main Rotor Blades – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-006	Main Rotor Blades Skin Cracks – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-094	Landing Gear Forward Cross Tube Assemblies – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-131	Main Rotor Blades – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-159	Emergency Float Kits – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-160	Float Landing Gear – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-161	Main Rotor Hub Inboard Fitting – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-163	Emergency Exits – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-166	Main Rotor Drive Centre Line Firewall – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-180	Passenger Door Emergency Escape Panels – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-192	External Cargo Hook Link Assembly – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-211	Skid Landing Gear – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-219	Flight Control Rods and Bellcranks – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1978-245	Main Rotor Drive Spiral Bevel Gear – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1979-062	Emergency Flotation Equipment – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1979-187	Main Rotor Blades – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1979-188	Main Rotor Blades Steel Grip Pad – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1980-036	Main Rotor Hub Assembly – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1980-252	Main Rotor Hub Strap Assemblies – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1980-253	Main Rotor Hub Strap Assemblies – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1981-055	Main Rotor Mast Bearing – Inspection	26-Mar-20

Agusta Bell AB212	EASA AD IT-1981-057	Main Rotor Swashplate Filter – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1981-107	Main Rotor Swashplate Support – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1981-224	Main Rotor Yokes – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1986-030	Main Rotor Swashplate Bearing – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1989-165	Main Rotor Transmission Internal Sump Oil Filter – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1989-272	Landing Gear Cross Tubes – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1991-074	Main Rotor Drag Brace Assemblies – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1993-079	Tail Rotor Driveshaft Hanger Bearing – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1993-116	Main Rotor Yokes – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1993-157	Main Rotor Pillow Blocks – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1994-261	Main Rotor Retention Strap – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1994-273	Main Transmission Lower Planetary Spider – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1997-195	Tail Rotor Blades – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1997-226	Tail Rotor Flapping Loads – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-1998-282	Tail Rotor Yoke Assembly – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-2000-382	Main Rotor Mast – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-2001-206	Rotor Flight Control Actuator Pin – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-2001-275	Tail Rotor Counterweight Bellcrank Retention Nut – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-2001-485	Main Rotor Drive – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-2004-022	Main Hydraulic Servo Actuator – Inspection	26-Mar-20
Agusta Bell AB212	EASA AD IT-2005-139	Tail Rotor Blades – Inspection	26-Mar-20
Airbus Helicopters AS350 Series	DCA/AS350/131	Dual Front Seat Modification MB 25.20.05 - Inspection	27-Feb-20
Airbus Helicopters AS350 Series	DCA/AS350/70	Cancelled – EASA AD 2019-0228 refers	26-Sep-19
Airbus Helicopters AS350 Series	EASA AD 2010-0006	Cancelled by EASA on 3 September 2021	3-Sep-21
Airbus Helicopters AS350 Series	EASA AD 2011-0164R3	Tail Rotor Control Stop Screws – Inspection	30-Apr-20
Airbus Helicopters AS350 Series	EASA AD 2013-0287	Cancelled – EASA AD 2021-0195 Refers	3-Sep-21
Airbus Helicopters AS350 Series	EASA AD 2014-0076R2	Rear Structure Junction Frame Reinforcement Angles – Inspection	27-Aug-20
Airbus Helicopters AS350 Series	EASA AD 2015-0094	Cancelled by EASA on 3 September 2021	3-Sep-21
Airbus Helicopters AS350 Series	EASA AD 2015-0132	Cancelled – EASA AD 2021-0194 Refers	3-Sep-21
Airbus Helicopters AS350 Series	EASA AD 2017-0032	Cancelled by EASA on 11 August 2021	11-Aug-21
Airbus Helicopters AS350 Series	EASA AD 2017-0089R1	Main Rotor Mast Upper Bearing - Inspection	30-Jun-20
Airbus Helicopters AS350 Series	EASA AD 2017-0114	Cancelled - EASA AD 2020-0186 refers	3-Sep-20
Airbus Helicopters AS350 Series	EASA AD 2019-0225-E	MGB Drive Shaft / Engine Coupling – Inspection	13-Sep-19
Airbus Helicopters AS350 Series	EASA AD 2019-0228	Electric Hoist Installation – Inspection	26-Sep-19
Airbus Helicopters AS350 Series	EASA AD 2019-0280	Spherical Bearing – Inspection	3-Dec-19
Airbus Helicopters AS350 Series	EASA AD 2020-0064	Emergency Flotation System – Inspection	2-Apr-20
Airbus Helicopters AS350 Series	EASA AD 2020-0175	Cancelled by EASA on 13 September 2021	30-Sep-21
Airbus Helicopters AS350 Series	EASA AD 2020-0186	Cancelled – EASA AD 2021-0099 refers	29-Apr-21
Airbus Helicopters AS350 Series	EASA AD 2020-0217-E	Cancelled – EASA AD 2021-0023 refers	2-Feb-21
Airbus Helicopters AS350 Series	EASA AD 2020-0224R1	Tail Rotor Blades – Inspection	26-Nov-20
Airbus Helicopters AS350 Series	EASA AD 2021-0023	Cyclic Stick Grip UP / Down Hoist Control Switch – Modification	2-Feb-21

Airbus Helicopters AS350 Series	EASA AD 2021-0048	Main Rotor Pitch Rod Upper Links – Inspection	2-Mar-21
Airbus Helicopters AS350 Series	EASA AD 2021-0099	Vertical Fin – Inspection	29-Apr-21
Airbus Helicopters AS350 Series	EASA AD 2021-0123-E	Tail Rotor Load Compensator – Inspection	11-May-21
Airbus Helicopters AS350 Series	EASA AD 2021-0168	Indicating / Recording Systems Control Unit – Inspection	30-Jul-21
Airbus Helicopters AS350 Series	EASA AD 2021-0194R1	Airworthiness Limitations - Amendment	28-Oct-21
Airbus Helicopters AS350 Series	EASA AD 2021-0195	Engine Digital ECU Emergency Procedure – AFM Amendment	3-Sep-21
Airbus Helicopters AS350 Series	EASA AD 2021-0282	Tail Rotor Head Pitch Change Unit Bearing Spacer - Inspection	31-Dec-21
Airbus Helicopters AS350 Series	FAA AD 2018-18-12	Cancelled – FAA AD 2019-16-16 refers	26-Sep-19
Airbus Helicopters AS350 Series	FAA AD 2019-16-16	Inlet Barrier Filter – Inspection	26-Sep-19
Airbus Helicopters AS350 Series	FAA AD 2020-02-23	Emergency Float System STC SR00470LA - Inspection	28-Feb-20
Airbus Helicopters AS355 Series	DCA/AS355/45	Cancelled – EASA AD 2019-0228 refers	26-Sep-19
Airbus Helicopters AS355 Series	EASA AD 2010-0006	Cancelled by EASA on 3 September 2021	3-Sep-21
Airbus Helicopters AS355 Series	EASA AD 2011-0164R3	Tail Rotor Control Stop Screws – Inspection	30-Apr-20
Airbus Helicopters AS355 Series	EASA AD 2013-0130	Cancelled – EASA AD 2021-0193 Refers	3-Sep-21
Airbus Helicopters AS355 Series	EASA AD 2014-0076R2	Rear Structure Junction Frame Reinforcement Angles – Inspection	27-Aug-20
Airbus Helicopters AS355 Series	EASA AD 2015-0094	Cancelled by EASA on 3 September 2021	3-Sep-21
Airbus Helicopters AS355 Series	EASA AD 2017-0032	Cancelled by EASA on 11 August 2021	11-Aug-21
Airbus Helicopters AS355 Series	EASA AD 2017-0089R1	Main Rotor Mast Upper Bearing - Inspection	30-Jun-20
Airbus Helicopters AS355 Series	EASA AD 2017-0114	Cancelled - EASA AD 2020-0186 refers	3-Sep-20
Airbus Helicopters AS355 Series	EASA AD 2019-0228	Electric Hoist Installation – Inspection	26-Sep-19
Airbus Helicopters AS355 Series	EASA AD 2020-0064	Emergency Flotation System – Inspection	2-Apr-20
Airbus Helicopters AS355 Series	EASA AD 2020-0175	Cancelled by EASA on 13 September 2021	30-Sep-21
Airbus Helicopters AS355 Series	EASA AD 2020-0186	Cancelled – EASA AD 2021-0099 refers	29-Apr-21
Airbus Helicopters AS355 Series	EASA AD 2020-0217-E	Cancelled – EASA AD 2021-0023 refers	2-Feb-21
Airbus Helicopters AS355 Series	EASA AD 2020-0224R1	Tail Rotor Blades – Inspection	26-Nov-20
Airbus Helicopters AS355 Series	EASA AD 2020-0266	N2 Speed Avoidance Limitation – Placard and AFM Amendment	22-Dec-20
Airbus Helicopters AS355 Series	EASA AD 2021-0023	Cyclic Stick Grip UP / Down Hoist Control Switch – Modification	2-Feb-21
Airbus Helicopters AS355 Series	EASA AD 2021-0027R1	Collective Controls – Modification	3-Feb-21
Airbus Helicopters AS355 Series	EASA AD 2021-0048	Main Rotor Pitch Rod Upper Links – Inspection	2-Mar-21
Airbus Helicopters AS355 Series	EASA AD 2021-0099	Vertical Fin – Inspection	29-Apr-21
Airbus Helicopters AS355 Series	EASA AD 2021-0193	Airworthiness Limitations	3-Sep-21
Airbus Helicopters AS355 Series	EASA AD 2021-0282	Tail Rotor Head Pitch Change Unit Bearing Spacer - Inspection	31-Dec-21
Airbus Helicopters AS355 Series	FAA AD 2020-02-23	Emergency Float System STC SR00645LA - Inspection	28-Feb-20
Airbus Helicopters BO105 Series	DCA/BO105/12	EASA AD 2010-0153 Cancelled – EASA AD 2021-0142 refers	1-Jul-21
Airbus Helicopters BO105 Series	DCA/BO105/1B	Airworthiness Directive Compliance at Initial Airworthiness Certificate Issue	1-Jul-21
Airbus Helicopters BO105 Series	EASA AD 2013-0015	Cancelled – EASA AD 2021-0142 refers	1-Jul-21
Airbus Helicopters BO105 Series	EASA AD 2015-0042	Cancelled – EASA AD 2021-0142 refers	1-Jul-21
Airbus Helicopters BO105 Series	EASA AD 2019-0024	Cancelled - EASA AD 2021-0142 refers	1-Jul-21
Airbus Helicopters BO105 Series	EASA AD 2021-0142	Airworthiness Limitations	1-Jul-21

Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2018-0163	Cancelled – EASA AD 2021-0116 refers	10-May-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2018-0283	Cancelled – EASA AD 2020-0257 refers	1-Dec-20
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0030	Cancelled – EASA AD 2019-0275 refers	21-Nov-19
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0258	Tail Rotor Drive Titanium Bolts – Inspection	1-Nov-19
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0275	Engine Mount Bushings – Inspection	21-Nov-19
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0305R1	Cabin Wiring Harness – Inspection	29-Jul-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0313	Tail Rotor Actuator – Inspection	30-Jan-20
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2020-0013	Hand Held Fire Extinguishers – Inspection	27-Feb-20
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2020-0064	Emergency Flotation System – Inspection	2-Apr-20
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2020-0084	Collective Lever Switch Unit – Inspection	17-Apr-20
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2020-0246	Lateral Control Rod Wiring – Inspection	26-Nov-20
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2020-0257	Main Rotor Actuator – Inspection	1-Dec-20
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0074	Collective Bellcrank – Inspection	29-Mar-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0116	Co-pilot Collective Lever Wire Harness - Inspection	10-May-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0122	Time Limits and Maintenance Checks – Airworthiness Limitations Amendment	27-May-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0160	Main Rotor Flex Control Unit Bearing Pin – Inspection	29-Jul-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0231	Emergency Flashlight – Replacement	29-Oct-21
Airbus Helicopters Deutschland MBB-BK117 Series	FAA AD 2019-10-51	FAA STC SR00592DE – Inspection	19-Sep-19
Airbus Helicopters EC120 B	DCA/EC120/21	EASA AD 2007-0211 cancelled on 23 September 2021	23-Sep-21
Airbus Helicopters EC120 B	EASA AD 2015-0020	Cancelled – EASA AD 2020-0095 refers	13-May-20
Airbus Helicopters EC120 B	EASA AD 2019-0139	Cancelled - EASA AD 2021-0046 refers	26-Feb-21
Airbus Helicopters EC120 B	EASA AD 2019-0272R1	Cancelled - EASA AD 2021-0069 refers	25-Mar-21
Airbus Helicopters EC120 B	EASA AD 2020-0064	Emergency Flotation System – Inspection	2-Apr-20
Airbus Helicopters EC120 B	EASA AD 2020-0095	Sliding Door Star Support – Inspection	13-May-20
Airbus Helicopters EC120 B	EASA AD 2020-0247	Skid Tubes – Inspection	26-Nov-20
Airbus Helicopters EC120 B	EASA AD 2021-0015	Tailboom – Inspection	28-Jan-21

Airbus Helicopters EC120 B	EASA AD 2021-0046	Main Rotor Hub Scissors Attach Bolts - Inspection	26-Feb-21
Airbus Helicopters EC120 B	EASA AD 2021-0069	Tail Rotor Hub Body - Inspection	25-Mar-21
Airbus Helicopters EC120 B	EASA AD 2021-0079	Tail Rotor Blades - Inspection	31-Mar-21
Airbus Helicopters EC120 B	EASA AD 2021-0168	Indicating / Recording Systems Control Unit – Inspection	30-Jul-21
Airbus Helicopters EC130 Series	EASA AD 2013-0287	Cancelled – EASA AD 2021-0195 Refers	3-Sep-21
Airbus Helicopters EC130 Series	EASA AD 2015-0020	Cancelled – EASA AD 2020-0095 refers	13-May-20
Airbus Helicopters EC130 Series	EASA AD 2015-0094	Cancelled by EASA on 3 September 2021	3-Sep-21
Airbus Helicopters EC130 Series	EASA AD 2015-0132	Cancelled – EASA AD 2021-0194 Refers	3-Sep-21
Airbus Helicopters EC130 Series	EASA AD 2017-0032	Cancelled by EASA on 11 August 2021	11-Aug-21
Airbus Helicopters EC130 Series	EASA AD 2017-0089R1	Main Rotor Mast Upper Bearing - Inspection	30-Jun-20
Airbus Helicopters EC130 Series	EASA AD 2018-0104R1	Tailboom Fenestron Junction Frame - Inspection	23-Dec-21
Airbus Helicopters EC130 Series	EASA AD 2019-0001	Cancelled – EASA AD 2020-0069 refers	7-Apr-20
Airbus Helicopters EC130 Series	EASA AD 2019-0225-E	MGB Drive Shaft / Engine Coupling – Inspection	13-Sep-19
Airbus Helicopters EC130 Series	EASA AD 2020-0064	Emergency Flotation System – Inspection	2-Apr-20
Airbus Helicopters EC130 Series	EASA AD 2020-0069	Sliding Door Opening Mechanism – Inspection	7-Apr-20
Airbus Helicopters EC130 Series	EASA AD 2020-0095	Sliding Door Star Support – Inspection	13-May-20
Airbus Helicopters EC130 Series	EASA AD 2020-0187	Tail Rotor Blades – Inspection	4-Sep-20
Airbus Helicopters EC130 Series	EASA AD 2021-0048	Main Rotor Pitch Rod Upper Links – Inspection	2-Mar-21
Airbus Helicopters EC130 Series	EASA AD 2021-0168	Indicating / Recording Systems Control Unit – Inspection	30-Jul-21
Airbus Helicopters EC130 Series	EASA AD 2021-0194R1	Airworthiness Limitations - Amendment	28-Oct-21
Airbus Helicopters EC130 Series	EASA AD 2021-0195	Engine Digital ECU Emergency Procedure – AFM Amendment	3-Sep-21
Airbus Helicopters EC130 Series	EASA AD 2021-0216	Engine to MGB Coupling Shaft – Inspection	7-Oct-21
Airbus Helicopters EC130 Series	EASA AD 2021-0235-E	Cancelled – EASA AD 2021-0283-E refers	21-Dec-21
Airbus Helicopters EC130 Series	EASA AD 2021-0283-E	Rear Transmission Bearing Support - Inspection	21-Dec-21
Airbus Helicopters EC135 Series	EASA AD 2017-0199	Cancelled – EASA AD 2021-0011 refers	31-Jan-21
Airbus Helicopters EC135 Series	EASA AD 2018-0168R1	Tail Rotor Blades – Life Limitation	28-Jan-21
Airbus Helicopters EC135 Series	EASA AD 2019-0087-E	Cancelled – EASA AD 2020-0105 refers	28-May-20
Airbus Helicopters EC135 Series	EASA AD 2020-0013	Hand Held Fire Extinguishers – Inspection	27-Feb-20
Airbus Helicopters EC135 Series	EASA AD 2020-0064	Emergency Flotation System – Inspection	2-Apr-20
Airbus Helicopters EC135 Series	EASA AD 2020-0099	Titanium Bolts – Inspection	28-May-20
Airbus Helicopters EC135 Series	EASA AD 2020-0102	Tail Rotor Control System – Inspection	28-May-20
Airbus Helicopters EC135 Series	EASA AD 2020-0105	Main Rotor Actuator Single-Axis Actuators – Inspection	28-May-20
Airbus Helicopters EC135 Series	EASA AD 2020-0282	Tail Rotor Blades – Inspection	28-Jan-21
Airbus Helicopters EC135 Series	EASA AD 2021-0011	Outboard Load System – Inspection and Modification	31-Jan-21
Airbus Helicopters EC135 Series	EASA AD 2021-0050	Tail Rotor Blades – Replacement	9-Mar-21
Airbus Helicopters EC135 Series	EASA AD 2021-0066	Outboard Load System Fittings – Inspection	22-Mar-21
Airbus Helicopters EC135 Series	EASA AD 2021-0149	Emergency Flashlight – Inspection	5-Jul-21
Bell 205 Series	FAA AD 2020-12-10	Tail Rotor Blades – Inspection	16-Jul-20
Bell 205 Series	FAA AD 2020-16-10	Shoulder Harness Seat Belt – Inspection	3-Sep-20
Bell 205 Series	FAA AD 2020-19-08	Main Rotor Hub Tension-Torsion Straps – Inspection	21-Oct-20
Bell 205 Series	FAA AD 2021-15-51	Outboard Main Rotor Hub Strap Pin - Inspection	8-Jul-21
Bell 206 & AB206 series	TC AD CF-2016-13R1	Freewheel Lubrication System – Inspection	26-Sep-19

Bell 206 Series	FAA AD 2021-24-15	Oil Cooler Blower – Inspection	18-Jan-22
Bell 206 Series	TC AD CF-2019-34	Cancelled – CF-2020-15 refers	28-May-20
Bell 206 Series	TC AD CF-2020-15	Tail Rotor Drive Shaft Coupling Bolted Connections – Inspection	28-May-20
Bell 212 Series	EASA AD 2014-0244	Cancelled – EASA AD 2021-0148 refers	5-Jul-21
Bell 212 Series	EASA AD 2021-0148	Emergency Flotation System (EFS) – AFM Supplement	5-Jul-21
Bell 212 Series	FAA AD 2011-12-08	Cancelled – FAA AD 2020-12-10 refers	16-Jul-20
Bell 212 Series	FAA AD 2020-12-10	Tail Rotor Blades – Inspection	16-Jul-20
Bell 212 Series	FAA AD 2020-16-10	Shoulder Harness Seat Belt – Inspection	3-Sep-20
Bell 212 Series	FAA AD 2020-19-08	Main Rotor Hub Tension-Torsion Straps – Inspection	21-Oct-20
Bell 212 Series	FAA AD 2021-15-51	Outboard Main Rotor Hub Strap Pin - Inspection	8-Jul-21
Bell 222 Series	EASA AD 2014-0244	Cancelled – EASA AD 2021-0148 refers	5-Jul-21
Bell 222 Series	EASA AD 2021-0148	Emergency Flotation System (EFS) – AFM Supplement	5-Jul-21
Bell 407	TC AD CF-2016-13R1	Freewheel Lubrication System – Inspection	26-Sep-19
Bell 407	TC AD CF-2021-34	Tailboom Lower Skin Cracking - Inspection	5-Nov-21
Bell 412 & 412EP Series	EASA AD 2014-0244	Cancelled – EASA AD 2021-0148 refers	5-Jul-21
Bell 412 & 412EP Series	EASA AD 2021-0148	Emergency Flotation System (EFS) – AFM Supplement	5-Jul-21
Bell 412 Series	DCA/BELL412/15	Cancelled – FAA AD 2020-12-10 refers	16-Jul-20
Bell 412 Series	FAA AD 2015-04-04	Cancelled – FAA AD 2020-02-11 refers	17-Mar-20
Bell 412 Series	FAA AD 2020-02-11	Static Inverter – Inspection	17-Mar-20
Bell 412 Series	FAA AD 2020-12-10	Tail Rotor Blades – Inspection	16-Jul-20
Bell 412 Series	FAA AD 2020-16-10	Shoulder Harness Seat Belt – Inspection	3-Sep-20
Bell 412 Series	FAA AD 2020-22-07	MGB Support Case – AFM Amendment	18-Nov-20
Bell 429	TC AD CF-2015-16R3	Tail Rotor Pitch Link Spherical Bearing – Inspection	27-May-21
Bell 429	TC AD CF-2016-11R3	Bellcrank Pivot Bearings – Inspection	30-Sep-21
Bell 429	TC AD CF-2020-11	Control Bellcrank Bearing Staking - Inspection	30-Apr-20
Bell 429	TC AD CF-2020-18R1	Prohibit use of Map Mode on LH and RH Display Units - AFM Amendment	17-Dec-20
Bell 429	TC AD CF-2020-21R1	Emergency Flotation System Supply Hoses - Inspection	2-Sep-20
Bell 429	TC AD CF-2021-15	TRGB Support Assembly to Tailboom Attachment - Inspection	29-Apr-21
Bell 505	FAA AD 2021-26-01	Stability Augmentation System and Autopilot – Inspection	28-Dec-21
Bell 505	TC AD CF-2019-35	Airframe Truss Clevis Lower Lug – Inspection	24-Oct-19
Bell 505	TC AD CF-2021-05R3	Pilot Collective Stick and Grip Assembly – Inspection	2-Apr-21
Bell UH-1 Series	FAA AD 2021-15-14	Tailboom Attach Structure - Inspection	30-Aug-21
Bell UH-1 Series	FAA AD 2021-15-52	Outboard Main Rotor Hub Strap Pin - Inspection	12-Jul-21
Brantly B-2 Series	FAA AD 2021-26-09	Tail Rotor Hub – Inspection	19-Jan-22
Guimbal Cabri G2	EASA AD 2020-0199 (Correction)	Cancelled – EASA AD 2021-0155 refers	29-Jul-21
Guimbal Cabri G2	EASA AD 2021-0155	Main Rotor Scissors Fittings - Inspection	29-Jul-21
Helicopters - General	DCA/HELI/7A	Flight Control Cable End Assemblies - Proof Load	17-Dec-20
Helicopters - General	EASA AD 2020-0039	Hand Held Fire Extinguishers - Inspection	26-Mar-20
Helicopters - General	FAA AD 2021-23-13	Radio Altimeter Interference from 5G C-Band	23-Dec-21
Kawasaki BK117 Series	DCA/BK117/21A	Cancelled by JCAB AD TCD-6982A-2021	13-Apr-21

Kawasaki BK117 Series	JCAB AD TCD-9361-2019	Airworthiness Limitations – Revision	24-Oct-19
Kawasaki BK117 Series	JCAB AD TCD-9687-2020	Airworthiness Limitations – Revision	28-Jan-21
Leonardo A109 Series	DCA/A109/4	Cancelled – EASA AD 2020-0230 refers	5-Nov-20
Leonardo A109 Series	EASA AD 2014-0150	Cancelled – EASA AD 2019-0294 refers	18-Dec-19
Leonardo A109 Series	EASA AD 2015-0097	Cancelled – EASA AD 2020-0142 refers	30-Jul-20
Leonardo A109 Series	EASA AD 2016-0261R1	Fire Extinguisher Bottles – Inspection	27-Feb-20
Leonardo A109 Series	EASA AD 2019-0213	Hydraulic Pumps – Inspection	26-Sep-19
Leonardo A109 Series	EASA AD 2019-0294	Vertical Fin Vibration Absorber – Inspection	18-Dec-19
Leonardo A109 Series	EASA AD 2020-0065	Main Rotor Blades – Inspection	3-Apr-20
Leonardo A109 Series	EASA AD 2020-0142	Tail Rotor Drive Slider Assembly Pitch Control – Inspection	30-Jul-20
Leonardo A109 Series	EASA AD 2020-0230	Main Rotor Blade Tip Cap – Inspection	5-Nov-20
Leonardo A109 Series	EASA AD 2020-0256	Centre Fuselage Frame Assembly – Inspection	1-Dec-20
Leonardo A109 Series	EASA AD 2021-0031	Gearbox Assembly – Inspection	5-Feb-21
Leonardo A109 Series	EASA AD 2021-0065	Wiring Protection – Modification	25-Mar-21
Leonardo A109 Series	EASA AD 2021-0067	Rotor Brake Control Cable – Inspection	25-Mar-21
Leonardo A109 Series	EASA AD 2021-0144	Tail Rotor Shaft Assembly – Inspection	1-Jul-21
Leonardo A109 Series	EASA AD 2021-0179	Hoist Support Assembly – Inspection	10-Aug-21
Leonardo A109 Series	EASA AD 2021-0255 (Correction)	Control Rods and Levers – Inspection	29-Nov-21
Leonardo A119 & AW119 Series	EASA AD 2018-0156	Cancelled – EASA AD 2020-0206 refers	14-Oct-20
Leonardo A119 & AW119 Series	EASA AD 2019-0057	Cancelled – EASA AD 2021-0096 refers	29-Apr-21
Leonardo A119 & AW119 Series	EASA AD 2019-0194-E	Cancelled – EASA AD 2020-0128 refers	25-Jun-20
Leonardo A119 & AW119 Series	EASA AD 2020-0128	Tail Rotor Duplex Bearing and Plug – Inspection	25-Jun-20
Leonardo A119 & AW119 Series	EASA AD 2020-0206	Gearbox Output Shaft – Inspection	14-Oct-20
Leonardo A119 & AW119 Series	EASA AD 2021-0040	Instrument Wiring – Inspection	25-Feb-21
Leonardo A119 & AW119 Series	EASA AD 2021-0096	Collective Stick Torque Tube Assembly – Inspection	29-Apr-21
Leonardo AW169 Helicopters	EASA AD 2019-0193	Cancelled – EASA AD 2020-0048 refers	20-Mar-20
Leonardo AW169 Helicopters	EASA AD 2019-0252	Cancelled – EASA AD 2021-0199 refers	30-Sep-21
Leonardo AW169 Helicopters	EASA AD 2020-0013	Hand Held Fire Extinguishers – Inspection	27-Feb-20
Leonardo AW169 Helicopters	EASA AD 2020-0048	Cancelled – EASA AD 2020-0197 refers	24-Sep-20
Leonardo AW169 Helicopters	EASA AD 2020-0197	Tail Rotor Servo Actuator / Duplex Bearing – Inspection	24-Sep-20
Leonardo AW169 Helicopters	EASA AD 2021-0199	Yaw Pedal Assemblies – Modification	30-Sep-21
Leonardo AW169 Helicopters	EASA AD 2021-0238	Fuel Tank Vent Lines – Inspection	25-Nov-21
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	DCA/HU369/34B	Main Rotor Transmission Cooling Installation - Inspection	1-Oct-20
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	DCA/HU369/97A	DG500 External Cargo Pod STC 11/21E/2 – Inspection	26-Mar-20
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2020-11-07	Main Rotor Hub Lead-lag Bolt - Inspection	30-Jun-20
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2020-18-20	Main Rotor Blade Leading Edge Abrasion Strip - Inspection	28-Oct-20
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2021-22-11	Pilot to Co-pilot Tail Rotor Torque Tube - Inspection	10-Jan-22

MD 600N Helicopters	FAA AD 2020-06-11	Main Rotor Blade Link Assembly – Inspection	28-Apr-20
MD 600N Helicopters	FAA AD 2020-11-07	Main Rotor Hub Lead-lag Bolt - Inspection	30-Jun-20
MD 600N Helicopters	FAA AD 2020-18-20	Main Rotor Blade Leading Edge Abrasion Strip - Inspection	28-Oct-20
MD 600N Helicopters	FAA AD 2021-22-11	Pilot to Co-pilot Tail Rotor Torque Tube - Inspection	10-Jan-22
Robinson R22 Series	DCA/R22/17A	Cancelled – FAA AD 88-26-01R2 refers	30-Apr-20
Robinson R22 Series	DCA/R22/18	Cancelled – FAA AD 88-26-01R2 refers	30-Apr-20
Robinson R22 Series	FAA AD 88-26-01R2	Main Rotor Spindle and Journals - Inspection	30-Apr-20
Robinson R44 Series	FAA AD 2019-12-18	Cancelled – FAA AD 2020-18-08 refers	29-Aug-20
Robinson R44 Series	FAA AD 2020-05-11	Agricultural Spray System STCs – Inspection	16-Apr-20
Robinson R44 Series	FAA AD 2020-08-10	Tail Rotor Blades – Inspection	22-May-20
Robinson R44 Series	FAA AD 2020-18-08	Engine Air Induction Hoses – Inspection	29-Aug-20
Robinson R44 Series	FAA AD 2021-19-08	Tail Rotor Blades – Inspection	22-Sep-21
Robinson R66	FAA AD 2021-04-12	Tail Rotor Drive Shaft Assembly – Inspection	12-Apr-21
Sikorsky S-76 Series	EASA AD 2014-0244	Cancelled – EASA AD 2021-0148 refers	5-Jul-21
Sikorsky S-76 Series	EASA AD 2021-0148	Emergency Flotation System (EFS) – AFM Supplement	5-Jul-21
Sikorsky S-76 Series	FAA AD 2018-10-07	Cancelled – FAA AD 2019-19-12 refers	8-Nov-19
Sikorsky S-76 Series	FAA AD 2019-19-12	Engine Collective Position Transducer (CPT) – Inspection	8-Nov-19
Sikorsky S-76 Series	FAA AD 2020-15-17	Remote Data Acquisition Unit and Display Unit – Inspection	9-Sep-20
Amateur Built	Amateur Built		
Amateur Built Aircraft	DCA/ABUILT/12	Engine Control Rod Eye Ends - Modification	25-Nov-21
Amateur Built Aircraft	DCA/ABUILT/13	Flight Control Cable End Assemblies - Proof Load	25-Nov-21
Dyn'Aero MCR Type Aircraft	DGAC AD F-2008-003	Front Landing Gear Leg (NLG) - Inspection	17-Dec-20
Dyn'Aero MCR Type Aircraft	DGAC AD F-2012-001	Horizontal Stabiliser - Inspection	17-Dec-20
Jodel D.11 Aircraft	DCA/ABUILT/2A	Aileron Pulley Mounting - Modification	17-Dec-20
Microlights	Microlights		
Airmaster AP306 & AP406 Propellers	DCA/MICRO/18	Airmaster Propellers - Removal from Service	17-Dec-20
Dyn'Aero MCR Type Aircraft	DCA/MICRO/4	Cancelled – DGAC AD F-2012-001 refers	17-Dec-20
Dyn'Aero MCR Type Aircraft	DGAC AD F-2012-001	Horizontal Stabiliser - Inspection	17-Dec-20
Jodel D.11 Aircraft	DCA/MICRO/20	Aileron Pulley Mounting - Modification	17-Dec-20
Revmaster Engines	DCA/MICRO/19	Crankshaft - Replacement and Propeller Attachment Flange - Inspection	17-Dec-20
Ex-military and Vintage Aircraft Factory Built – Not type certified	Ex-military and Vintage Aircraft Factory Built – Not type certified		
Ex-military and Vintage Aircraft Factory Built Aircraft	UK MPD 2020-002	Cancelled – Refer Rolls-Royce Merlin Engines AD Schedule	28-May-20
Gliders	Gliders		
DG-100, DG-200, DG-300, DG-400, DG-500, DG-800, DG-808 and DG-1000 series	EASA AD 2019-0237R1	Canopy Lock / Rear Locking Rods – Inspection	24-Sep-19
Glasflugel series	EASA AD 2021-0223-E	Elevator Control Rod – Inspection	8-Oct-21
Gliders - General	DCA/GLIDER/10	Cancelled – Refer EASA AD 2007-0001R1 in Solo 2625 Series AD Schedule	25-Nov-21

Grob series	EASA AD 2020-0121	Cancelled – EASA AD 2020-0138 refers	3-Jul-20
Grob series	EASA AD 2020-0138	Elevator Control Pushrod – Inspection	3-Jul-20
M&D JS-MD Series	EASA AD 2021-0070	Airbrake Blade No. 3 - Inspection	25-Nov-21
M&D JS-MD Series	EASA AD 2021-0243	Tail Wheel Cable - Inspection	25-Nov-21
Schempp-Hirth series	EASA AD 2020-0063	Flaperon Control – Inspection	1-Apr-20
Schempp-Hirth series	EASA AD 2020-0233	Airbrake End Stops / Bushings – Inspection	10-Nov-20
Schempp-Hirth series	EASA AD 2020-0260	Elevator Connection – Inspection	17-Dec-20
Schleicher series	DCA/SCH/138	Cancelled - EASA AD 2021-0230 refers	28-Oct-21
Schleicher series	EASA AD 2021-0187	Wing Root Ribs – Inspection	26-Aug-21
Schleicher series	EASA AD 2021-0230	Elevators – Inspection	28-Oct-21
Stemme S10 Series	EASA AD 2021-0278-E	Freewheel Clutch P/N 12AK – Inspection	17-Dec-21
Balloons	Balloons		
Balloons - Cylinder P/N CB2901, CB2902 & CB2903	UK CAA AD G-2021-0010-E	Cancelled - UK CAA AD G-2021-0014R1-E refers	4-Nov-21
Balloons - Cylinder P/N CB2901, CB2902 & CB2903	UK CAA AD G-2021-0014R1-E	Cylinder Quick Shut-off Valve Mounting Flange – Inspection	14-Dec-21
Balloons - Schroeder FB6 burners	EASA AD 2019-0245	Schroeder Burners – Inspection	24-Oct-19
Balloons - Stratus Double Burners P/N CB8504	EASA AD 2021-0042	Burner Assembly and Hanger – Inspection	12-Feb-21
Balloons - Various UK/EASA Types and Models	UK CAA AD G-2021-0012	Burner Assembly and Hanger – Inspection	3-Nov-21
Engines	Engines		
Austro E4 Series Engines	EASA AD 2011-0039	High Pressure Fuel Pump – Inspection and Replacement	25-Jun-20
Austro E4 Series Engines	EASA AD 2013-0213R1	Waste Gate Controller - Replacement	25-Jun-20
Austro E4 Series Engines	EASA AD 2017-0103R1	Timing Chain – Replacement / AFM – Amendment	25-Jun-20
Austro E4 Series Engines	EASA AD 2018-0125	Waste Gate Controller & Control Rod Circlip – Life Limit/Mod	25-Jun-20
Austro E4 Series Engines	EASA AD 2019-0041	Airworthiness Limitations - Amendment	25-Jun-20
Austro E4 Series Engines	EASA AD 2021-0055R1	Cancelled – EASA AD 2021-0094 refers	29-Apr-21
Austro E4 Series Engines	EASA AD 2021-0094	Oil Pump - Replacement	29-Apr-21
Austro E4 Series Engines	EASA AD 2021-0143-E	Cancelled – EASA AD 2021-0191-E Refers	20-Aug-21
Austro E4 Series Engines	EASA AD 2021-0191-E	Oil Pump – Replacement	20-Aug-21
Austro E4 Series Engines	EASA AD 2021-0203R1	Cancelled – EASA AD 2021-0274-E Refers	23-Dec-21
Austro E4 Series Engines	EASA AD 2021-0274-E	High Pressure Pump Driving Gear – Inspection	23-Dec-21
Continental 470 Series	DCA/CON/201	Exhaust Valves – Inspection	27-Aug-20
Continental 520 Series	FAA AD 2010-11-04	Hydraulic Lifters – Inspection	25-Jun-20
Continental 520 Series	FAA AD 2020-16-11	Cross-flow Cylinder Assemblies – Inspection	21-Sep-20
Continental 520 Series	FAA AD 77-05-04	Crankshaft – Inspection	25-Jun-20
Continental 520 Series	FAA AD 89-14-01	Crankshaft – Inspection	26-Aug-21
Continental 550 Series	FAA AD 2020-16-11	Cross-flow Cylinder Assemblies – Inspection	21-Sep-20
Continental TAE 125-01 /-02 Series	DCA/THIE/3	Cancelled – DCA/THIE/26 refers	29-Oct-20
Continental TAE 125-01 /-02 Series	EASA AD 2020-0228 (Correction)	Turbocharger Hoses – Inspection	17-Dec-20

Continental TAE 125-01 /-02 Series	EASA AD 2021-0022	Main Bearing / Studs – Inspection	2-Feb-21
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2020-0201R2	Fuel Control Unit – Replacement	28-Jan-21
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2021-0052	Cancelled – EASA AD 2021-0154 refers	29-Jul-21
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2021-0060	Airworthiness Limitations	25-Mar-21
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2021-0125-E	Critical Parts - Replacement	11-May-21
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2021-0154	Propeller Shaft - Replacement	29-Jul-21
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2021-0264	Critical Parts - Replacement	6-Dec-21
Lycoming AEIO-360, HIO-360, IO-360 and LIO-360 Series	FAA AD 2020-25-12	Crankshaft Assemblies – Inspection	15-Jan-21
Lycoming HO-360, LO-360 and O-360 Series	FAA AD 2020-25-12	Crankshaft Assemblies – Inspection	15-Jan-21
Pratt & Whitney PT6 Series	TC AD CF-2015-01R2	Engine Torque Indication – Inspection	29-Oct-20
Pratt & Whitney PT6 Series	TC AD CF-2019-30R1	Compressor Turbine Blades - Inspection	30-Jan-20
Pratt & Whitney PW617F-E and PW617F1-E engines	TC AD CF-2010-02	Fuel Oil Heat Exchanger (FOHE) Fuel Filter Bypass Valve – Inspection	26-Nov-20
Rolls-Royce 250 Series	DCA/AL250/60B	Engine Compressor Modules - Inspection	4-May-20
Rolls-Royce Merlin & Packard Merlin Engine Variants	UK MPD 2020-002R1	Camshaft Bracket Retaining Studs – Inspection	28-May-20
Rotax Engines	EASA AD 2019-0055-E (Correction)	Cancelled – EASA AD 2019-0253-E refers	15-Oct-19
Rotax Engines	EASA AD 2019-0253-E	Fuel Pump Assembly – Inspection	15-Oct-19
Rotax Engines	UK MPD 2019-004-E	Cancelled – UK MPD 2019-006-E refers	19-Oct-19
Rotax Engines	UK MPD 2019-006-E	Fuel Pump Assembly – Inspection	19-Oct-19
Safran Helicopter Engines Arriel 1 Series	EASA AD 2020-0151-E	Module 03 / Stage 2 High Pressure Turbine Disc – Replacement	11-Jul-20
Safran Helicopter Engines Arriel 2 Series	EASA AD 2020-0046	Digital Engine Control Unit – Inspection	26-Mar-20
Safran Helicopter Engines Arrius 1 Series	EASA AD 2019-0266-E	Module 02 / Gas Generator – Service Life	29-Oct-19
Safran Helicopter Engines Arrius 2 Series	DCA/TUR/24	Cancelled – EASA AD 2021-0088 refers	29-Apr-21
Safran Helicopter Engines Arrius 2 Series	EASA AD 2013-0082	Cancelled – EASA AD 2020-0033 refers	10-Mar-20
Safran Helicopter Engines Arrius 2 Series	EASA AD 2020-0033R1	Hydro-Mechanical Metering Unit (HMU) – Inspection	23-Dec-21
Safran Helicopter Engines Arrius 2 Series	EASA AD 2021-0088R1	Digital Engine Control Unit (DECU) – Software Update	2-Aug-21
Solo 2625 Series Engines	EASA AD 2020-0056	Engine Control Unit - Software Update	27-Mar-20
Superior Air Parts Engines	FAA AD 2020-25-12	Crankshaft Assemblies – Inspection	15-Jan-21

Propellers		Propellers	
Hartzell Propellers	FAA AD 1987-05-01	Blade Pilot Tube Bore Area - Inspection	27-May-21
Hartzell Propellers	FAA AD 2004-07-25	New Design Blades - Inspection	27-May-21
Hoffmann Propellers	EASA AD 2020-0226R1	Propeller Hub – Inspection	29-Apr-21
McCauley Propellers	FAA AD 2020-19-06	McCauley Governors – Inspection	3-Nov-20
Components & Equip**		Components & Equip**	
Aircraft Seats and Harnesses	DCA/SEAT/12A	Cancelled – FAA AD 2021-07-13 refers	11-May-21
Aircraft Seats and Harnesses	EASA AD 2021-0137	Safran 191 Series Pilot and Co-pilot Seats – Inspection	24-Jun-21
Aircraft Seats and Harnesses	FAA AD 2021-07-13	Pacific Science Rotary Buckle Assemblies – Inspection	11-May-21
Avionics Equipment	FAA AD 2019-12-09	Cancelled – FAA AD 2021-05-17 refers	29-Apr-21
Avionics Equipment	FAA AD 2020-16-08 (Correction)	Aspen Avionics Flight Displays – Inspection	17-Aug-20
Avionics Equipment	FAA AD 2020-18-51	Sandia Attitude Indicators – Inspection	28-Sep-20
Avionics Equipment	FAA AD 2021-05-17	Rockwell FDSA-6500 Flight Display System – Inspection	29-Apr-21
Avionics Equipment	FAA AD 2020-10-05	Rockwell Collins Pro Line 4 & Pro Line 21 Flight Management Systems – Inspection	24-Jun-20
Avionics Equipment	FAA AD 2021-08-07	Rockwell Collins GPS-4000S – Inspection	12-May-21
Avionics Equipment	FAA AD 2021-08-15	Garmin GMN-00962 GTS Processor Units – Inspection	17-May-21
Carburetors & Injection Systems	DCA/MA/18A	Fuel Injection Servo RSA-10AD1 – Inspection	30-Jul-20
Carburetors & Injection Systems	DCA/MA/19B	Fuel Injection Servos RSA-5AB1, RSA-5AD1, RSA-10ED1, RSA-10ED2, RSA-10DB1 and RSA-10DB2 – Inspection	30-Jul-20
Emergency Equipment	EASA AD 2021-0185R1	Hand Operated Fire Extinguishers – Inspection	26-Aug-21
Emergency Equipment	UK AD G-2021-0004	Life Raft Heliraft 18R MK3 – Inspection	5-Jul-21
Role Equipment - Helicopters	DCA/EQUIP/1H	Cancelled – DCA/EQUIP/28A refers	25-Jun-20
Role Equipment - Helicopters	DCA/EQUIP/27A	Electric Hoists Bonding – Inspection	23-Dec-21
Role Equipment - Helicopters	DCA/EQUIP/28A	Cable Suspended Cargo Hook Systems - Inspection	29-Oct-20
Role Equipment - Helicopters	EASA AD 2015-0226R6 (Correction)	Goodrich Hoists – Inspection	23-Dec-21

Notes:

* The AD Schedule often covers a complete series of types.

** This is not the AD Schedule title but more specific to the components affected.

*** AD Numbering - If the AD number is less than 10, a zero has been added before the number.

This is for sorting only and the AD should still be referred to as in the AD Schedule.