

**List of NZ CAA ADs issued in the last 27 months as at Amendment Nr 22-08**

<b>AD Schedule*</b>	<b>AD</b>	<b>AD Title</b>	<b>Eff Date</b>
<b>Aeroplanes</b>	<b>Aeroplanes</b>		
Aeroplanes General - Large	FAA AD 2021-23-12	Radio Altimeter Interference from 5G C-Band	23-Dec-21
Aeroplanes General - Small	DCA/GEN/6A	Flight Control Cable End Assemblies - Proof Load	29-Oct-20
Aeroplanes General - Small	FAA AD 2021-23-12	Radio Altimeter Interference from 5G C-Band	23-Dec-21
Aero Commander 100	FAA AD 68-23-03	Fuel Octane Placard - Inspection	24-Jun-21
Aero Commander 100	FAA AD 73-01-01	Exhaust Outlet Blockage - Inspection	24-Jun-21
Aerostar 600 & 601 Series	FAA AD 2002-24-07	Roto-Master and Rajay Scavenge Pumps – Inspection	25-Feb-21
Aerostar 600 & 601 Series	FAA AD 80-18-03	Fuel Pressure System – Fuel Gauge Markings and AFM Amendment	25-Feb-21
Aerostar 600 & 601 Series	FAA AD 87-21-01	Fuel Filler Openings – Inspection	25-Feb-21
Aerostar 600 & 601 Series	FAA AD 88-21-05	Exhaust Systems STC SA980NM – Inspection	25-Feb-21
Aerostar 600 & 601 Series	FAA AD 88-25-02	Engine Fluid Hoses – Inspection	25-Feb-21
Air Tractor AT-402 Series	FAA AD 2021-05-14	Flap Torque Tube Actuator Attachment Brackets – Inspection	29-Apr-21
Air Tractor AT-602 Series	FAA AD 2021-05-14	Flap Torque Tube Actuator Attachment Brackets – Inspection	29-Apr-21
Aviat A-1 (Husky) Series	FAA AD 2020-16-06	Forward Horizontal Stabiliser Support Assembly – Inspection	1-Sep-20
Beechcraft 300LW	FAA AD 2022-03-23	Garmin G1000 Integrated Avionics System – Inspection	22-Feb-22
Beechcraft 76 Series (Duchess)	DCA/B76/10B	Cancelled – FAA AD 2021-08-06 refers	25-May-21
Beechcraft 76 Series (Duchess)	FAA AD 2021-08-06	MLG “A” Frame Assemblies - Inspection	25-May-21
Cessna 120 Series	FAA AD 2022-08-03	Seat Belt Bracket – Inspection	17-May-22
Cessna 172 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection	12-Nov-20
Cessna 180 Series	FAA AD 2020-21-22	Tailcone and Horizontal Stabiliser – Inspection	7-Dec-20
Cessna 182 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection	12-Nov-20
Cessna 182 Series	FAA AD 2020-21-22	Tailcone and Horizontal Stabiliser – Inspection	7-Dec-20
Cessna 185 Series	FAA AD 2020-21-22	Tailcone and Horizontal Stabiliser – Inspection	7-Dec-20
Cessna 188 Series	DCA/CESS188/114B	Cancelled – Purpose Fulfilled	27-Aug-20
Cessna 206 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection	12-Nov-20
Cessna 207 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection	12-Nov-20
Cessna 208 Series	FAA AD 2021-04-10	Elevator Torque Tube – Inspection	12-Apr-21
Cessna 210 Series	FAA AD 2020-18-01	Forward Cabin Doorpost Bulkhead – Inspection	12-Nov-20
De Havilland DHC-2 (Beaver)	CASA AD/DHC-2/15 Amdt 1 (Correction)	Main Undercarriage Lower Forward Bolt Attachment – Inspection	1-Oct-20
De Havilland DHC-2 (Beaver)	DCA/C2/143	Cancelled – CASA AD/DHC-2/15 Amdt 1 refers	30-Jul-20
De Havilland DHC-2 (Beaver)	DCA/C2/160A	Cancelled – CF-2020-22 refers	25-Jun-20
De Havilland DHC-2 (Beaver)	TC AD CF-2020-22	Fuselage Struts - Inspection	25-Jun-20
De Havilland DHC-3 (Otter)	TC AD CF-2020-20	Wing Strut – Inspection	25-Jun-20
De Havilland DHC-3 (Otter)	TC AD CF-2022-41	Engine Mount Pickup Fittings – Inspection	31-Aug-22
Diamond DA 40 Series	EASA AD 2012-0180	Airspeed Indicator Markings / Placard – Installation	26-Nov-20
Diamond DA 40 Series	EASA AD 2013-0018	Turbo Intercooler Installation – Inspection	26-Nov-20

Diamond DA 40 Series	EASA AD 2016-0190	Auto-pilot Bridle Cable Clamps – Inspection	26-Nov-20
Diamond DA 40 Series	EASA AD 2016-0203	V-band Clamps – Inspection	26-Nov-20
Diamond DA 40 Series	TC AD CF-2021-24	Baggage Nets – Inspection	4-Aug-21
Diamond DA 42 Series	EASA AD 2012-0269	Air Intake / Induction Filter Icing – AFM Revision	26-Nov-20
Diamond DA 42 Series	EASA AD 2013-0224	Alternator Fail Indication – Modification	26-Nov-20
Diamond DA 42 Series	EASA AD 2016-0190	Auto-pilot Bridle Cable Clamps – Inspection	26-Nov-20
Diamond DA 42 Series	EASA AD 2018-0214	Rudder Pedal Gust Lock Mounts – Removal	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2009-02-04	Flap System – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2009-09-01	Elevator Mass Balance Fasteners – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2009-10-01R3	ADS Sensors - Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2010-07-01	Drain Holes in Control Surfaces – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2010-08-01	Cabin Pressurization - Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2010-09-02	Harness W101 - Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2011-05-03	Angle of Attack (AOA) Sensor – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2014-07-03	Stabilizer Joint – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2016-04-02	Optimized Performance Analyser Software – AFM Revision	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2016-05-01	Passenger Seat Attachment – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2017-11-01	Aileron, Rudder and Elevator – Inspection	26-Nov-20
Embraer EMB-500	Brazilian ANAC AD 2020-05-03	Operation at Static Temperature Below -54 Deg Celsius – Inspection	26-Nov-20
Extra EA 300 Series	EASA AD 2006-0281	Upper Longeron at the Horizontal Stabiliser – Inspection	1-Oct-20
Extra EA 300 Series	EASA AD 2009-0160	Tail Spring Support – Inspection	1-Oct-20
Extra EA 300 Series	EASA AD D-1994-043R1	Upper Longeron Cutout Bridge – Inspection	1-Oct-20
Extra EA 300 Series	EASA AD D-2004-489	Bottom Fuselage Cover/Firewall Sealing – Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1992-199	Elevator Mass Balance Support – Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1993-081	Rudder Control Cable Compression Sleeve – Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1993-145/2	Wing Root Rib/Auxiliary Spar Attachment - Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1994-258	Canopy Latches - Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1995-125	Air Inlet Screen - Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1995-126	Engine Cowling and Firewall Fire Protection – Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1995-443	Rudder Pedal Safety Control Stop – Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 1997-203/2	Front Seat Belt Safety Cover – Inspection	1-Oct-20
Extra EA 300 Series	LBA AD 2002-408	Fuel Selector Valve – Inspection	1-Oct-20
G-164 Ag-Cat	FAA AD 62-08-07	Aileron Control Cable - Modification	29-Jul-21
G-164 Ag-Cat	FAA AD 63-01-01	Engine Mount Washers - Inspection	29-Jul-21
G-164 Ag-Cat	FAA AD 63-22-01	Spray Pump Fan Blades - Inspection	29-Jul-21
G-164 Ag-Cat	FAA AD 63-22-02	Throttle Control Pivot Bolt - Inspection	29-Jul-21
G-164 Ag-Cat	FAA AD 66-01-02	Propeller Cone and Spacer Sets - Inspection	29-Jul-21
G-164 Ag-Cat	FAA AD 67-29-04	Elevator Forward Pushrod - Inspection	29-Jul-21
G-164 Ag-Cat	FAA AD 72-02-02	Fuel Line Fitting - Inspection	29-Jul-21

G-164 Ag-Cat	FAA AD 77-13-04	Brake Warning - Placard	29-Jul-21
G-164 Ag-Cat	FAA AD 77-19-05	Flying Wire Terminals - Inspection	29-Jul-21
Grumman AA-1 and AA-5 Series	FAA AD 2021-14-12	Horizontal Stabiliser – Inspection	27-Jul-21
Jabiru Aeroplanes	CASA AD/JABIRU/3	Aileron Control Tube - Inspection	21-Mar-21
Jabiru Aeroplanes	CASA AD/JABIRU/4	Control Surface Hinges - Inspection	27-May-21
Mitsubishi MU-2B-26A/-60 Series	DCA/MU2/17C	FAA AD 75-16-20 Cancelled - FAA AD 2020-26-14 refers	2-Feb-21
Mitsubishi MU-2B-26A/-60 Series	FAA AD 2016-08-19	MLG Oleo Strut Attach Fittings – Inspection	25-Jun-20
Mitsubishi MU-2B-26A/-60 Series	FAA AD 2020-26-14	Propeller Pitch Control Lever – Inspection	2-Feb-21
Mitsubishi MU-2B-30 Series	DCA/MU2B-30/1A	Airworthiness Directive Compliance	10-Jun-20
Mitsubishi MU-2B-30 Series	JCAB AD TCD-4753B-2020	Pilot in Charge Training Requirements	10-Jun-20
Pacific Aerospace Cresco 08-600	DCA/CRESCO/22	Wing Main Spar Assembly - Inspection	7-May-20
Pacific Aerospace CT/4 Series Airtrainer	DCA/CT4/9	Wing Rear Spar – Inspection	29-Apr-21
Partenavia P68 Series	EASA AD 2021-0267	Rudder Hinges – Inspection	23-Dec-21
Pilatus PC-12 Series	EASA AD 2016-0083	Cancelled – EASA AD 2021-0005 (Correction) refers	28-Jan-21
Pilatus PC-12 Series	EASA AD 2020-0229	Fuel Transfer Injector – Inspection	3-Nov-20
Pilatus PC-12 Series	EASA AD 2021-0005	Cancelled - EASA AD 2021-0214 refers	1-Oct-21
Pilatus PC-12 Series	EASA AD 2021-0010	Inward Vent Valve – Inspection	28-Jan-21
Pilatus PC-12 Series	EASA AD 2021-0110 Cancelled	Cancelled by EASA on 3 November 2021	25-Nov-21
Pilatus PC-12 Series	EASA AD 2021-0214	Cancelled – EASA AD 2022-0103 refers	30-Jun-22
Pilatus PC-12 Series	EASA AD 2022-0103	Airworthiness Limitations - Amendment	30-Jun-22
Pilatus PC-12 Series	EASA AD 2022-0158	NLG and MLG Actuators - Inspection	31-Aug-22
Pilatus PC-12 Series	FAA AD 2021-24-01	Aerodynamic Fairing - Inspection	13-Jan-22
Pilatus PC-6 Series	DCA/PC6/38	Cancelled – EASA AD 2021-0098 refers	23-Apr-21
Pilatus PC-6 Series	EASA AD 2018-0285	Cancelled – EASA AD 2020-0120 refers	25-Jun-20
Pilatus PC-6 Series	EASA AD 2020-0120	Cancelled – EASA AD 2020-0278 refers	28-Dec-20
Pilatus PC-6 Series	EASA AD 2020-0278	Airworthiness Limitations	28-Dec-20
Pilatus PC-6 Series	EASA AD 2021-0098	Aileron, Elevator and Rudder Hinge Bolts – Inspection	23-Apr-21
Piper PA-23 Series	DCA/PA-23/150	Cancelled – FAA AD 2021-25-11 refers	25-Jan-22
Piper PA-23 Series	DCA/PA-23/151	Cancelled – FAA AD 2021-25-11 refers	25-Jan-22
Piper PA-23 Series	DCA/PA-23/152	Cancelled – FAA AD 2021-25-11 refers	25-Jan-22
Piper PA-23 Series	FAA AD 2021-25-11	Horizontal Stabilator Structure – Inspection	25-Jan-22
Piper PA-28 Series	FAA AD 2020-24-05	Wing Spars – Inspection	28-Dec-20
Piper PA-28 Series	FAA AD 2020-26-16	Wing Spars – Inspection	16-Feb-21
Piper PA-31 Series	DCA/PA31/26C	Cancelled – FAA AD 82-27-13R2 refers	29-Jul-21
Piper PA-32 Series	FAA AD 2020-24-05	Wing Spars - Inspection	28-Dec-20
Piper PA-32 Series	FAA AD 2020-26-16	Wing Spars – Inspection	16-Feb-21
Piper PA-34 Series	FAA AD 2020-24-09	Rudder Flight Control Cables – Inspection	5-Jan-21
Piper PA-34 Series	FAA AD 2022-09-13	Nose Landing Gear – Inspection	31-May-22
Piper PA-46 Series	FAA AD 2021-09-02	Stall Warning Heat Control System – Inspection	29-Apr-21

Robin DR400 Series	EASA AD 2020-0147	Mixture Control Cable – Inspection	30-Jul-20
Robin DR400 Series	EASA AD 2022-0041	Flight Control Cables – Inspection	31-Mar-22
Robin DR400 Series	EASA AD 2022-0163-E	Flap Control Rods – Inspection	9-Aug-22
Rockwell Commander 112 & 114	FAA AD 73-14-04	Engine and Propeller Controls - Inspection	24-Jun-21
Rockwell Commander 112 & 114	FAA AD 73-14-06	Propeller Spinner Bulkhead - Inspection	24-Jun-21
Rockwell Commander 112 & 114	FAA AD 73-24-01	Aileron Hinges and Elevator Trim Tab Hinges - Inspection	24-Jun-21
Rockwell Commander 112 & 114	FAA AD 75-22-09	Ailerons - Inspection	24-Jun-21
Rockwell Commander 112 & 114	FAA AD 76-23-02	Cabin Vents and Air Ducts - Inspection	24-Jun-21
Rockwell Commander 112 & 114	FAA AD 77-01-08	Engine Oil Pressure Tube Assembly - Inspection	24-Jun-21
Supermarine Spitfire	UK CAA MPD 2020-004 (Correction)	Main Landing Gear Chassis Pintles – Inspection	29-Oct-20
Supermarine Spitfire	UK CAA MPD 2020-005	Main Landing Gear Support Eye Bolts – Inspection	1-Oct-20
Supermarine Spitfire	UK CAA MPD 2020-006	Main Landing Gear Pintle Mount Studs – Inspection	1-Oct-20
Tecnam Aircraft	EASA AD 2022-0131	Fuel Shut-off Valves - Placards Replacement and AFM Amendment	18-Jul-22
Tecnam Aircraft	EASA AD 2022-0132	Cancelled – EASA AD 2022-0167 refers	31-Aug-22
Tecnam Aircraft	EASA AD 2022-0132	Aileron Control Rod / Cover Panel Screws - Inspection	18-Jul-22
Tecnam Aircraft	EASA AD 2022-0167	Aileron Control Rod / Cover Panel Screws - Inspection	31-Aug-22
Vulcanair P68 Series	EASA AD 2020-0262	Stabilator Trim Control Cable – Inspection	17-Dec-20
<b>Helicopters</b>	<b>Helicopters</b>		
Agusta Bell AB212	EASA AD 2021-0126	Fuel/Oil Check Valves - Inspection	24-May-21
Agusta Bell AB212	EASA AD 2021-0165-E	Cancelled – EASA AD 2022-0052-E refers	25-Mar-22
Agusta Bell AB212	EASA AD 2022-0035	Cancelled - EASA AD 2022-0046 refers	24-Mar-22
Agusta Bell AB212	EASA AD 2022-0046	Tail Boom Attachment - Inspection	24-Mar-22
Agusta Bell AB212	EASA AD 2022-0052-E	Main Rotor Hub Strap Pins - Inspection	25-Mar-22
Agusta Bell AB212	EASA AD 2022-0084	Tail Boom / Fin Spar Cap - Inspection	26-May-22
Airbus Helicopters AS350 Series	DCA/AS350/122	EASA AD 2011-0072 Cancelled by EASA on 4 March 2022	4-Mar-22
Airbus Helicopters AS350 Series	EASA AD 2010-0006	Cancelled by EASA on 3 September 2021	3-Sep-21
Airbus Helicopters AS350 Series	EASA AD 2013-0287	Cancelled – EASA AD 2021-0195 Refers	3-Sep-21
Airbus Helicopters AS350 Series	EASA AD 2014-0076R3	Rear Structure Junction Frame Reinforcement Angles – Inspection	27-Jan-22
Airbus Helicopters AS350 Series	EASA AD 2014-0076R3	Cancelled – EASA AD 2022-0051 refers	5-Apr-22
Airbus Helicopters AS350 Series	EASA AD 2015-0094	Cancelled by EASA on 3 September 2021	3-Sep-21
Airbus Helicopters AS350 Series	EASA AD 2015-0132	Cancelled – EASA AD 2021-0194 Refers	3-Sep-21
Airbus Helicopters AS350 Series	EASA AD 2017-0032	Cancelled by EASA on 11 August 2021	11-Aug-21
Airbus Helicopters AS350 Series	EASA AD 2017-0089R1	Main Rotor Mast Upper Bearing - Inspection	30-Jun-20
Airbus Helicopters AS350 Series	EASA AD 2017-0114	Cancelled - EASA AD 2020-0186 refers	3-Sep-20
Airbus Helicopters AS350 Series	EASA AD 2018-0152	Cancelled – EASA AD 2022-0128 refers	28-Jul-22
Airbus Helicopters AS350 Series	EASA AD 2020-0175	Cancelled by EASA on 13 September 2021	30-Sep-21
Airbus Helicopters AS350 Series	EASA AD 2020-0186	Cancelled – EASA AD 2021-0099 refers	29-Apr-21
Airbus Helicopters AS350 Series	EASA AD 2020-0217-E	Cancelled – EASA AD 2021-0023 refers	2-Feb-21
Airbus Helicopters AS350 Series	EASA AD 2020-0224R1	Tail Rotor Blades – Inspection	26-Nov-20

Airbus Helicopters AS350 Series	EASA AD 2021-0023	Cyclic Stick Grip UP / Down Hoist Control Switch – Modification	2-Feb-21
Airbus Helicopters AS350 Series	EASA AD 2021-0048	Main Rotor Pitch Rod Upper Links – Inspection	2-Mar-21
Airbus Helicopters AS350 Series	EASA AD 2021-0099	Vertical Fin – Inspection	29-Apr-21
Airbus Helicopters AS350 Series	EASA AD 2021-0123-E	Tail Rotor Load Compensator – Inspection	11-May-21
Airbus Helicopters AS350 Series	EASA AD 2021-0168	Indicating / Recording Systems Control Unit – Inspection	30-Jul-21
Airbus Helicopters AS350 Series	EASA AD 2021-0194R1	Airworthiness Limitations - Amendment	28-Oct-21
Airbus Helicopters AS350 Series	EASA AD 2021-0195	Engine Digital ECU Emergency Procedure – AFM Amendment	3-Sep-21
Airbus Helicopters AS350 Series	EASA AD 2021-0282	Tail Rotor Head Pitch Change Unit Bearing Spacer - Inspection	31-Dec-21
Airbus Helicopters AS350 Series	EASA AD 2022-0051	(Correction) Rear Structure Junction Frame Reinforcement Angles - Inspection	30-Jun-22
Airbus Helicopters AS350 Series	EASA AD 2022-0077-E	Flight Control Flexball Cables - Replacement	2-May-22
Airbus Helicopters AS350 Series	EASA AD 2022-0128	Main Gearbox Bracket Bolts - Inspection	28-Jul-22
Airbus Helicopters AS355 Series	DCA/AS355/91	EASA AD 2011-0072 Cancelled by EASA on 4 March 2022	4-Mar-22
Airbus Helicopters AS355 Series	EASA AD 2010-0006	Cancelled by EASA on 3 September 2021	3-Sep-21
Airbus Helicopters AS355 Series	EASA AD 2013-0130	Cancelled – EASA AD 2021-0193 Refers	3-Sep-21
Airbus Helicopters AS355 Series	EASA AD 2014-0076R3	Rear Structure Junction Frame Reinforcement Angles – Inspection	27-Jan-22
Airbus Helicopters AS355 Series	EASA AD 2014-0076R3	Cancelled – EASA AD 2022-0051 refers	5-Apr-22
Airbus Helicopters AS355 Series	EASA AD 2015-0094	Cancelled by EASA on 3 September 2021	3-Sep-21
Airbus Helicopters AS355 Series	EASA AD 2017-0032	Cancelled by EASA on 11 August 2021	11-Aug-21
Airbus Helicopters AS355 Series	EASA AD 2017-0089R1	Main Rotor Mast Upper Bearing - Inspection	30-Jun-20
Airbus Helicopters AS355 Series	EASA AD 2017-0114	Cancelled - EASA AD 2020-0186 refers	3-Sep-20
Airbus Helicopters AS355 Series	EASA AD 2018-0152	Cancelled – EASA AD 2022-0128 refers	28-Jul-22
Airbus Helicopters AS355 Series	EASA AD 2020-0175	Cancelled by EASA on 13 September 2021	30-Sep-21
Airbus Helicopters AS355 Series	EASA AD 2020-0186	Cancelled – EASA AD 2021-0099 refers	29-Apr-21
Airbus Helicopters AS355 Series	EASA AD 2020-0217-E	Cancelled – EASA AD 2021-0023 refers	2-Feb-21
Airbus Helicopters AS355 Series	EASA AD 2020-0224R1	Tail Rotor Blades – Inspection	26-Nov-20
Airbus Helicopters AS355 Series	EASA AD 2020-0266	N2 Speed Avoidance Limitation – Placard and AFM Amendment	22-Dec-20
Airbus Helicopters AS355 Series	EASA AD 2021-0023	Cyclic Stick Grip UP / Down Hoist Control Switch – Modification	2-Feb-21
Airbus Helicopters AS355 Series	EASA AD 2021-0027R1	Collective Controls – Modification	3-Feb-21
Airbus Helicopters AS355 Series	EASA AD 2021-0048	Main Rotor Pitch Rod Upper Links – Inspection	2-Mar-21
Airbus Helicopters AS355 Series	EASA AD 2021-0099	Vertical Fin – Inspection	29-Apr-21
Airbus Helicopters AS355 Series	EASA AD 2021-0193	Airworthiness Limitations	3-Sep-21
Airbus Helicopters AS355 Series	EASA AD 2021-0282	Tail Rotor Head Pitch Change Unit Bearing Spacer - Inspection	31-Dec-21
Airbus Helicopters AS355 Series	EASA AD 2022-0051	(Correction) Rear Structure Junction Frame Reinforcement Angles - Inspection	30-Jun-22
Airbus Helicopters AS355 Series	EASA AD 2022-0069	Cancelled – EASA AD 2022-0180 refers	12-Sep-22
Airbus Helicopters AS355 Series	EASA AD 2022-0077-E	Flight Control Flexball Cables - Replacement	2-May-22
Airbus Helicopters AS355 Series	EASA AD 2022-0128	Main Gearbox Bracket Bolts - Inspection	28-Jul-22
Airbus Helicopters AS355 Series	EASA AD 2022-0180	Tail Rotor Drive Fan Assembly - Inspection	12-Sep-22

Airbus Helicopters BO105 Series	DCA/BO105/12	EASA AD 2010-0153 Cancelled – EASA AD 2021-0142 refers	1-Jul-21
Airbus Helicopters BO105 Series	DCA/BO105/1B	Airworthiness Directive Compliance at Initial Airworthiness Certificate Issue	1-Jul-21
Airbus Helicopters BO105 Series	EASA AD 2013-0015	Cancelled – EASA AD 2021-0142 refers	1-Jul-21
Airbus Helicopters BO105 Series	EASA AD 2015-0042	Cancelled – EASA AD 2021-0142 refers	1-Jul-21
Airbus Helicopters BO105 Series	EASA AD 2019-0024	Cancelled - EASA AD 2021-0142 refers	1-Jul-21
Airbus Helicopters BO105 Series	EASA AD 2021-0142	Airworthiness Limitations	1-Jul-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2018-0163	Cancelled – EASA AD 2021-0116 refers	10-May-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2018-0283	Cancelled – EASA AD 2020-0257 refers	1-Dec-20
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0305R1	Cabin Wiring Harness – Inspection	29-Jul-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2019-0313	Cancelled – EASA AD 2022-0086 refers	27-May-22
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2020-0246	Lateral Control Rod Wiring – Inspection	26-Nov-20
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2020-0257	Main Rotor Actuator – Inspection	1-Dec-20
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0074	Collective Bellcrank – Inspection	29-Mar-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0116	Co-pilot Collective Lever Wire Harness - Inspection	10-May-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0122	Time Limits and Maintenance Checks – Airworthiness Limitations Amendment	27-May-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0160	Main Rotor Flex Control Unit Bearing Pin – Inspection	29-Jul-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0231	Emergency Flashlight – Replacement	29-Oct-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0287 (Correction)	Seat Belt Restraint System – Inspection	24-Feb-22
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0289-E	Aircraft Flight Manual - Amendment	27-Dec-21
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2021-0290 (Correction)	Airworthiness Limitations - Amendment	27-Jan-22
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2022-0077-E	Flight Control Flexball Cables - Replacement	2-May-22
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2022-0086	Tail Rotor Actuator - Inspection	27-May-22
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2022-0097	Instrument Flight Rule Screens - Removal	8-Jun-22

Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2022-0143	Cancelled – EASA AD 2022-0168 refers	31-Aug-22
Airbus Helicopters Deutschland MBB-BK117 Series	EASA AD 2022-0168	Integrated Modular Avionics, Ethernet Network - Inspection	31-Aug-22
Airbus Helicopters EC120 B	DCA/EC120/21	EASA AD 2007-0211 cancelled on 23 September 2021	23-Sep-21
Airbus Helicopters EC120 B	EASA AD 2015-0020	Cancelled – EASA AD 2020-0095 refers	13-May-20
Airbus Helicopters EC120 B	EASA AD 2019-0139	Cancelled - EASA AD 2021-0046 refers	26-Feb-21
Airbus Helicopters EC120 B	EASA AD 2019-0272R1	Cancelled - EASA AD 2021-0069 refers	25-Mar-21
Airbus Helicopters EC120 B	EASA AD 2020-0095	Sliding Door Star Support – Inspection	13-May-20
Airbus Helicopters EC120 B	EASA AD 2020-0247	Skid Tubes – Inspection	26-Nov-20
Airbus Helicopters EC120 B	EASA AD 2021-0015	Tailboom – Inspection	28-Jan-21
Airbus Helicopters EC120 B	EASA AD 2021-0046	Main Rotor Hub Scissors Attach Bolts - Inspection	26-Feb-21
Airbus Helicopters EC120 B	EASA AD 2021-0069	Tail Rotor Hub Body - Inspection	25-Mar-21
Airbus Helicopters EC120 B	EASA AD 2021-0079	Tail Rotor Blades - Inspection	31-Mar-21
Airbus Helicopters EC120 B	EASA AD 2021-0168	Indicating / Recording Systems Control Unit – Inspection	30-Jul-21
Airbus Helicopters EC120 B	EASA AD 2022-0053	Skid Type Landing Gear – Inspection	6-Apr-22
Airbus Helicopters EC130 Series	EASA AD 2013-0287	Cancelled – EASA AD 2021-0195 Refers	3-Sep-21
Airbus Helicopters EC130 Series	EASA AD 2015-0020	Cancelled – EASA AD 2020-0095 refers	13-May-20
Airbus Helicopters EC130 Series	EASA AD 2015-0094	Cancelled by EASA on 3 September 2021	3-Sep-21
Airbus Helicopters EC130 Series	EASA AD 2015-0132	Cancelled – EASA AD 2021-0194 Refers	3-Sep-21
Airbus Helicopters EC130 Series	EASA AD 2017-0032	Cancelled by EASA on 11 August 2021	11-Aug-21
Airbus Helicopters EC130 Series	EASA AD 2017-0089R1	Main Rotor Mast Upper Bearing - Inspection	30-Jun-20
Airbus Helicopters EC130 Series	EASA AD 2018-0104R1	Tailboom Fenestron Junction Frame - Inspection	23-Dec-21
Airbus Helicopters EC130 Series	EASA AD 2018-0152	Cancelled – EASA AD 2022-0128 refers	28-Jul-22
Airbus Helicopters EC130 Series	EASA AD 2020-0095	Sliding Door Star Support – Inspection	13-May-20
Airbus Helicopters EC130 Series	EASA AD 2020-0187	Tail Rotor Blades – Inspection	4-Sep-20
Airbus Helicopters EC130 Series	EASA AD 2021-0048	Main Rotor Pitch Rod Upper Links – Inspection	2-Mar-21
Airbus Helicopters EC130 Series	EASA AD 2021-0168	Indicating / Recording Systems Control Unit – Inspection	30-Jul-21
Airbus Helicopters EC130 Series	EASA AD 2021-0194R1	Airworthiness Limitations - Amendment	28-Oct-21
Airbus Helicopters EC130 Series	EASA AD 2021-0195	Engine Digital ECU Emergency Procedure – AFM Amendment	3-Sep-21
Airbus Helicopters EC130 Series	EASA AD 2021-0216	Engine to MGB Coupling Shaft – Inspection	7-Oct-21
Airbus Helicopters EC130 Series	EASA AD 2021-0235-E	Cancelled – EASA AD 2021-0283-E refers	21-Dec-21
Airbus Helicopters EC130 Series	EASA AD 2021-0283R1 (Correction)	Rear Transmission Bearing Support - Inspection	31-Mar-22
Airbus Helicopters EC130 Series	EASA AD 2022-0053	Skid Type Landing Gear – Inspection	6-Apr-22
Airbus Helicopters EC130 Series	EASA AD 2022-0077-E	Flight Control Flexball Cables - Replacement	2-May-22
Airbus Helicopters EC130 Series	EASA AD 2022-0128	Main Gearbox Bracket Bolts - Inspection	28-Jul-22
Airbus Helicopters EC130 Series	EASA AD 2022-0150	Tail Rotor Blades - Inspection	4-Aug-22
Airbus Helicopters EC135 Series	EASA AD 2017-0199	Cancelled – EASA AD 2021-0011 refers	31-Jan-21
Airbus Helicopters EC135 Series	EASA AD 2017-0243	Cancelled – EASA AD 2022-0067 refers	28-Apr-22

Airbus Helicopters EC135 Series	EASA AD 2018-0168R1	Tail Rotor Blades – Life Limitation	28-Jan-21
Airbus Helicopters EC135 Series	EASA AD 2018-0168R1	Cancelled – EASA AD 2022-0067 refers	28-Apr-22
Airbus Helicopters EC135 Series	EASA AD 2018-0284	Cancelled – EASA AD 2022-0067 refers	28-Apr-22
Airbus Helicopters EC135 Series	EASA AD 2019-0087-E	Cancelled – EASA AD 2020-0105 refers	28-May-20
Airbus Helicopters EC135 Series	EASA AD 2020-0099	Titanium Bolts – Inspection	28-May-20
Airbus Helicopters EC135 Series	EASA AD 2020-0102	Tail Rotor Control System – Inspection	28-May-20
Airbus Helicopters EC135 Series	EASA AD 2020-0105	Main Rotor Actuator Single-Axis Actuators – Inspection	28-May-20
Airbus Helicopters EC135 Series	EASA AD 2020-0282	Tail Rotor Blades – Inspection	28-Jan-21
Airbus Helicopters EC135 Series	EASA AD 2021-0011	Outboard Load System – Inspection and Modification	31-Jan-21
Airbus Helicopters EC135 Series	EASA AD 2021-0050	Tail Rotor Blades – Replacement	9-Mar-21
Airbus Helicopters EC135 Series	EASA AD 2021-0066	Outboard Load System Fittings – Inspection	22-Mar-21
Airbus Helicopters EC135 Series	EASA AD 2021-0149	Emergency Flashlight – Inspection	5-Jul-21
Airbus Helicopters EC135 Series	EASA AD 2022-0023	Air Conditioning System – Inspection	24-Feb-22
Airbus Helicopters EC135 Series	EASA AD 2022-0067	Airworthiness Limitations – Amendment	28-Apr-22
Airbus Helicopters EC135 Series	EASA AD 2022-0077-E	Flight Control Flexball Cables - Replacement	2-May-22
Airbus Helicopters EC135 Series	EASA AD 2022-0097	Instrument Flight Rule Screens - Removal	8-Jun-22
Airbus Helicopters EC135 Series	EASA AD 2022-0143	Cancelled – EASA AD 2022-0168 refers	31-Aug-22
Airbus Helicopters EC135 Series	EASA AD 2022-0168	Integrated Modular Avionics, Ethernet Network - Inspection	31-Aug-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1979-102-002	Inspection of the TRGB tripod mount P/N 360	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1979-135-003	Spherical thrust bearings SEP P/N 704A.33.633.27 or 30 - Conformity i	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1979-190-004	Bolts for attachment of pitch change rods to swasplates main servo cor	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1979-211-005	Inspection of the magnetic plug on the Engine reduction gear and in-flig	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1979-253-006	Magnetic plug with warning system	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1980-164-007	Magnetic plug on engine oil system with warning installation - Evolution	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1981-066-010	Long sliders on pilot and co-pilots seats / Addition of a reinforcement fo	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1982-080-012	Horizontal stabilizers inspection of spar tube	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1982-136-014R1	Installation of a system for holding the horizontal stabilizer flanges	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1982-166-001	Unusable fuel	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1983-012-002	Fire extinguishing system pipes - Checking the condition and standardi	24-Feb-22



Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1983-013-015	Life time reduction for rotor drive element	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1983-038-016R1	Installation of system for holding the horizontal stabilizers flanges	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1983-077-003	Flight controls - Clearance between roll lever and 9 degrees frame cove	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1983-182-017	Flexible coupling - Reducing service life limitation	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1983-183-004	Flexible coupling - Reducing service life limitation	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1983-186-018	Main gear box modified to AMS 07-7149 (Relocation of drain plug)	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1983-200-019	Monitoring the rotating fairings and the tail rotor hub body	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1983-201-005	Monitoring the rotating fairings and the tail rotor hub body	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1983-203-020	Main rotor head fairing supports	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1984-019-021R2	Main rotor mast shaft	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1984-020-006R2	Main rotor mast shaft	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1984-151-023	Tail rotor drive shaft bearing block assembly N.1	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1984-152-008	Tail rotor drive shaft bearing block assembly N.1	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1985-013-009R1	Wire antenna installation for HF SSB radio	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1985-037-010	Locking of rear sidegate	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1985-085-012	Engine fire extinguisher system	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1985-155-024	Tail rotor gearbox - Oil filler cap	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1985-156-013	Tail rotor gear box - Oil filler cap	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1986-017-014	Fuel filter	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1986-033-025R1	Main rotor head - Roving sleeve beams	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1986-034-015R2	Main rotor head - Roving sleeve beams	24-Feb-22

Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1986-087-016R2	Interference with Flight Controls - Modifications	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1986-122-026	BLU Wire antenna	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1986-123-017R1	Main rotor shaft	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1986-170-019	Spherical thrust bearing/attach beams bolt - Reduction of life limit	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1986-175-018	Hydraulic generation system	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1986-176-027	Hydraulic generation system	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1987-008-028	Power plant interference of fuel flow control with fuel pipe on engine	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1987-009-020R1	Power plant incorporating TURBOMECA modification	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1987-166-021	Flight cycle calculation	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1987-167-022R1	Electrical multiple panels	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1987-168-029	Flight cycle calculation	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1988-188-024R1	Tripod	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1988-189-030	Tripod check	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1990-006-025R1	Swashplate	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1990-007-031R1	Swashplate	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1990-099-026	MGB oil line	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1990-119-032R1	MGB bar shackles	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1990-203-028	Autopilot actuators	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1990-204-033R1	Tail rotor control shaft	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1990-205-027R1	Tail rotor control shaft	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1991-022-029	Front passenger door	24-Feb-22

Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1991-041-030	LUCAS AIR EQUIPEMENT electric hoist	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1991-082-034	LUCAS AIR EQUIPEMENT electric hoist	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1991-267-031	Main rotor shaft	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1991-268-035	Main rotor shaft	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1992-181-032R1	Main rotor pitch change horn bushes	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1992-182-036R1	Main rotor pitch change horn bushes	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1992-185-033R4	Tail Rotor	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1993-065-034R1	Rotor mast shaft	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1993-066-037R1	Rotor mast shaft	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1994-052-035	Front passenger door jettison mechanism	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1994-076-036R1	Outboard fins attachment	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1994-145-039	Free wheel	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1994-148-037	Fuel filter elements	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1994-149-038	Fuel filter elements	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1995-067-038	Transmission deck	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1995-107-039R1	Tail rotor hub fairing	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1995-112-040	Tair rotor hub fairing	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1996-117-040	Main rotor head frequency adapter	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1997-145-042	MGB Planet gear shaft	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1998-112-042	Single-pole circuit breakers	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1998-113-043	Single-pole circuit breakers	24-Feb-22

Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1998-252-043	Electrical connection modules manufactured by CONNECTRAL	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1998-253-044R1	Electrical connection modules manufactured by CONNECTRAL	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1998-324-045	MGB Vibration Level Monitoring	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1998-383-044	Main rotor head / Spherical thrust bearings / Attach beams attachment	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1998-384-047	Main rotor head spherical thrust bearings/Attach beams attachment bol	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1998-517-048R2	Power loss printed circuit boards - Functional check	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-1999-459-049R1	Enlarged sliding doors - Non-jettisonable windows	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2000-108-050R2	Sand filter ejection nozzles	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2000-235-045	Main rotor blades - Service life limitation	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2000-302	Ferry fuel tanks	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2000-517-051	Engine indicating adaptation	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2001-058-001R1	Cabin sliding door	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2001-060-052	Fuselage - Frame - Reinforced latch support	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2001-061-053	Fuselage - Frame - Stretcher support	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2001-439-002R1	SMS 45 H screens	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2001-617-004R1	SMD 45 H screens	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2002-044	SIREN cargo hooks	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2002-186-005R1	Doors	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2002-283-048R1	MGB - Torque tightening of attachment stud	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2002-285-055R1	MGB - Torque tightening of attachment studs	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2002-312R1	Rotor Flight Controls - "TRW-SAMM" Main Servo Controls - Check	24-Feb-22

Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2002-452R1	Main rotor and tail rotor dynamic component - Correction of operating h	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2002-472-057	Tail rotor head - Pitch change control rod	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2002-473-006	Tail rotor head - Pitch change control rod	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2002-474R2	Landing Gear - MLG Wheel Brake Hydraulic Hose - Check	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2002-515R1	Landing gear indicating system	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2003-028R1	Fuel - Interference between Air Vent Hose and RH Front Passenger Door	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2003-196	Engine governing - Red "GOV" warning lights	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2003-321	Landing gear - Brace strut actuator - Corrosion	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2003-322R1	Rotor Flight Controls - Double Locking of Stop Screws	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2003-323	Indicating and recording systems - Landing gear PCBs 10 and 11 Alpha	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2003-345R2	Doors - Cabin Sliding Doors - Inspection & Operational Limitations	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2003-372	Cabin sliding doors - Microswitches	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2004-013R1	Rotor Flight Controls - Prohibition of Intentional Auto-rotation	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2004-052R1	Doors - Sliding Doors Upper Rail & Fitting - Check	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2004-057R1	Electrical Power - Electrical / Electronic Panel 12 Alpha Wiring - Modification	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2004-060R1	Limitations - Never Exceed Speed (Vne)	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2004-099	Landing Gear - Main Landing Gear Wheel Brake Hose - Checks	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2004-106	Rotor - Main rotor blade / Tip cap junction	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2004-107R1	Doors - Cabin Sliding Doors	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2004-156	Doors - Cabin Sliding Door Rails and Fittings - Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2004-157	Doors - Cabin Sliding Doors Forward Centering Pins - Reinforcement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2004-179	Fire Protection - Engine Fire Extinguishers - Weight Check	24-Feb-22

Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2004-180	Fire Protection - Engine- & Baggage Compartment Fire Extinguishers -	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2004-188	Equipment & Furnishings - Cargo Hold Fire Detectors & Upholstering -	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2005-036	Rotor Drive - Check of the Main Gearbox (MGB) Bottom Plate	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2005-119R1	Hydraulic System - Cooler Filter Element - Identification/Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	DGAC AD F-2006-042	Hydraulic Power - Flexible Hydraulic Pipes & Attachment Clamps - Che	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0052-E	Doors - Cabin Sliding Doors	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0078	Tail Rotor - Blade Tuning Weights	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0080	Equipment/Furnishings - Life Raft Installation	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0084-E	Main Rotor - Hub-to-Mast Bolted Attachment - Check	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0098	[Corrected] Equipment / Furnishings - Hoist Hooks	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0099	Tail Rotor- Tail Rotor Blade Check	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0101	Rotor Drive(s) - Check of Main Gearbox (MGB) Base Plate	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0213	Landing Gear - Optional Ski Installation - Flight Manual Supplement VN	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0214	Indicating System/Rotor Drive - Main Gear Box- Low Oil Pressure Warr	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0255	Engine Controls- Engine Control Selector Switch Guard on Panel 12 AL	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0256R1	[Corrected] Engine Controls - Engine Control Selector Switch Guard on	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0362-E	Rotor(s) - Main Rotor Head Frequency Adapters - Modification	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2006-0368R1	[Correction] Rotor - Rotor Mast Nut - Check / Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2007-0099	Rotors Flight Control - Main & Tail Rotors Servo-Controls - Inspection /	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2007-0129	Main Rotor Drive - Main Gearbox (MGB) Suspension Diagonal Cross-M	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2007-0159-E	Equipment / Furnishings - Hoist cut-off connector 24 Delta - Inspection	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2007-0220	Tail Rotor Drive - Tail Rotor Blade Pitch Control Shafts - Identification/F	24-Feb-22

Airbus Helicopters EC155 and SA365 Series	EASA AD 2007-0224R1	[Corrected] Equipment & Furnishings - CPT 609 Crash Position Transr	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2007-0288R1	Main Rotor Drive - Main Gearbox (MGB) Planet Gear Carrier - Inspectic	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2008-0096-E	Equipment & Furnishings - Crash Position Indicator (CPI) Components	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2008-0165R1	Rotor(s) - Starflex Star Arm Ends - Check / Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2008-0204R1	Stabilizers - Never-Exceed Speed (VNE) and Rate-of-Descent (R/D) - Li	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2009-0035-E	Navigation - UNS-1D Navigation System - Limitation	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2009-0078R1	Equipment / Furnishings - VIP 4-seat Benches - Limitation	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2009-0109-E	Fuel - High Level Switches / Fuel Transfer between Fuel Tank Groups -	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2009-0122R1	Equipment / Furnishings -Load Release Units - Inspection / Modificatio	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2010-0014	Equipment and Furnishings - Hoist Operator's Belt Snap Hook - Replac	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2010-0040	Doors - Jettisoning System of the Pilot's and Co-pilot's Doors - Test / R	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2010-0052-E	Equipment / Furnishings - External Life Raft Mooring Line Attachment -	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2010-0100R1	[Correction] Navigation - Vertical Gyro Unit Data Output - Operational L	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2010-0116-E	Main Rotor Drive - Main Gearbox Oil Low Pressure Switch Connection -	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2010-0181	Time Limits/Maintenance Checks - Airworthiness Limitation Section - A	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2010-0257	Windows - Jettisoning System of Hinged Cabin Door Window - Rework	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2011-0108	Fuselage - Upper Fin / Fenestron Attachment Fittings - Inspection / Rep	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2011-0127	Main Rotor Drive - Main Gearbox Casing - Inspection / Repair	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2011-0154	[Correction] Rotor Flight Controls - Collective Pitch Lever Restraining T	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2011-0190	Fuselage - Fuel Draining System - Modification	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2012-0067	Tail Rotor - Tail Rotor Blade Monitoring and Limitations	24-Feb-22

Airbus Helicopters EC155 and SA365 Series	EASA AD 2012-0098-E	Rotorcraft Flight Manual - Emergency Procedures - Rush Revision	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2012-0108R1	Fuselage - Frame No.9 - Inspection / Repair	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2012-0148	Rotorcraft Flight Manual - Operating Limitations Section - Amendment	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2012-0206	Equipment / Furnishings - EADS SOGERMA Flight Crew Seats - Inspection	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2012-0227R1	Tail Rotor - Tail Rotor Hub - Inspection / Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2013-0218	Main Rotor Hub - Frequency Adapter / Torque Value - Adjustment / Modification	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2013-0294	Lights - Passenger Compartment Lighting - Modification	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2014-0159R1	Fuselage - Frame - Inspection	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2014-0162R2	Fuselage - Upper Frame - Inspection	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2014-0188R4	Equipment & Furnishings - Emergency Flotation System - Rotorcraft Flight Manual Amendment	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2014-0214	Equipment / Furnishing - External Life Rafts - Inspection	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2014-0231	Equipment / Furnishings - Safety Belt Straps / Arm-Rest Stops and Footrests	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2014-0236R1	Lights - Emergency Lighting Rotorcraft Flight Manual Amendment / Operation	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2014-0240	Fuel - Fuel Supply - Inspection	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2015-0048	Equipment / Furnishing - External Life Raft - Modification	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2015-0068-E	Placards and Markings - Installation / Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2015-0075	Equipment / Furnishings - Emergency Locator Transmitter - Identification	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2015-0157	Doors - Jettisoning System of the Pilot and Co-pilot Doors - Functional Test	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2015-0168	Windows - Cabin Windows / Jettisoning System - Inspection	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2015-0226R6	[Correction] Equipment / Furnishings - Hoist - Test / Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2016-0028	Equipment / Furnishing - Internal Life Rafts - Inspection	24-Feb-22



Airbus Helicopters EC155 and SA365 Series	EASA AD 2016-0115-E	Rotor(s) - Main Rotor Mast / Starflex Star / Mast Connecting Bolts -Rep	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2016-0258	Lights - Strobe Light Harnesses - Inspection/Modification	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2017-0116R2	Time Limits / Maintenance Checks - Main Gearbox Magnetic Plugs - Ins	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2018-0069	Navigation - Flight / Ground Logic - Modification	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2018-0173-E	Equipment & Furnishings - Hoist Carrier Assembly - Inspection	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2018-0176	Main Rotor Drive - Main Gearbox Magnetic Plug - Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2018-0258	Windows - Swing Door Jettisonable Window - Modification	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2018-0263	Time Limits / Maintenance Checks - Main Gearbox Magnetic Plugs - Ins	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2019-0008	Fuselage - Cowlings and Fairings - Inspection / Modification	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2019-0080	Fuselage - Aft Fuselage Skin Panels - Inspection	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2019-0088R1	Placards and Markings - Inspection / Installation	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2019-0165-E	Tail Rotor Drive - Tail Rotor Gearbox - Inspection / Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2019-0184	Rotors Flight Control - Main Rotor Servo Actuators - Inspection	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2019-0246	Rotors Flight Control - Collective Controls / Protective Cover - Modificat	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2020-0013	Fire Protection - Hand-held Fire Extinguishers - Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2020-0043	Main Rotor Drive - Main Gearbox - Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2020-0064	Equipment / Furnishings - Emergency Flotation System / Inflation Hose	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2020-0287	Tail Rotor Drive - Tail Rotor Drive Flange / Shaft Flexible Coupling - Ins	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2021-0016	Main Rotor Drive - Main Gearbox / Magnetic Plug and Oil Filter / Planet	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2021-0048	Main Rotor - Pitch Rod Upper Links - Marking / Inspection	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2021-0101R1	Doors - Placards - Installation / Rotorcraft Flight Manual - Section Emer	31-Mar-22

Airbus Helicopters EC155 and SA365 Series	EASA AD 2021-0170	Tail Rotor - Double Bearing - Inspection / Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2021-0171	Tail Rotor - Pitch Control Rod Bearing - Inspection / Replacement	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2021-0225	Rotorcraft Flight Manual - Supplements / One-Engine Inoperative Perfo	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2021-0265	Power Plant - Cowlings - Inspection / Repainting	24-Feb-22
Airbus Helicopters EC155 and SA365 Series	EASA AD 2022-0006R2	Main Rotor Drive - Oil Cooling Fan Hub - Inspection / Replacement	24-Feb-22
Bell 205 Series	FAA AD 2020-12-10	Tail Rotor Blades – Inspection	16-Jul-20
Bell 205 Series	FAA AD 2020-16-10	Shoulder Harness Seat Belt – Inspection	3-Sep-20
Bell 205 Series	FAA AD 2020-19-08	Main Rotor Hub Tension-Torsion Straps – Inspection	21-Oct-20
Bell 205 Series	FAA AD 2021-15-51	Cancelled - FAA AD 2022-02-02 refers	16-Feb-22
Bell 205 Series	FAA AD 2022-02-02	Cancelled - FAA AD 2022-06-03 refers	31-Mar-22
Bell 205 Series	FAA AD 2022-06-03	Main Rotor Hub Strap Pins - Inspection	31-Mar-22
Bell 205 Series	FAA AD 2022-07-02	Tail Boom Fin Spar Cap - Inspection	9-May-22
Bell 205 Series	TC AD CF-2022-46	Landing Gear Forward Crosstube - Inspection	31-Aug-22
Bell 206 Series	FAA AD 2021-24-15	Oil Cooler Blower – Inspection	18-Jan-22
Bell 206 Series	TC AD CF-2019-34	Cancelled – CF-2020-15 refers	28-May-20
Bell 206 Series	TC AD CF-2020-15	Tail Rotor Drive Shaft Coupling Bolted Connections – Inspection	28-May-20
Bell 206 Series	TC AD CF-2022-33	Tail Rotor Drive Shafts with Bonded Adapters – Inspection	30-Jun-22
Bell 212 Series	EASA AD 2014-0244	Cancelled – EASA AD 2021-0148 refers	5-Jul-21
Bell 212 Series	EASA AD 2021-0148	Emergency Flotation System (EFS) – AFM Supplement	5-Jul-21
Bell 212 Series	EASA AD 2022-0047	Tail Boom Attachment – Inspection	24-Mar-22
Bell 212 Series	FAA AD 2011-12-08	Cancelled – FAA AD 2020-12-10 refers	16-Jul-20
Bell 212 Series	FAA AD 2020-12-10	Tail Rotor Blades – Inspection	16-Jul-20
Bell 212 Series	FAA AD 2020-16-10	Shoulder Harness Seat Belt – Inspection	3-Sep-20
Bell 212 Series	FAA AD 2020-19-08	Main Rotor Hub Tension-Torsion Straps – Inspection	21-Oct-20
Bell 212 Series	FAA AD 2021-15-51	Cancelled - FAA AD 2022-02-02 refers	16-Feb-22
Bell 212 Series	FAA AD 2022-02-02	Outboard Main Rotor Hub Strap Pins - Inspection	16-Feb-22
Bell 212 Series	FAA AD 2022-02-02	Cancelled - FAA AD 2022-06-03 refers	31-Mar-22
Bell 212 Series	FAA AD 2022-06-03	Main Rotor Hub Strap Pins - Inspection	31-Mar-22
Bell 212 Series	FAA AD 2022-07-02	Tail Boom Fin Spar Cap - Inspection	9-May-22
Bell 212 Series	FAA AD 2022-11-19	Engine Oil Check Valve - Inspection	6-Jul-22
Bell 212 Series	TC AD CF-2022-46	Landing Gear Forward Crosstube - Inspection	31-Aug-22
Bell 222 Series	DCA/BELL222/24A	Cancelled – Transport Canada AD CF-2010-29R2 refers	4-Aug-22
Bell 222 Series	EASA AD 2014-0244	Cancelled – EASA AD 2021-0148 refers	5-Jul-21
Bell 222 Series	EASA AD 2021-0148	Emergency Flotation System (EFS) – AFM Supplement	5-Jul-21

Bell 222 Series	TC AD CF-2010-29R2	Servo Actuator Piston Rod – Inspection	4-Aug-22
Bell 407	TC AD CF-2021-34	Tail Boom Lower Skin Cracking - Inspection	5-Nov-21
Bell 412 Series	DCA/BELL412/15	Cancelled – FAA AD 2020-12-10 refers	16-Jul-20
Bell 412 Series	EASA AD 2014-0244	Cancelled – EASA AD 2021-0148 refers	5-Jul-21
Bell 412 Series	EASA AD 2021-0148	Emergency Flotation System (EFS) – AFM Supplement	5-Jul-21
Bell 412 Series	EASA AD 2022-0047	Tail Boom Attachment – Inspection	24-Mar-22
Bell 412 Series	FAA AD 2020-12-10	Tail Rotor Blades – Inspection	16-Jul-20
Bell 412 Series	FAA AD 2020-16-10	Shoulder Harness Seat Belt – Inspection	3-Sep-20
Bell 412 Series	FAA AD 2020-22-07	MGB Support Case – AFM Amendment	18-Nov-20
Bell 412 Series	FAA AD 2022-07-02	Tail Boom Fin Spar Cap - Inspection	9-May-22
Bell 412 Series	FAA AD 2022-07-03	Collective Levers – Inspection	27-Apr-22
Bell 412 Series	FAA AD 2022-11-19	Engine Oil Check Valve - Inspection	6-Jul-22
Bell 412 Series	TC AD CF-2022-46	Landing Gear Forward Crosstube - Inspection	31-Aug-22
Bell 429	TC AD CF-2015-16R3	Tail Rotor Pitch Link Spherical Bearing – Inspection	27-May-21
Bell 429	TC AD CF-2016-11R3	Bellcrank Pivot Bearings – Inspection	30-Sep-21
Bell 429	TC AD CF-2020-18R2	Prohibit use of Map Mode on LH and RH Display Units - AFM Amendment	24-Feb-22
Bell 429	TC AD CF-2020-21R1	Emergency Flotation System Supply Hoses - Inspection	2-Sep-20
Bell 429	TC AD CF-2021-15	TRGB Support Assembly to Tailboom Attachment - Inspection	29-Apr-21
Bell 505	FAA AD 2021-26-01	Stability Augmentation System and Autopilot – Inspection	28-Dec-21
Bell 505	TC AD CF-2021-05R3	Pilot Collective Stick and Grip Assembly – Inspection	2-Apr-21
Bell UH-1 Series	FAA AD 2021-15-14	Tailboom Attach Structure - Inspection	30-Aug-21
Bell UH-1 Series	FAA AD 2021-15-52	Cancelled - FAA AD 2022-06-05 refers	16-Mar-22
Bell UH-1 Series	FAA AD 2021-26-16	KAflex Main Driveshaft - Inspection	25-Feb-22
Bell UH-1 Series	FAA AD 2022-06-05	Main Rotor Hub Strap Pins - Inspection	16-Mar-22
Brantly B-2 Series	FAA AD 2021-26-09	Tail Rotor Hub – Inspection	19-Jan-22
Guimbal Cabri G2	EASA AD 2020-0199 (Correction)	Cancelled – EASA AD 2021-0155 refers	29-Jul-21
Guimbal Cabri G2	EASA AD 2021-0155	Main Rotor Scissors Fittings - Inspection	29-Jul-21
Helicopters - General	DCA/HELI/7A	Flight Control Cable End Assemblies - Proof Load	17-Dec-20
Helicopters - General	FAA AD 2021-23-13	Radio Altimeter Interference from 5G C-Band	23-Dec-21
Kawasaki BK117 Series	DCA/BK117/21A	Cancelled by JCAB AD TCD-6982A-2021	13-Apr-21
Kawasaki BK117 Series	JCAB AD TCD-8201C-1-2022	Goodrich Rescue Hoists – Inspection	28-Jul-22
Kawasaki BK117 Series	JCAB AD TCD-9687-2020	Airworthiness Limitations – Revision	28-Jan-21
Kawasaki BK117 Series	JCAB AD TCD-9876-2022	Tension Torsion Straps – Inspection	3-Mar-22
Leonardo A109 Series	DCA/A109/4	Cancelled – EASA AD 2020-0230 refers	5-Nov-20
Leonardo A109 Series	EASA AD 2015-0097	Cancelled – EASA AD 2020-0142 refers	30-Jul-20

Leonardo A109 Series	EASA AD 2020-0142	Tail Rotor Drive Slider Assembly Pitch Control – Inspection	30-Jul-20
Leonardo A109 Series	EASA AD 2020-0230	Main Rotor Blade Tip Cap – Inspection	5-Nov-20
Leonardo A109 Series	EASA AD 2020-0256	Cancelled – EASA AD 2022-0153 refers	11-Aug-22
Leonardo A109 Series	EASA AD 2021-0031	Gearbox Assembly – Inspection	5-Feb-21
Leonardo A109 Series	EASA AD 2021-0065	Wiring Protection – Modification	25-Mar-21
Leonardo A109 Series	EASA AD 2021-0067	Rotor Brake Control Cable – Inspection	25-Mar-21
Leonardo A109 Series	EASA AD 2021-0144	Tail Rotor Shaft Assembly – Inspection	1-Jul-21
Leonardo A109 Series	EASA AD 2021-0179	Hoist Support Assembly – Inspection	10-Aug-21
Leonardo A109 Series	EASA AD 2021-0255 (Correction)	Control Rods and Levers – Inspection	29-Nov-21
Leonardo A109 Series	EASA AD 2022-0037(Correction)	Main Rotor Rotating Scissor Assembly – Inspection	31-Mar-22
Leonardo A109 Series	EASA AD 2022-0153	Centre Fuselage Frame Assembly – Inspection	11-Aug-22
Leonardo A119 & AW119 Series	EASA AD 2018-0156	Cancelled – EASA AD 2020-0206 refers	14-Oct-20
Leonardo A119 & AW119 Series	EASA AD 2019-0057	Cancelled – EASA AD 2021-0096 refers	29-Apr-21
Leonardo A119 & AW119 Series	EASA AD 2019-0194-E	Cancelled – EASA AD 2020-0128 refers	25-Jun-20
Leonardo A119 & AW119 Series	EASA AD 2020-0128	Tail Rotor Duplex Bearing and Plug – Inspection	25-Jun-20
Leonardo A119 & AW119 Series	EASA AD 2020-0206	Gearbox Output Shaft – Inspection	14-Oct-20
Leonardo A119 & AW119 Series	EASA AD 2021-0040	Instrument Wiring – Inspection	25-Feb-21
Leonardo A119 & AW119 Series	EASA AD 2021-0096	Collective Stick Torque Tube Assembly – Inspection	29-Apr-21
Leonardo A119 & AW119 Series	EASA AD 2022-0037(Correction)	Main Rotor Rotating Scissor Assembly – Inspection	31-Mar-22
Leonardo A119 & AW119 Series	EASA AD 2022-0148	Starter Generator Drive Shaft – Inspection	28-Jul-22
Leonardo AW169 Helicopters	EASA AD 2019-0252	Cancelled – EASA AD 2021-0199 refers	30-Sep-21
Leonardo AW169 Helicopters	EASA AD 2020-0048	Cancelled – EASA AD 2020-0197 refers	24-Sep-20
Leonardo AW169 Helicopters	EASA AD 2020-0197	Tail Rotor Servo Actuator / Duplex Bearing – Inspection	24-Sep-20
Leonardo AW169 Helicopters	EASA AD 2021-0199	Yaw Pedal Assemblies – Modification	30-Sep-21
Leonardo AW169 Helicopters	EASA AD 2021-0238	Fuel Tank Vent Lines – Inspection	25-Nov-21
Leonardo AW169 Helicopters	EASA AD 2022-0178	Maintenance Checks - Airworthiness Limitations	9-Sep-22
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	DCA/HU369/34B	Main Rotor Transmission Cooling Installation - Inspection	1-Oct-20
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2020-11-07	Main Rotor Hub Lead-lag Bolt - Inspection	30-Jun-20
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2020-18-20	Main Rotor Blade Leading Edge Abrasion Strip - Inspection	28-Oct-20
MD 369 Series, 500N & Kawasaki-Hughes 369 Series	FAA AD 2021-22-11	Pilot to Co-pilot Tail Rotor Torque Tube - Inspection	10-Jan-22
MD 600N Helicopters	FAA AD 2020-11-07	Main Rotor Hub Lead-lag Bolt - Inspection	30-Jun-20
MD 600N Helicopters	FAA AD 2020-18-20	Main Rotor Blade Leading Edge Abrasion Strip - Inspection	28-Oct-20
MD 600N Helicopters	FAA AD 2021-22-11	Pilot to Co-pilot Tail Rotor Torque Tube - Inspection	10-Jan-22
Robinson R22 Series	FAA AD 2022-12-08	Engine Governor and RPM Sensor - Inspection	29-Jun-22
Robinson R44 Series	DCA/R44/12A	FAA AD 98-21-36 Cancelled – FAA AD 99-23-01 refers	28-Apr-22
Robinson R44 Series	FAA AD 2019-12-18	Cancelled – FAA AD 2020-18-08 refers	29-Aug-20

Robinson R44 Series	FAA AD 2020-08-10	Tail Rotor Blades – Inspection	22-May-20
Robinson R44 Series	FAA AD 2020-18-08	Engine Air Induction Hoses – Inspection	29-Aug-20
Robinson R44 Series	FAA AD 2021-19-08	Tail Rotor Blades – Inspection	22-Sep-21
Robinson R44 Series	FAA AD 2022-12-08	Engine Governor and RPM Sensor - Inspection	29-Jun-22
Robinson R44 Series	FAA AD 99-23-01	Cyclic Control Grip Assembly - Inspection	28-Apr-22
Robinson R66	FAA AD 2021-04-12	Tail Rotor Drive Shaft Assembly – Inspection	12-Apr-21
Sikorsky S-76 Series	EASA AD 2014-0244	Cancelled – EASA AD 2021-0148 refers	5-Jul-21
Sikorsky S-76 Series	EASA AD 2021-0148	Emergency Flotation System (EFS) – AFM Supplement	5-Jul-21
Sikorsky S-76 Series	FAA AD 2020-15-17	Remote Data Acquisition Unit and Display Unit – Inspection	9-Sep-20
<b>Amateur Built</b>	<b>Amateur Built</b>		
All Amateur Built Aircraft	DCA/ABUILT/12	Engine Control Rod Eye Ends - Modification	25-Nov-21
All Amateur Built Aircraft	DCA/ABUILT/13	Flight Control Cable End Assemblies - Proof Load	25-Nov-21
Dyn'Aero MCR Type Aircraft	DGAC AD F-2008-003	Front Landing Gear Leg (NLG) - Inspection	17-Dec-20
Dyn'Aero MCR Type Aircraft	DGAC AD F-2012-001	Horizontal Stabiliser - Inspection	17-Dec-20
Europa Aircraft, all models	UK CAA MPD 2022-003 (Correction)	Door Brackets – Modification	17-Feb-22
Jodel D.11 Aircraft	DCA/ABUILT/2A	Aileron Pulley Mounting - Modification	17-Dec-20
Reality Escapades & Sherwood Scout Aeroplanes	UK CAA MPD 2022-004-E	Seat Locking and Secondary Seat Restraint – Inspection	24-Feb-22
<b>Microlights</b>	<b>Microlights</b>		
Aeroplanes fitted with Edge Wings	UK MPD 2022-001	Aileron Centre Hinge Attachment – Inspection	4-Feb-22
Airmaster AP306 & AP406 Propellers	DCA/MICRO/18	Airmaster Propellers - Removal from Service	17-Dec-20
Dyn'Aero MCR Type Aircraft	DCA/MICRO/4	Cancelled – DGAC AD F-2012-001 refers	17-Dec-20
Dyn'Aero MCR Type Aircraft	DGAC AD F-2012-001	Horizontal Stabiliser - Inspection	17-Dec-20
Europa Aircraft, all models	UK CAA MPD 2022-003 (Correction)	Door Brackets – Modification	17-Feb-22
Jodel D.11 Aircraft	DCA/MICRO/20	Aileron Pulley Mounting - Modification	17-Dec-20
Reality Escapades & Sherwood Scout Aeroplanes	UK CAA MPD 2022-004-E	Seat Locking and Secondary Seat Restraint – Inspection	24-Feb-22
Revmaster Engines	DCA/MICRO/19	Crankshaft - Replacement and Propeller Attachment Flange - Inspection	17-Dec-20
<b>Ex-military and Vintage Aircraft</b>	<b>Ex-military and Vintage Aircraft</b>		
<b>Factory Built – Not type certified</b>	<b>Factory Built – Not type certified</b>		
Ex-military and Vintage Factory Built Aircraft	UK MPD 2020-002	Cancelled – Refer Rolls-Royce Merlin Engines AD Schedule	28-May-20
<b>Gliders</b>	<b>Gliders</b>		
Glasflugel series	EASA AD 2021-0223-E	Elevator Control Rod – Inspection	8-Oct-21
Gliders - General	DCA/GLIDER/10	Cancelled – Refer EASA AD 2007-0001R1 in Solo 2625 Series AD Schedule	25-Nov-21
Grob series	EASA AD 2020-0121	Cancelled – EASA AD 2020-0138 refers	3-Jul-20
Grob series	EASA AD 2020-0138	Elevator Control Pushrod – Inspection	3-Jul-20
M&D JS-MD series	EASA AD 2021-0070	Airbrake Blade No. 3 - Inspection	25-Nov-21

M&D JS-MD series	EASA AD 2021-0243	Tail Wheel Cable - Inspection	25-Nov-21
Schempp-Hirth series	EASA AD 2020-0233	Airbrake End Stops / Bushings – Inspection	10-Nov-20
Schempp-Hirth series	EASA AD 2020-0260	Elevator Connection – Inspection	17-Dec-20
Schempp-Hirth series	EASA AD 2022-0076	AFM – Amendment	26-May-22
Schempp-Hirth Series	EASA AD 2022-0138	Airbrake System – Inspection	28-Jul-22
Schleicher series	DCA/SCH/138	Cancelled - EASA AD 2021-0230 refers	28-Oct-21
Schleicher series	EASA AD 2021-0187	Wing Root Ribs – Inspection	26-Aug-21
Schleicher Series	EASA AD 2021-0187	Cancelled – EASA AD 2022-0146 refers	28-Jul-22
Schleicher series	EASA AD 2021-0230	Elevators – Inspection	28-Oct-21
Schleicher Series	EASA AD 2022-0146	Wing Root Ribs – Inspection	28-Jul-22
Stemme S10 Series	EASA AD 2021-0278R1	Freewheel Clutch P/N 12AK – Inspection	31-Aug-22
<b>Balloons</b>	<b>Balloons</b>		
Balloons - Fuel Cylinder P/N CB2901, CB2902 & CB2903	UK CAA AD G-2021-0010-E	Cancelled - UK CAA AD G-2021-0014R1-E refers	4-Nov-21
Balloons - Fuel Cylinder P/N CB2901, CB2902 & CB2903	UK CAA AD G-2021-0014R1-E	Cylinder Quick Shut-off Valve Mounting Flange – Inspection	14-Dec-21
Balloons - Fuel Cylinder P/N CB2990	UK CAA AD G-2022-0010-E	Fuel Cylinders – Inspection	16-May-22
Balloons - Stratus Double Burners P/N CB8504	EASA AD 2021-0042	Burner Assembly and Hanger – Inspection	12-Feb-21
Balloons - Various UK/EASA Types and Models	UK CAA AD G-2021-0012	Burner Assembly and Hanger – Inspection	3-Nov-21
<b>Engines</b>	<b>Engines</b>		
Austro E4 Series Engines	EASA AD 2011-0039	High Pressure Fuel Pump – Inspection and Replacement	25-Jun-20
Austro E4 Series Engines	EASA AD 2013-0213R1	Waste Gate Controller - Replacement	25-Jun-20
Austro E4 Series Engines	EASA AD 2017-0103R1	Timing Chain – Replacement / AFM – Amendment	25-Jun-20
Austro E4 Series Engines	EASA AD 2018-0125	Waste Gate Controller & Control Rod Circlip – Life Limit/Mod	25-Jun-20
Austro E4 Series Engines	EASA AD 2019-0041	Airworthiness Limitations - Amendment	25-Jun-20
Austro E4 Series Engines	EASA AD 2021-0055R1	Cancelled – EASA AD 2021-0094 refers	29-Apr-21
Austro E4 Series Engines	EASA AD 2021-0094	Oil Pump - Replacement	29-Apr-21
Austro E4 Series Engines	EASA AD 2021-0143-E	Cancelled – EASA AD 2021-0191-E Refers	20-Aug-21
Austro E4 Series Engines	EASA AD 2021-0191-E	Oil Pump – Replacement	20-Aug-21
Austro E4 Series Engines	EASA AD 2021-0203R1	Cancelled – EASA AD 2021-0274-E Refers	23-Dec-21
Austro E4 Series Engines	EASA AD 2021-0274-E	High Pressure Pump Driving Gear – Inspection	23-Dec-21
Continental 300 Series	FAA AD 2022-04-04	Oil Filter Adapter - Inspection	29-Mar-22
Continental 360 Series	FAA AD 2022-04-04	Oil Filter Adapter - Inspection	29-Mar-22
Continental 470 Series	DCA/CON/201	Exhaust Valves – Inspection	27-Aug-20
Continental 470 Series	FAA AD 2022-04-04	Oil Filter Adapter - Inspection	29-Mar-22
Continental 520 Series	FAA AD 2010-11-04	Hydraulic Lifters – Inspection	25-Jun-20
Continental 520 Series	FAA AD 2020-16-11	Cross-flow Cylinder Assemblies – Inspection	21-Sep-20
Continental 520 Series	FAA AD 2022-04-04	Oil Filter Adapter - Inspection	29-Mar-22

Continental 520 Series	FAA AD 77-05-04	Crankshaft – Inspection	25-Jun-20
Continental 520 Series	FAA AD 89-14-01	Crankshaft – Inspection	26-Aug-21
Continental 550 Series	FAA AD 2020-16-11	Cross-flow Cylinder Assemblies – Inspection	21-Sep-20
Continental 550 Series	FAA AD 2022-04-04	Oil Filter Adapter - Inspection	29-Mar-22
Continental TAE 125-01 /-02 Series	DCA/THIE/3	Cancelled – DCA/THIE/26 refers	29-Oct-20
Continental TAE 125-01 /-02 Series	EASA AD 2020-0228 (Correction)	Turbocharger Hoses – Inspection	17-Dec-20
Continental TAE 125-01 /-02 Series	EASA AD 2021-0022	Main Bearing / Studs – Inspection	2-Feb-21
Engines - General	FAA AD 2022-16-03	Magnetos S-1200 Series - Inspection	15-Aug-22
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2020-0201R2	Fuel Control Unit – Replacement	28-Jan-21
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2021-0052	Cancelled – EASA AD 2021-0154 refers	29-Jul-21
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2021-0060	Airworthiness Limitations	25-Mar-21
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2021-0125-E	Critical Parts - Replacement	11-May-21
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2021-0154	Propeller Shaft - Replacement	29-Jul-21
GE Aviation Czech (previously Walter Engines) M601 Series	EASA AD 2021-0264	Critical Parts - Replacement	6-Dec-21
Honeywell LTS101 and T53 Series	FAA AD 2002-03-01	Cancelled – FAA AD 2022-10-02 refers	30-Jun-22
Honeywell LTS101 and T53 Series	FAA AD 2022-10-02	Tachometer Drive Spur Gear – Inspection	30-Jun-22
Lycoming AEIO-360, HIO-360, IO-360 and LIO-360 Series	FAA AD 2020-25-12	Crankshaft Assemblies – Inspection	15-Jan-21
Lycoming HO-360, LO-360 and O-360 Series	FAA AD 2020-25-12	Crankshaft Assemblies – Inspection	15-Jan-21
Pratt & Whitney JT15D Series	CF-2022-27	Compressor Impeller – Inspection	30-Jun-22
Pratt & Whitney PT6 Series	TC AD CF-2015-01R2	Engine Torque Indication – Inspection	29-Oct-20
Pratt & Whitney PW617F-E and PW617F1-E engines	TC AD CF-2010-02	Fuel Oil Heat Exchanger (FOHE) Fuel Filter Bypass Valve – Inspection	26-Nov-20
Rolls-Royce 250 Series	DCA/AL250/60B	Engine Compressor Modules - Inspection	4-May-20
Rolls-Royce 250 Series	FAA AD 2022-10-06	Turbine Wheels 3rd and 4th Stage - Inspection	28-Jun-22
Rolls-Royce Merlin & Packard Merlin Engine Variants	UK MPD 2020-002R1	Camshaft Bracket Retaining Studs – Inspection	28-May-20
Safran Helicopter Engines Arriel 1 Series	EASA AD 2020-0151-E	Module 03 / Stage 2 High Pressure Turbine Disc – Replacement	11-Jul-20
Safran Helicopter Engines Arriel 2 Series	EASA AD 2016-0004R1	Hydro-Mechanical Metering Unit – Inspection	29-Apr-22
Safran Helicopter Engines Arriel 2 Series	EASA AD 2017-0102R2	HP/LP Fuel Pump Metering Unit – Inspection	5-Sep-22
Safran Helicopter Engines Arriel 2 Series	EASA AD 2018-0273	Cancelled - EASA AD 2022-0083 refers	26-May-22
Safran Helicopter Engines Arriel 2 Series	EASA AD 2022-0083	Airworthiness Limitations	26-May-22
Safran Helicopter Engines Arrius 1A Series	EASA AD 2022-0005	Airworthiness Limitations – Amendment	27-Jan-22

Safran Helicopter Engines Arrius 2 Series	DCA/TUR/24	Cancelled – EASA AD 2021-0088 refers	29-Apr-21
Safran Helicopter Engines Arrius 2 Series	EASA AD 2020-0033R1	Hydro-Mechanical Metering Unit (HMU) – Inspection	23-Dec-21
Safran Helicopter Engines Arrius 2 Series	EASA AD 2021-0088R1	Digital Engine Control Unit (DECU) – Software Update	2-Aug-21
Solo 2350 Series Engines	EASA AD 2015-0052R1	Cancelled - EASA AD 2022-0044 refers	31-Mar-22
Solo 2350 Series Engines	EASA AD 2022-0044R1	Engine – Inspection	26-May-22
Superior Air Parts Engines	FAA AD 2020-25-12	Crankshaft Assemblies – Inspection	15-Jan-21
Walter M601 Engines	EASA AD 2022-0034	Outer Liner Dilution Tube - Inspection	18-Mar-22
<b>Propellers</b>	<b>Propellers</b>		
Hartzell Propellers	FAA AD 1987-05-01	Blade Pilot Tube Bore Area - Inspection	27-May-21
Hartzell Propellers	FAA AD 2004-07-25	New Design Blades - Inspection	27-May-21
Hoffman Propellers	EASA AD 2020-0226R1	Cancelled – EASA AD 2022-0061 refers	28-Apr-22
Hoffman Propellers	EASA AD 2022-0061	Propeller Hub – Inspection	28-Apr-22
McCauley Propellers	FAA AD 2020-19-06	McCauley Governors – Inspection	3-Nov-20
MT-Propellers	EASA AD 2022-0134	Propeller Blade Lag Screws – Inspection	22-Jul-22
<b>Components &amp; Equip**</b>	<b>Components &amp; Equip**</b>		
Aircraft Seats and Harnesses	DCA/SEAT/12A	Cancelled – FAA AD 2021-07-13 refers	11-May-21
Aircraft Seats and Harnesses	EASA AD 2021-0137	Safran 191 Series Pilot and Co-pilot Seats – Inspection	24-Jun-21
Aircraft Seats and Harnesses	FAA AD 2021-07-13	Pacific Science Rotary Buckle Assemblies – Inspection	11-May-21
Aircraft Seats and Harnesses	UK CAA AD G-2022-0011	Pilot and Co-pilot Seats – Inspection	30-Jun-22
Avionics Equipment	EASA AD 2022-0024	Flight Management Computer 2 – Inspection	24-Feb-22
Avionics Equipment	FAA AD 2019-12-09	Cancelled – FAA AD 2021-05-17 refers	29-Apr-21
Avionics Equipment	FAA AD 2020-16-08 (Correction)	Aspen Avionics Flight Displays – Inspection	17-Aug-20
Avionics Equipment	FAA AD 2020-18-51	Sandia Attitude Indicators – Inspection	28-Sep-20
Avionics Equipment	FAA AD 2021-05-17	Rockwell FDSA-6500 Flight Display System – Inspection	29-Apr-21
Avionics Equipment	FAA AD 2020-10-05	Rockwell Collins Pro Line 4 & Pro Line 21 Flight Management Systems – Inspection	24-Jun-20
Avionics Equipment	FAA AD 2021-08-07	Rockwell Collins GPS-4000S – Inspection	12-May-21
Avionics Equipment	FAA AD 2021-08-15	Garmin GMN-00962 GTS Processor Units – Inspection	17-May-21
Carburettors & Injection Systems	DCA/MA/18A	Fuel Injection Servo RSA-10AD1 – Inspection	30-Jul-20
Carburettors & Injection Systems	DCA/MA/19B	Fuel Injection Servos RSA-5AB1, RSA-5AD1, RSA-10ED1, RSA-10ED2, RSA-10DB1 and RSA-10DB2 – Inspection	30-Jul-20
Emergency Equipment	EASA AD 2021-0185R1	Hand Operated Fire Extinguishers – Inspection	26-Aug-21
Emergency Equipment	EASA AD 2022-0029R1	Emergency Parachutes – Inspection	28-Apr-22
Emergency Equipment	UK AD G-2021-0004	Life Raft Heliraft 18R MK3 – Inspection	5-Jul-21
Emergency Equipment	UK AD G-2022-0009	Lifejackets – Inspection	5-May-22
Instruments & Automatic Pilots	FAA AD 2022-03-15	Garmin G3X Touch Electronic Flight Instrument System – Inspection	21-Mar-22
Role Equipment - Helicopters	DCA/EQUIP/1H	Cancelled – DCA/EQUIP/28A refers	25-Jun-20
Role Equipment - Helicopters	DCA/EQUIP/27A	Electric Hoists Bonding – Inspection	23-Dec-21
Role Equipment - Helicopters	DCA/EQUIP/28A	Cable Suspended Cargo Hook Systems - Inspection	29-Oct-20



**Notes:**

\* The AD Schedule often covers a complete series of types.

\*\* This is not the AD Schedule title but more specific to the components affected.

\*\*\* AD Numbering - If the AD number is less than 10, a zero has been added before the number.

This is for sorting only and the AD should still be referred to as in the AD Schedule.