Airworthiness Directive Schedule

Aeroplanes Gippsland GA200 Series (Fatman) 27 September 2012

Notes

- 1. This AD schedule is applicable to Gippsland GA200 Series aircraft manufacturered under Civil Aviation Safety Authority (CASA) Type Certificate No. VA519.
- 2. The date above indicates the amendment date of this schedule.
- 3. New or amended ADs are shown with an asterisk *.

Contents

DCA/GA200/1	Cancelled – Superseded by DCA/GA200/2	2
* DCA/GA200/2A	Wing Strut Bolt – Inspection and Replacement	2

DCA/GA200/1 Cancelled – Superseded by DCA/GA200/2

Effective Date: 24 August 2012

* DCA/GA200/2A Wing Strut Bolt - Inspection and Replacement

Applicability: Model GA200 and GA200C aircraft, all S/N.

Note 1: DCA/GA200/2A revised to extend the repetitive inspection interval to 500 hours TIS

(previously 100 hours) and introduce GippsAero SB-GA200-2012-08 issue 2, dated 4 September 2012. The initial inspection compliance of 10 hours remains unchanged.

Requirement: To prevent failure of a wing strut attachment bolts which could result in a catastrophic

structural failure, accomplish the requirements in CASA AD/GA200/1 Amdt 1.

Note 2: A copy of CASA AD/GA200/1 Amdt 1 can be obtained from the CASA AD web site at

http://www.casa.gov.au/scripts/nc.dll?WCMS:STANDARD::pc=PC_90822

Note 3: GippsAero SB-GA200-2012-08 issue 2, dated 4 September 2012 or later approved

revisions are acceptable to comply with the requirements of this AD.

(NZ Occurrence 12/3452 and CASA AD/GA200/1 Amdt 1 refer)

Compliance: Within the next 10 hours TIS unless previously accomplished and thereafter at

intervals not to exceed 500 hours TIS.

Effective Date: DCA/GA200/2 - 24 August 2012

DCA/GA200/2A - 27 September 2012